

**Duane Arnold Energy Center** 

Operated by Nuclear Management Company, LLC

## SAFEGUARDS INFORMATION

August 15, 2003

SI-03-014 10 CFR 50.54(p) 10 CFR 72.212

Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Attn: Document Control Desk Mail Station 0-P1-17 Washington, DC 20555-0001

DUANE ARNOLD ENERGY CENTER DOCKET NO.: 50-331

OP. LICENSE NO.: DPR-49

DAEC Security Plan Change No. 47

The Duane Arnold Energy Center (DAEC) Security Plan is being revised to make changes required for the Independent Spent Fuel Storage Installation (ISFSI) Security Plan. The changes have been made pursuant to 10 CFR 50.54(p). This Security Plan Change (SPC-47) has been reviewed in accordance with the requirements of 10 CFR 50.54(p). We have determined that the changes do not decrease the effectiveness of the DAEC Security Plan. A description of the changes is included in Attachment 1 and our evaluation is included in Attachment 2 to this letter. The revised Security Plan is included as Attachment 3.

This letter contains no new commitments.

The attachments to this letter contain information of the type described in 10 CFR 73.21; therefore, they should be withheld from public disclosure.

SAFEGUARDS INFORMATION

3277 DAEC Road • Palo, Iowa 52324-9785 Telephone: 319.851.7611 X 1453

Should you have any questions regarding this matter, please contact Ben Kindred of this office at (319) 851-7259.

Sincerely,

Mark A. Peifer

Site Vice President, Duane Arnold Energy Center

Attachments: 1) SPC-47, Description of Changes

2) SPC-47, Evaluation of Change With Respect to 10 CFR 50.54(p)

3) Duane Arnold Energy Center Physical Security Plan, Revision 47

cc: D. Barta w/o

B. Linde (NMC) w/o

Project Manager (NRC-NRR) w/o

Regional Administrator, USNRC, Region III (2 copies w/attachments)

S. O'Connor (NRC-NMSS/SFPO) w/o

NRC Resident Inspector w/o

NRC Document Control Desk (3 copies w/attachments)

CTS Project w/o

IRMS, A-53, A-100, SPF-164 w/o

## ATTACHMENT CONTAINS SAFEGUARDS INFORMATION

THIS LETTER MAY BE HANDLED AS DECONTROLLED WHEN SEPARATED FROM THE ATTACHMENTS.