

From: "Scott Bakken" <sbakkenpri@coffey.com>
To: "John Lusher" <JHL@nrc.gov>
Date: 9/10/03 3:01PM
Subject: License SUA-1548; Docket 40-8964; Ground Water Monitoring at Well CM-39

Dear Mr. Lusher:

Power Resources, Inc. (PRI) is informing you that, due to an equipment malfunction, Well CM-39 in the C-Wellfield at the Highland Uranium Project will not be sampled within the 65-day limit as described in Section 6.1.3.4 of the License Amendment Application dated May 6, 2003. In accordance with Section 6.1.3.4, PRI has also informed Mr. Steve Ingle, WDEQ-LQD Project Manager, of this incident.

PRI anticipates that the well will be repaired within the next one-week period, at which time the well will be sampled. PRI does not anticipate any environmental concerns due to the delay in sampling, as the water quality at Well CM-39 has remained at baseline conditions since the startup of the C-Wellfield and that the C-Wellfield is currently undergoing ground water restoration.

If you have any questions or concerns, please call myself or Bill Kearney at (307) 358-6541.

Sincerely,

Scott Bakken
Sr. Environmental Scientist
Power Resources, Inc.

cc: File SR-HUP 4.6.4.1

CC: "Ralph Knode" <knode@coffey.com>, "Bill Kearney" <dowfk@coffey.com>, "Steve Collings" <SColli1945@aol.com>

Mail Envelope Properties (3F5F77CB.E35 : 18 : 21336)

Subject: Fwd: License SUA-1548; Docket 40-8964; Ground Water Monitoring at Well CM-39
Creation Date: 9/10/03 3:13PM
From: John Lusher
Created By: JHL@nrc.gov

Recipients

twf4_po.TWFN_DO
BSG (Betty Garrett)

Post Office

twf4_po.TWFN_DO

Route**Files**

Mail

MESSAGE

Size

670

Date & Time

09/10/03 03:13PM

Options

Expiration Date:

None

Priority:

Standard

Reply Requested:

No

Return Notification:

None

Concealed Subject:

No

Security:

Standard