

OAK RIDGE NATIONAL LABORATORY
OPERATED BY MARTIN MARIETTA ENERGY SYSTEMS, INC.

WM DOCKET CONTROL
CENTER

POST OFFICE BOX X
OAK RIDGE, TENNESSEE 37831

'86 / OCT 20 AM 11:46

Oct. 16, 1986

Dr. D. J. Brooks
Geotechnical Branch
Office of Nuclear Material
Safety and Safeguards
Room 623-SS
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Dave:

In response to your verbal request for short-term technical assistance, Don Kelmers, Jim Blencoe, and I came up with a few issues that we believe should be included on the agenda for a workshop on performance assessment for the Hanford Site. I have included our major concerns in the attached letter report. As necessary, we will be glad to provide more detail. Please call me if you have any questions.

Sincerely,

Gary K. Jacobs

Gary K. Jacobs
Manager, NRC Waste Programs
Environmental Sciences Division
Building 1505, MS-038, FTS/626-0567

GKJ/

Enclosure: Letter Report LR-287-61

cc: Office of the Director, NMSS (Attn: Program Support Branch)
Division Director, NMSS Division of Waste Management (2)
P. S. Justus, Chief, Geotechnical Branch, NMSS
K. C. Jackson, Geotechnical Branch, NMSS
J. G. Blencoe
A. D. Kelmers
A. P. Malinauskas
GKJ File

WM-RES
WM Record File
B0287
ORNL

WM Project 10, 11, 16
Docket No. _____

PDR ✓
LPDR ✓ (B, N, S)

Distribution:

DBrooks

(Return to WM, 623-SS)

Sac

8610280592 861016
PDR WMRES EXIORNL
B-0287 PDR

3408