Jeffrey T. Gasser Vice President Southern Nuclear Operating Company, Inc. 40 Inverness Center Parkway Post Office Box 1295 Birmingham, Alabama 35201

Tel 205.992.7721 Fax 205.992.0403



October 15, 2003

Docket Nos.: 50-424 50-425

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D. C. 20555-0001

> Vogtle Electric Generating Plant Monthly Operating Reports

Ladies and Gentlemen:

Enclosed are the September 2003 Monthly Operating Reports as required by Section 5.6.4 of the Technical Specifications.

Sincerely,

Man Jeffrey T. Gasser

JTG/NJS/daj

Enclosures: E1 – VEGP Unit 1 Monthly Operating Report E2 – VEGP Unit 2 Monthly Operating Report

cc: <u>Southern Nuclear Operating Company</u> Mr. J. D. Woodard, Executive Vice President Mr. W. F. Kitchens, General Manager – Plant Vogtle Mr. M. Sheibani, Engineering Supervisor – Plant Vogtle Document Services RTYPE: CVC7000

U. S. Nuclear Regulatory Commission Mr. L. A. Reyes, Regional Administrator Mr. F. Rinaldi, NRR Project Manager – Vogtle Mr. J. Zeiler, Senior Resident Inspector – Vogtle



OPERATING DATA REPORT

.

.

		Docket No.: Unit Name: Date: Completed By: Telephone:	50-424 VEGP UNIT 1 October 1, 2003 Andrew R. Cato (706) 826-3823
Operating Status			
 Reporting Period: Design Electrical Rating (Net MWe): Maximum Dependable Capacity (Net MWe): 	September 2003 1169 1152		
	This Month	Year-To-Date	Cumulative
 Number Of Hours Reactor Was Critical: Hours Generator On Line: Unit Reserve Shutdown Hours: Net Electrical Energy Generated (MWHe): 	650.8 649.6 0.0 744,645	<u> </u>	B 127,053.1 0 0.0

CHALLENGES TO PRESSURIZER PORV AND PRESSURIZER SAFETY VALVES

Date (YYMMDD)	Tag No.	Event Description	
N/A	N/A	N/A	

E1-1

UNIT SHUTDOWNS

.

.

Docket No.: Unit Name: Date: Completed By: Telephone:

50-424 VEGP UNIT 1 October 1, 2003 Andrew R. Cato (706) 826-3823

Reporting Period:

September 2003

No.	Date (YYMMDD)	Type F: Forced S: Scheduled	Duration (Hours)	Reason (1)	Method of Shutting Down (2)	Cause/Corrective Actions Comments
2003-02	03/09/28	s	70.40	с	1	See Below
· · ·						

(1) REASON:

- A Equipment Failure (Explain) E Operator Training/License Examination
- B Maintenance or Test

C - Refueling

- D Regulatory Restriction
- F Administrative G Operational Error (Explain)
 - H Other (Explain)

(2) METHOD:

- 1. Manual
- 2. Manual Trip/Scram

3. Automatic Trip/Scram

- 4. Continuation
- 5. Other

CAUSE/CORRECTIVE /	ACTION/COMMENTS:
--------------------	------------------

EVENT:	2003-02
CAUSE:	Scheduled Refueling Outage
CORRECTIVE ACTION:	Disassemble vessel, refuel reactor, reassemble vessel, and complete required outage work
CRITICAL PATH WAS:	Disassembly of vessel, refueling, reassembly of vessel, and mode change prerequisites.

NARRATIVE REPORT

September 01	00:00 Unit 1 at 100% power with no significant operating problems.
September 20	11:00 Unit 1 began coastdown in preparation for the scheduled refueling outage.
September 27	15:00 Unit 1 began ramp down for the scheduled refueling outage
September 28	01:34 Unit 1 Main Turbine tripped,
September 28	02:27 Unit 1 entered mode 2. Reactor manually shutdown.
September 28	02:48 Unit 1 entered mode 3.
September 28	12:53 Unit 1 entered mode 4.
September 28	16:00 Unit 1 entered mode 5.
September 30	23:59 Unit 1 in mode 5 for scheduled refueling outage.

E1-2

OPERATING DATA REPORT

.

•

		Docket No.: Unit Name: Date: Completed By: Telephone:	50-425 VEGP UNIT 2 October 1, 2003 Andrew R. Cato (706) 826-3823
Operating Status			
 Reporting Period: Design Electrical Rating (Net MWe): Maximum Dependable Capacity (Net MWe): 	September 2003 1169 1149		
	This Month	Year-To-Date	Cumulative
 Number Of Hours Reactor Was Critical: Hours Generator On Line: Unit Reserve Shutdown Hours: 	<u>650.1</u> 638.0 0.0	0.0	<u>3 113,762.2</u> 0 0.0
7. Net Electrical Energy Generated (MWHe):	733,087	7,124,120	5 128,335,492

CHALLENGES TO PRESSURIZER PORV AND PRESSURIZER SAFETY VALVES

Date (YYMMDD)	Tag No.	Event Description
N/A	N/A	N/A
		· · · ·

UNIT SHUTDOWNS

Docket No.: Unit Name: Date: Completed By: Telephone: 50-425 VEGP UNIT 2 October 1, 2003 Andrew R. Cato (706) 826-3823

Reporting Period:

September 2003

No.	Date (YYMMDD)	Type F: Forced S: Scheduled	Duration (Hours)	Reason (1)	Method of Shutting Down (2)	Cause/Corrective Actions Comments
2003-03	03/08/30	S	82	В	4	See Below

(1) REASON:

A - Equipment Failure (Explain) E - Operator Training/License Examination

CAUSE/CORRECTIVE ACTION/COMMENTS:

B - Maintenance or Test

C - Refueling

- D Regulatory Restriction
- G Operational Error (Explain)
 - H Other (Explain)

F - Administrative

(2) METHOD:

1. Manual

2. Manual Trip/Scram

3. Automatic Trip/Scram

- 4. Continuation
- 5. Other

 EVENT:
 2003-03

 CAUSE:
 RCS leak at canopy seal weld

 CORRECTIVE ACTION:
 Repairing the canopy seal weld leak on the Reactor Head.

CRITICAL PATH WAS:

Repairing the canopy seal weld and completion of prerequisites for mode changes.

NARRATIVE REPORT

September 0100:00Unit 2 in mode 5 repairing RCS leak.September 0220:56Unit 2 entered mode 4.September 0301:32Unit 2 entered mode 3.September 0320:48Unit 2 entered mode 2.September 0321:52Unit 2 reactor is critical.September 0404:16Unit 2 entered mode 1.September 0410:01Unit 2 Main Generator synchronized to the grid.September 0507:00Unit 2 returned to 100% power following the scheduled Maintenance outage.September 3023:59Unit 2 at 100% power with no significant operating problems.

E2-2 ·