achco

Surry Power Stacioa
P.O. Bux 315
Surry, Virginia 23883

April 28, 1975

Director of Regulatory Operations 230 Peachtree Street Suite 818 Atlanta, Georgia 30303

This is to inform you by telecopy of an Abnormal Occurrence that was noted on April 27, 1975 at Surry Nuclear Power Station.

With Unit #2 at intermediate shutdown, an accumulator discharge valve failed to open when a safety injection signal was initiated during Performanc Test 18.2.

E. M. Sweeney, Jr. Station Manager

50-28.1

8402270649 750502 PDR ADDCK 05000281 8