

**Vepco**

VIRGINIA ELECTRIC AND POWER COMPANY  
Surry Power Station  
P.O. Box 315  
Surry, Virginia 23883

February 3, 1975

Director of Regulatory Operations  
230 Peachtree Street  
Suite 818  
Atlanta, Georgia 30303

This is to inform you by teletype within twenty-four (24) hours of an Abnormal Occurrence that was noted on January 31, 1975, at Surry Nuclear Power Station.

Steam Generator narrow range level detector drifted high due to sludge in the reference leg.

*E. M. Sweeney, Jr.*  
E. M. Sweeney, Jr.  
Station Manager

50-280

8402280603 750219  
PDR ADOCK 05000280  
8 PDR