Change Notice 03-036

	DELETED:		TRANSMITTED:	
	Number	<u>Date</u>	Number	<u>Date</u>
1.	IMC 0302	09/27/95		
2.			IMC 0309	11/05/03
3.	IP 71111.20	01/17/02	IP 71111.20	11/05/03
4.	TI 2515/152	09/05/03	TI 2515/152, Rev 1	11/05/03

TRAINING: No special training requirements have been identified for any documents

issued with this change notice.

REMARKS: <u>IMC 0302</u> (Inspection Program Evaluation Activities) is deleted. The requirements of this IMC have been superceded by IMC 0307, "Reactor Oversight Process Self-Assessment Program."

<u>IMC 0309</u> (Reactive Inspection Decision Basis For Reactors) is issued to provide guidance for implementing Management Directive 8.3, "NRC Incident Investigation Program," at operating power reactors.

<u>IP 71111.20</u> (Refueling and Other Outage Activities) has been revised to address licensee procedures for foreign material exclusion, instruments tracking plant condition changes, training procedures for BWR alternate decay heat removal. It also cross references IMC 2515, Appendix D, "Plant Status" regarding plant status tours of areas accessible only during outages.

TI 2515/152, Revision 1 (Reactor Pressure Vessel Lower Head Penetration Nozzles (NRC Bulletin 2003-02)) has been revised to provide additional guidance on reporting requirements in inspection reports.

DISTRIBUTION: Standard

END