



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-4005

November 17, 2003

Craig G. Anderson, Vice President,
Operations
Arkansas Nuclear One
Entergy Operations, Inc.
1448 S.R. 333
Russellville, AR 72801-0967

Subject: REVISED INSPECTION SCHEDULE ARISING FROM REORGANIZATION OF
THE NRC REGION IV DIVISION OF REACTOR SAFETY

Dear Mr. Anderson:

The U.S. Nuclear Regulatory Commission (NRC), Region IV, has reorganized its Division of Reactor Safety (DRS) effective December 28, 2003.

The Division's inspection duties were formerly divided among three branches:

<u>Operations Branch</u>	<u>Plant Support Branch</u>	<u>Engineering & Maintenance Branch</u>
<ul style="list-style-type: none">■ Operator licensing■ Identification and Resolution of Problems (PI&R)	<ul style="list-style-type: none">■ Security■ Radiological Controls■ Emergency Preparedness	<ul style="list-style-type: none">■ Safety System Design and Performance Capability■ Permanent Plant Modifications■ Inservice Inspection Activities■ Evaluation of Changes, Tests or Experiments■ Fire Protection■ Heat Sink Performance■ Maintenance Effectiveness

Beginning in January, 2004, there will be four DRS inspection branches with inspection responsibilities as follows:

<u>Operations Branch</u>	<u>Performance Evaluation Branch</u>
<ul style="list-style-type: none">■ Initial Operator Licensing■ Operator Requalification Programs■ Emergency Preparedness■ PI&R Support	<ul style="list-style-type: none">■ PI&R Lead Responsibility■ Fire Protection■ Heat Sink Performance■ Maintenance Effectiveness

Engineering Branch

- Safety System Design and Performance Capability
- Permanent Plant Modifications
- Inservice Inspection Activities
- Evaluation of Changes, Tests or Experiments
- PI&R Support

Plant Support Branch

- Security
- Radiological Controls
- PI&R Support

The reorganization of DRS and the reallocation of inspection duties required changes to the 2004 calendar year inspection schedule. The new DRS inspection schedule for your plant is attached.

Sincerely,

/RA/

Dwight D. Chamberlain, Director
Division of Reactor Safety

Enclosure: as stated

Dockets: 50-313; 50-368
Licenses: DPR-51; NPF-6

cc w/enclosure:
Senior Vice President
& Chief Operating Officer
Entergy Operations, Inc.
P.O. Box 31995
Jackson, MS 39286-1995

Vice President
Operations Support
Entergy Operations, Inc.
P.O. Box 31995
Jackson, MS 39286-1995

Manager, Washington Nuclear Operations
ABB Combustion Engineering Nuclear
Power
12300 Twinbrook Parkway, Suite 330
Rockville, MD 20852

Entergy Operations, Inc.

-3-

County Judge of Pope County
Pope County Courthouse
100 West Main Street
Russellville, AR 72801

Winston & Strawn
1400 L Street, N.W.
Washington, DC 20005-3502

Bernard Bevill
Radiation Control Team Leader
Division of Radiation Control and
Emergency Management
Arkansas Department of Health
4815 West Markham Street, Mail Slot 30
Little Rock, AR 72205-3867

Mike Schoppman
Framatome ANP, Inc.
Suite 705
1911 North Fort Myer Drive
Rosslyn, VA 22209

Electronic distribution by RIV:
 Regional Administrator (**BSM1**)
 DRP Director (**ATH**)
 DRS Director (**DDC**)
 Senior Resident Inspector (**RWD**)
 Branch Chief, DRP/D (**LJS**)
 Senior Project Engineer, DRP/D (**JLT2**)
 Staff Chief, DRP/TSS (**PHH**)
 RITS Coordinator (**NBH**)

ADAMS: Yes No Initials: _____
 Publicly Available Non-Publicly Available Sensitive Non-Sensitive

C:EMB	C:OB	C:PSB	C:PBD	D:DRS
CSMarschall/lmb	ATGody	TWPruett	LJSmith	DDChamberlain
/RA/	/RA/	/RA/	/RA/	/RA/
11/13/03	11/10/03	11/13/03	11/13/03	11/17/03

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates Start	Planned Dates End	Inspection Type
	OB-IN - INITIAL EXAM		5			
1	X02257	ANO UNIT 1 - INITIAL EXAM (01/04)		01/12/2004	01/16/2004	Not Applicable
	LIC RNWL - LIC RNWL SCOPING & PLANNING INSPECTION		3			
2	IP 71002	License Renewal Inspection		02/09/2004	02/13/2004	License Renewal Insp
	ALARA1 - ALARA PLANNING AND CONTROLS		1			
1,2	IP 7112102	ALARA Planning and Controls		03/15/2004	03/19/2004	Baseline Inspections
	LIC RNWL - AGING MANAGEMENT INSPECTION		3			
2	IP 71002	License Renewal Inspection		04/12/2004	04/24/2004	License Renewal Insp
	EB-08P - ISI UNIT 1		1			
1	IP 7111108P	Inservice Inspection Activities - PWR		04/19/2004	04/23/2004	Baseline Inspections
1	IP 7111108P	Inservice Inspection Activities - PWR		05/03/2004	05/07/2004	Baseline Inspections
	ACCESSPI - ACRSA/PIV		1			
1,2	IP 7112101	Access Control to Radiologically Significant Areas		04/26/2004	04/30/2004	Baseline Inspections
	EB-17B - PERMANENT PLANT MODIFICATIONS		2			
1,2	IP 711117B	Permanent Plant Modifications		05/24/2004	05/28/2004	Baseline Inspections
	RPTEAM - RAD SAFETY TEAM		4			
1,2	IP 7112103	Radiation Monitoring Instrumentation and Protective Equipment		06/14/2004	06/18/2004	Baseline Inspections
1,2	IP 7112201	Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems		06/14/2004	06/18/2004	Baseline Inspections
1,2	IP 7112202	Radioactive Material Processing and Transportation		06/14/2004	06/18/2004	Baseline Inspections
1,2	IP 7112203	Radiological Environmental Monitoring Program		06/14/2004	06/18/2004	Baseline Inspections
	REQUAL - OB-REQUALIFICATION		2			
1,2	IP 711111B	Licensed Operator Requalification		07/19/2004	07/23/2004	Baseline Inspections
	ALARA2 - ALARA PLANNING AND CONTROLS		1			
1,2	IP 7112102	ALARA Planning and Controls		07/19/2004	07/23/2004	Baseline Inspections
	EMB - EVAL OF MAINTENANCE EFFECTIVENESS		1			
1,2	IP 711112B	Maintenance Effectiveness		08/16/2004	08/20/2004	Baseline Inspections
	EMB - TRIENNIAL FIRE PROTECTION INSPECTION		3			
1,2	IP 7111105T	Fire Protection		09/27/2004	10/01/2004	Baseline Inspections
1,2	IP 7111105T	Fire Protection		10/18/2004	10/22/2004	Baseline Inspections
	PSB-EP1 - EP EXERCISE		3			
1,2	IP 7111401	Exercise Evaluation		10/18/2004	10/22/2004	Baseline Inspections
1,2	IP 7111404	Emergency Action Level and Emergency Plan Changes		10/18/2004	10/22/2004	Baseline Inspections
1,2	IP 711151	Performance Indicator Verification		10/18/2004	10/22/2004	Baseline Inspections