

From: "Bill Kearney" <dowfk@coffey.com>
To: "John Lusher" <jhl@nrc.gov>, "Steve Ingle" <single@state.wy.us>
Date: 12/22/03 3:24PM
Subject: Wellfield Spill - Docket 40-8964

John/Steve:

Good afternoon. Please consider this communication notification that a spill of injection fluid occurred at the SR-HUP on Saturday 12/20/03. The spill occurred at the F-44 Headerhouse at the F-Wellfield. It was detected at about 10:30 am. The release occurred when a PVC end cap on an injection well meter run cracked and came off the one inch line. It was estimated that 600 gallons of injection fluid was released and a portion flowed out of the headerhouse. The fluid did not enter any waterway and it contained about 1.5 mg/L U3O8.

A written report will be forthcoming. If you have any questions, please call me.

Thanks

Bill Kearney

CC: "Josh Schultz" <jschultz@vcn.com>, "Ralph Knode" <knode@coffey.com>, "Steve Collings" <scolli1945@aol.com>

Mail Envelope Properties (3FE83FF3.957 : 18 : 22040)

Subject: Fwd: Wellfield Spill
Creation Date: 12/23/03 8:15AM
From: John Lusher

Created By: jhl@nrc.gov

Recipients

twf4_po.TWFN_DO
BSG (Betty Garrett)

Post Office

twf4_po.TWFN_DO

Route

Files	Size	Date & Time
Mail MESSAGE	362	12/23/03 08:15AM

Options

Expiration Date: None
Priority: Standard
Reply Requested: No
Return Notification: None

Concealed Subject: No
Security: Standard