

January 14, 2004

U.S. Nuclear Regulatory Commission **Attention: Document Control Desk** Washington, D.C. 20555

SUBJECT:

Entergy Nuclear Operations, Inc. Pilgrim Nuclear Power Station

Docket No.: 50-293 License No.: DPR-35

December 2003 Monthly Operating Report

LETTER NUMBER: 2.04.005

Dear Sir or Madam:

In accordance with Technical Specification 5.6.4, the operational status summary for Pilgrim Nuclear Power Station is provided in the attachment for your information and planning.

Should you have questions or comments concerning this report, please contact Mr. Bryan Ford at (508) 830-8403.

Sincerely,

Steve Bethay

Director, Nuclear Assessment

MJG/dm

Attachment: December 2003 Monthly Operating Report (1 page)

cc: Mr. Hubert Miller

Regional Administrator, Region I U.S. Nuclear Regulatory Commission 475 Allendale Road

King of Prussia, PA 19406

Senior Resident Inspector

OPERATING DATA REPORT

DOCKET NO.	50-293
UNIT NAME	Pilgrim 1
DATE	January 12, 2004
COMPLETED BY	Mary J. Gatslick
TELEPHONE	(508) 830-8373

REPORTING PERIOD: December 2003

1.	Design Electrical Rating	711.00
2.	Maximum Dependable Capacity (MWe-Net)	684.70

		<u>This Month</u>	<u>Yr-to-Date</u>	<u>Cumulative</u>
3.	Number of Hours the Reactor was Critical	744.00	7,662.10	190,154.90
4.	Number of Hours Generator On-line	744.00	7,548.15	187,944.95
5.	Reserve Shutdown Hours	0.00	0.00	0.00
6.	Net Electrical Energy Generated (MWHrs)	508,456.50	4,977,182.14	111,652,678.4

UNIT SHUTDOWNS

No.	Date	Type F: Forced S: Scheduled	Duration (Hours)	Reason 1	Method of Shutting Down 2	Cause & Corrective Action Comments
-----	------	-----------------------------------	---------------------	----------	---------------------------------	------------------------------------

SUMMARY: The period began with the unit on line, operating at 100% power (2028 MWt). On December 1st at 1950 hours, an unplanned power reduction from 100% to ~30% occurred as a result of a trip a recirculation motor generator set/pump while backing out of a surveillance test. The unit returned to 100% power on December 2nd at 1351 hours. On December 6th at 2045 hours, a power reduction from 100% to 77% was initiated as directed by the regional system operator (ISO-NE) due to electrical transmission system conditions. The unit returned to 100% power on December 7th at 0603 hours where it remained for the rest of the reporting period.

1 Reason:

A Equipment Failure (Explain)

B Maintenance or Test

C Refueling

D Regulatory Restriction

E Operator Training & License Examination

F Administration

G Operational Error (Explain)

H Other (Explain)

2 .

Method: 1 Manual

2 Manual Trip/Scram

3 Automatic Trip/Scram

4 Continuation

5 Other (Explain)