

WM Record File

101.2

WM Project

WM-10

Docket No.

PDR

LPDR

Distribution:

1

(Return to WM, 623-SS)

APR 29 1983

DISTRIBUTION

WM-10 (~~101.1~~) 101.2  
WMHT r/f  
NMSS r/f  
CF  
REBROWNING  
MBELL  
PALTOMARE  
HJMILLER  
RJWRIGHT  
JTGREEVES & r/f  
PDR

Telecom: Dated: 3/16/83 - 6:00 p.m.

NRC

BWIP

J. Greeves  
T. Verma  
P. Justus

A. Lassilla  
J. LaRue  
W. Price  
P. Long

The NRC staff initiated the call as a followup on some questions discussed earlier in the day regarding the recently received RRL-2 drill hole report.

After reviewing drilling history reports for core holes DC-4, DC-6 and DC-8, NRC noted mud loss reported within the dense interior of the Umtanum formation. This information can be found in the drilling history reports for the above core holes. Specifically, the following intervals were identified by NRC:

<u>Hole Number</u>	<u>Interval</u>
DC-4	3,622 and 3,789
DC-6	3,023 and 3,263
DC-8	3,567 and 3,821

BWIP advised that they would look into these reports and call back to discuss the data. It has been their experience that mud loss does not occur within the dense interior portion of the basalt flows.

*John T. Greeves*  
John T. Greeves, Section Leader  
Design Section  
High-Level Waste Technical  
Development Branch  
Division of Waste Management

*Robert S. Justus for*  
Philip S. Justus, Section Leader  
Siting Section  
High-Level Waste Technical  
Development Branch  
Division of Waste Management

8307220152 830429  
PDR WASTE  
WM-10 PDR

00426