

WM Cord File 101.1 WM Project WM-10
 Docket No. _____
 PDR ☒
 LPDR ☒
 Distribution: _____

 (Return to WM, 620 SS) JUN 6 1983

DISTRIBUTION

WM-10 (101.1) ✓
 WMHT r/f
 NMSS r/f
 CF
 REBROWNING
 MBELL
 PALTOMARE
 HJMILLER
 RWRIGHT & r/f
 PDR

PROJECT WM-10

MEMORANDUM FOR: R. Boyle, WMHL
 R. Cook, WMHL
 M. Knapp, WMHL
 P. Justus, WMHT
 J. Greeves, WMHT
 P. Prestholt, WMHT
 T. Verma, WMHT

FROM: Robert J. Wright
 High-Level Waste Technical
 Development Branch
 Division of Waste Management

SUBJECT: BWIP CLARIFICATION MEETING

Dates: June 13-16, 1983 in Richland.

Schedule: The following schedule of discussions, a revision of page iv, has been proposed to DOE-RL.

Monday, June 13 Groundwater
 Waste form/package

Tuesday, June 14 Geochemistry
 Performance assessment

Wednesday, June 15 Geology/site selection/environmental factors
 Repository design/quality assurance

Preparation: In preparation for the clarification meeting the following needs to be done in each technical area.

- (1) Scrub down Tables 2 and 3 to determine the comments in the DSCA that are omitted. Identify these by marking up pages of the DSCA and

JUN 6 1983

PROJECT WM-10/RJW/83/06/04/0

- 2 -

xeroxing copies. (I have unbound copies of the DSCA which can be used). Distribute copies of the mark-up as follows:

- 1 - Bell
- 1 - Miller
- 1 - Wright
- 10 - For use in Richland

(2) Categorize each item in the left column, "Description of Item" of Tables 2 and 3 by use of the following designation:

- A. Item is stated in a satisfactory way.
- B. Item is generally satisfactory but appears different from the intent of the DSCA: clarification is needed.
- C. Item does not appear to reflect the intent of the DSCA comment: discussion of apparent misunderstanding is needed

(3) Identify by asterisk the first priority items in Table 2 and any that may be in Table 3. At the same time seek to consolidate the item list by combining items that are substantially the same.

Next Meeting: We will meet at 9:30 a.m., in the 4th floor conference room on Thursday, June 9 to discuss preparations for the Richland meeting.

"ORIGINAL SIGNED BY"

Robert J. Wright
High-Level Waste Technical
Development Branch
Division of Waste Management

DesireeM 83/06/06

OFC	:	WMHT	:	WMHT	:	:	:	:	:
NAME	:	RJWright:dm	:	HJMiller	:	:	:	:	:
DATE	:	06/0/83	:	06/4/83	:	:	:	:	: