

AUG 17 1970

Jack R. Roeder, Chief, Materials Inspection and Enforcement Branch, Division of Compliance, HQ

TRANSMITTAL OF SATISFACTORY REPLY TO FORM AEC-592

Enclosed are copies of communications between CO:I and the indicated licensee. The licensee's reply is satisfactory.

<u>Licensee</u>	<u>Date of Inspection</u>	<u>Transmittal Date of Form AEC-592</u>
Pratt & Whitney Aircraft Div. United Aircraft Corporation 400 Main Street East Hartford, Connecticut License No. 06-0550-03	July 7, 1970	July 17, 1970

CO:I:EE

Paul R. Nelson
Senior Radiation Specialist

Enclosures:

1. Reply dated July 27, 1970
2. Acknowledgment dated August 17, 1970
3. Completed statistical Form

H-24

OFFICE ▶	CO					
SURNAME ▶	Epstein/at1	Nelson				
DATE ▶	8/17/70					

AUG 17 1970

Pratt and Whitney Aircraft Division
United Aircraft Corporation
400 Main Street
East Hartford, Connecticut 06108

Attention: Mr. J. Martin, Manager Health and Safety

Gentlemen:

Thank you for your letter dated July 27, 1970, informing us of the steps you have taken to correct the items of apparent noncompliance which we brought to your attention in our letter dated July 17, 1970. We will review these matters during our next inspection.

Your cooperation with us is appreciated.

Very truly yours,

Robert W. Kirkman
Director

CO:1:EE

OFFICE ▶	CO					
SURNAME ▶	<i>EE</i> Epstein/at1	<i>EE</i> Nelson				
DATE ▶	5/17/70					

U
A

July 27, 1970

Mr. Robert W. Kirkman, Director
United States Atomic Energy Commission
Division of Compliance
Region 1
970 Broad Street
Newark, New Jersey 07102


Dear Mr. Kirkman:

In response to your letter of July 17, 1970 requesting our position and our corrective action with respect to two items of noncompliance with AEC regulations for material handled in accordance with License Number 06-0550-03, I contacted Mr. W. F. Patton, Supervisor, Health and Safety Engineering, for Pratt & Whitney Aircraft.

Mr. Patton has notified me of the following corrective action:

- a. Noncompliance to 10 CFR 201(b)
Arrangements have been made to have air concentration in hot cells evaluated for each cell entry.
- b. Noncompliance to 10 CFR 20.407(b)(2)
A report was sent on July 13, 1970 covering the year 1969.

Sincerely,



J. A. Martin
Manager, Health and Safety
Loss Prevention

JAM:eyw

Region I, Division of Compliance

Routing Slip

To:

Epstein

Inspector

Response by licensee adequate

E.E.

Response by licensee inadequate

Comment on Inadequacy

CB Wilson

Reviewer

Concurrence

Non Concurrence

Comment on Non Concurrence