

9902080089

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

February 1, 1999

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Serial No. 99-011
NL&OS/ETS R0
Docket Nos. 50-338
50-280
50-281
License Nos. NPF-4
DPR-32
DPR-37

Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY
NORTH ANNA POWER STATION UNIT 1
SURRY POWER STATION UNITS 1 AND 2
COMPLETION OF THERMO-LAG 330-1 CORRECTIVE ACTIONS

In a December 18, 1997 letter (Serial No. 97-697), Virginia Electric and Power Company committed to take specific corrective actions with regard to Thermo-Lag 330-1 radiant energy shields for North Anna and Surry Power Stations. These corrective actions were incorporated into Confirmatory Orders Modifying Licenses as requirements for both North Anna and Surry Power Stations on June 15 and July 9, 1998, respectively. The corrective actions identified in that letter and the requirements of the Confirmatory Orders were completed during the last refueling outages for North Anna Unit 1 and Surry Unit 1 which ended in October and November 1998, respectively. The remaining corrective actions for Surry Unit 2 are scheduled for the April 1999 refueling outage.

If you have any further questions, please contact us.

Very truly yours,

JH For J.H. McCarthy

J. H. McCarthy, Manager
Nuclear Licensing and Operations Support

Commitments made in this letter:

1. None

1/0

A-1029

cc: U.S. Nuclear Regulatory Commission
Region II
Atlanta Federal Center
61 Forsyth Street, SW
Suite 23T85
Atlanta, Georgia 30303

Mr. M. J. Morgan
NRC Senior Resident Inspector
North Anna Power Station

Mr. R. A. Musser
NRC Senior Resident Inspector
Surry Power Station