

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

April 14, 2004

Jeffrey S. Forbes, Site Vice President Arkansas Nuclear One Entergy Operations, Inc. 1448 S.R. 333 Russellville, AR 72801-0967

SUBJECT: ERRATA FOR ARKANSAS NUCLEAR ONE, UNITS 1 AND 2 - NRC TRIENNIAL FIRE PROTECTION INSPECTION REPORT 50-313/01-06; 50-368/01-06

Dear Mr. Forbes:

Please replace the first page of the supplemental information attachment to NRC Inspection Report 50-313/01-06; 50-368/01-06, dated August 20, 2001, with the attached revised page. On the Supplemental Information page, unresolved items that were opened during this inspection were placed in error under a section titled "Items Opened and Closed." At the time of the report, these unresolved items were open.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/NRC/ADAMS/index.html (the Public Electronic Reading Room).

Should you have any questions concerning this correction, we will be pleased to discuss them with you.

Sincerely,

//RA//

Linda J. Smith, Chief Plant Engineering Branch Division of Reactor Safety

Enclosure:

Supplemental Information Attachment page from NRC Inspection Report 50-313/01-06; 50-368/01-06

-2-

Dockets: 50-313

50-368

Licenses: DPR-51

NPF-6

cc w/enclosure:

Senior Vice President & Chief Operating Officer Entergy Operations, Inc. P.O. Box 31995 Jackson, MS 39286-1995

Vice President
Operations Support
Entergy Operations, Inc.
P.O. Box 31995
Jackson, MS 39286-1995

Manager, Washington Nuclear Operations ABB Combustion Engineering Nuclear Power 12300 Twinbrook Parkway, Suite 330 Rockville, MD 20852

County Judge of Pope County Pope County Courthouse 100 West Main Street Russellville, AR 72801

Winston & Strawn 1400 L Street, N.W. Washington, DC 20005-3502

Bernard Bevill
Radiation Control Team Leader
Division of Radiation Control and
Emergency Management
Arkansas Department of Health
4815 West Markham Street, Mail Slot 30
Little Rock, AR 72205-3867

Mike Schoppman Framatome ANP, Inc. Suite 705 1911 North Fort Myer Drive Rosslyn, VA 22209

Entergy Operations, Inc3-					
Electronic distribution by RIV: Regional Administrator (BSM1) DRP Director (ATH) DRS Director (DDC) Senior Resident Inspector (RWD) Branch Chief, DRP/D (TWP) Senior Project Engineer, DRP/D (NLS) Staff Chief, DRP/TSS (PHH) RITS Coordinator (KEG) Rebecca Tadesse, OEDO RIV Coordinator (RXT) ANO Site Secretary (VLH)					
ADAMS: ■ Yes □ No Initials: <u>ljs</u> ■ Publicly Available □ Non-Publicly Available □ Sensitive ■ Non-Sensitive					
DOCUMENT: S\DRS\DRSLTRS\ANO errata 2001 FP.wpd					

RIV:PEB/RI	C:PEB		
TAMcConnell:jlh	LJSmith		
/RA/	/RA/		
4/40 /04	4/40 /04		

4/13 /04 4/13 / OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

<u>ATTACHMENT</u>

Supplemental Information

PARTIAL LIST OF PERSONS CONTACTED

<u>Licensee</u>

- L. Blocker, Shift Manager
- R. Cuilty, Procedure Group Writer
- G. Dobbs, Supervisor, Electrical Engineering
- M. Goecke, Procedure Group Writer
- R. Hendrix, Technical Specialist
- E. Jacks, Procedure Group Supervisor
- J. Johnson, Technical Specialist
- R. Kulbeth, Electrical Engineer
- B. Pace, Control Room Supervisor
- B. Possage, Reactor Operator
- M. Smith, Manager, Programs and Components
- R. Rispoli, Supervisor, Engineering
- T. Robinson, Technical Specialist
- J. Walker, Senior Lead Engineer
- D. Williams, Systems Engineer

NRC

- R. Bywater, Senior Resident Inspector, ANO
- J. S. Hyslop, Risk and Reliability Analyst, NRR
- K. Kennedy, Senior Reactor Analyst
- G. Mizuno, Senior Attorney, Office of General Council
- P. Qualls, Fire Protection Engineer, NRR
- M. Salley, Fire Protection Engineer, NRR
- K. Weaver, Resident Inspector, ANO

ITEMS OPENED, CLOSED, AND DISCUSSED

Opened

50-313;368//0106-01 URI Three conduits located in Fire Zone 98-J containing safe-

shutdown cables were wrapped using Hemyc. The acceptability of Hemyc for use as a 1-hour fire barrier is currently being reviewed by the NRC. This is considered an unresolved item,

pending the completion of that review.

50-313;368/0106-02 URI The acceptability of the use of manual actions in lieu of providing

protection for cables associated with equipment necessary for achieving and maintaining hot shutdown (for a fire in Fire Zones