



April 13, 2004

L-2004-092
10 CFR 50.36
10 CFR 50.4

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Re: St. Lucie Unit 1
Docket No. 50-335
Special Report
Steam Generator Tube Plugging Report

This letter is being sent pursuant to St. Lucie Unit 1 Technical Specification 4.4.5.5.a.
The following tubes were plugged during the Unit 1 refueling outage (SL1-19).

Steam Generator 1A - 3
Steam Generator 1B - 0

Cumulative tubes plugged during this outage and previous outages:

Steam Generator 1A - 14
Steam Generator 1B - 0

Please contact us should you have any questions regarding this information.

Very truly yours,

A handwritten signature in black ink, appearing to read "WJ", is written over the typed name of William Jefferson, Jr.

William Jefferson, Jr.
Vice President
St. Lucie Plant

WJ/spt

A001