Exelon Generation Company, LLC wy Byron Station 4450 North German Church Road Byron, IL 61010-9794

www.exeloncorp.com

May 15, 2004

LTR: BYRON 2004-0044 File: 2.12.1523

United States Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

> Byron Station, Units 1 and 2 Facility Operating License Nos. NPF-37 and NPF-66 NRC Docket Nos. STN 50-454 and STN 50-455

Subject: 2003 Annual Radiological Environmental Operating Report

In accordance with Technical Specification 5.6.2, "Annual Radiological Environmental Operating Report," we are submitting the Annual Radiological Environmental Operating Report (AREOR) for Byron Station. This report is required to be submitted to the NRC by May 15th of each year. Enclosed are two copies of this report. This report contains the results of the radiological environmental and meteorological monitoring programs. The Radioactive Effluent Release Report was submitted under separate cover. Also enclosed is a current revision of the Byron Station Offsite Dose Calculation Manual (ODCM).

If you have any questions regarding this information, please contact W. Grundmann, Regulatory Assurance Manager, at (815) 406-2800.

Respectfully,

ephen Hugynshi

Stephen E. Kuczynski Site Vice President Byron Nuclear Generating Station

SEK/ES/dd/rah

Attachments: AREOR ODCM

cc: Regional Administrator – NRC Region III NRC Senior Resident Inspector – Byron Station

IEDS AOO9

Exel[®]n

Nuclear