Richard L. Anderson Vice President - Nuclear Operations

PPL Susquehanna, LLC 769 Salem /Boulevard Berwick, PA 18603 Tel. 570.542.3883 Fax 570.542.1504 RLAnderson@pplweb.com



June 14, 2004

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Mail Stop O-P1-17 Washington, D.C. 20555-0001

SUSQUEHANNA STEAM ELECTRIC STATION MONTHLY OPERATING REPORTS
Docket Nos. 50-387/NPF-14 and 50-388/NPF-22
PLA-005777

The May 2004 Monthly Operating Reports for Susquehanna SES Units 1 and 2 are attached.

Very truly yours,

Richard L. Anderson

JJH/cmm

cc: NRC Region 1

NRC Sr. Resident Inspector, Mr. A. Blaney NRC Project Manager, Mr. R V. Guzman

IERY

OPERATING DATA REPORT



 DOCKET NO.
 50-387

 UNIT
 One

 DATE
 06/12/2004

 COMPLETED BY
 J. J. Hennings

 TELEPHONE
 (570) 542-3747

OPERATING STATUS

1.	Unit Name: Susquehanna Steam Electric S	Station (U1)		
2.	Reporting Period: May 2004			
3.	Design Electrical Rating (Net MWe): 1177*			
4.	Maximum Dependable Capacity (Net MWe) 1135*		,	
	•••	This Month	Yrto-Date	Cumulative
5.	Hours in Reporting Period	744	3,647	183,936
6.	Number of Hours Reactor Was Critical	744	2,366.2	152,851.0
7.	Hours Generator On-Line	744	2,316.4	150,556.0
8.	Unit Reserve Shutdown Hours	0	0	0
9.	Net Electrical Energy Generated (MWH)	849,436	2,389,840	155,003,278

NOTES:

^{*}Design Electrical Rating (DER) and Maximum Dependable Capacity (MDC) has been changed starting with the May reporting period due to turbine modifications that were completed in April. The values may change slightly following official review of the Turbine Acceptance Test in June.

UNIT SHUTDOWNS



 DOCKET NO.
 50-387

 UNIT
 One

 DATE
 06/12/2004

 COMPLETED BY
 J. J. Hennings

 TELEPHONE
 (570) 542-3747

REPORT MONTH May 2004

No.	Date	Туре	Duration (Hours)	Reason 2	Method of Shutting Down Reactor ³	Cause & Corrective Action To Prevent Recurrence
						No shutdowns this month

Summary: There wre no power reductions greater than 20%.

F. Forced
 S. Scheduled

2. Reason:

A – Equipment Failure (Explain)

B – Maintenance or Test

C-Refueling

D-Regulatory Restriction

E – Operator Training & Licensee Exam

F - Administrative

G - Operational Error (Explain)

3.

Method: 1 - Manual

2 - Manual Scram

3 - Automatic Scram

4 – Continuation from previous month

5 - Other

SUSQUEHANNA STEAM ELECTRIC STATION

Docket Number: 50-387
Completed by: J. J. Hennings Date: 06/12/04

Telephone: (570) 542-3747

Challenges to Main Steam Safety Relief Valves

None.

OPERATING DATA REPORT



DOCKET NO.
UNIT
DATE
COMPLETED BY
TELEPHONE

50-388 Two 06/12/04 J. J. Hennings (570) 542-3747

OPERATING STATUS

1.	Unit Name:	Susquehanna Steam Elec	tric Station (U2)	
2.	Reporting Period:	May 2004		
3.	Design Electrical Ratio	ng (Net MWe): 1182		
	Maximum Dependable	• •	1140	

5.	Hours in Reporting Period	This Month 744	Yrto-Date 3647.0	Cumulative 169,176
6.	Number of Hours Reactor Was Critical	744	3647.0	147,542.8
7.	Hours Generator On-Line	744	3647.0	145,555.6
8.	Unit Reserve Shutdown Hours	0	0	0
9.	Net Electrical Energy Generated (MWH)	823,862	4,217,736	152,975,747

NOTES:

UNIT SHUTDOWNS



DOCKET NO.
UNIT
DATE
COMPLETED BY
TELEPHONE

50-388
Two
06/12/04
J. J. Hennings
(570) 542-3747

REPORT MONTH May 2004

No.	Date	Туре	Duration (Hours)	Reason 2	Method of Shutting Down Reactor	Cause & Corrective Action to Prevent Recurrence
						No shutdowns this month.

Summary: The only power reduction greater than 20% was performed on 5/8/04 for a planned control rod sequence exchange and condenser maintenance. Power was reduced to 65% on 5/8/04 and was returned to 100% on 5/11/04.

1.

F. Forced

S. Scheduled

2.

Reason:

A – Equipment Failure (Explain)

B – Maintenance or Test

C-Refueling

D - Regulatory Restriction

E – Operator Training & Licensee Exam

F - Administrative

G – Operational Error (Explain)

3.

Method:

1 - Manual

2 - Manual Scram

3 - Automatic Scram

4 - Continuation from previous month

5 - Other

Page 1 of 1

SUSQUEHANNA STEAM ELECTRIC STATION

Docket Number: 50-388
Completed by: J. J. Hennings

Date: 06/12/2004

Telephone: (570) 542-3747

Challenges to Main Steam Safety Relief Valves

None.