

Crystal River Nuclear Plant Docket No. 50-302 Operating License No. DPR-72

Ref: ITS 5.7.1.2

June 14, 2004 3F0604-01

U.S. Nuclear Regulatory Commission

Attn: Document Control Desk Washington, DC 20555-0001

Subject:

Crystal River Unit 3 – May 2004 Monthly Operating Report

Dear Sir:

Florida Power Corporation, doing business as Progress Energy Florida, Inc., hereby submits the Crystal River Unit 3 (CR-3) May 2004 Monthly Operating Report in accordance with CR-3 Improved Technical Specification 5.7.1.2.

If you have any questions regarding this submittal, please contact Mr. Sid Powell, Supervisor, Licensing and Regulatory Programs at (352) 563-4883.

Sincerely.

J/A. Franke

Plant General Manager

JAF/ff

Attachment

xc: Regional Administrator, Region II

Senior Resident Inspector NRR Project Manager

Progress Energy Florida, Inc. Crystal River Nuclear Plant 15760 W. Power Line Street Crystal River, FL 34428 TERG

APPENDIX A OPERATING DATA REPORT

DOCKET NO. 50-302

UNIT NAME FLCRP-3

DATE June 1, 2004

COMPLETED BY K.V. Dyer

TELEPHONE (352) 795-6486 x3494

	REPORTING PERIOD (Month/Year):	May 2004		
		MONTH	YEAR TO DATE	CUMULATIVE
1	DESIGN ELECTRICAL RATING (MWe-Net)	860		
2	MAXIMUM DEPENDABLE CAPACITY (MWe-Net)	838		
3	NUMBER OF HOURS REACTOR WAS CRITICAL	744.0	3,597.2	169,668.5
4	NUMBER OF HOURS THE GENERATOR WAS ON LINE	744.0	3,575.3	167,302.9
5	UNIT RESERVE SHUTDOWN HOURS	0.0	0.0	0
6	NET ELECTRICAL ENERGY GENERATED (MWH)	635 435	3 061 834	130 910 835

NOTE On May 1, 2004, the pressurizer power operated relief valve (PORV) momentarily passed steam. This occurred when the PORV block valve was re-opened after being closed for 30 hours. The block valve had been closed to validate indications that the PORV was leaking slightly into its discharge drain line. The PORV operated as designed.

APPENDIX B UNIT SHUTDOWNS

DOCKET NO.	50-302
UNIT NAME	FLCRP-3
DATE	June 1, 2004
OMPLETED BY	K.V. Dyer
TELEPHONE	(352) 795-6486 x3494

REPORTING PERIOD: May 2004

No.	Type F: Forced S: Scheduled	Duration (Hours)	Reason (1)	Method of Shutting Down (2)	Cause / Corrective Actions Comments
None					
	·				
		·		·	

SUMMARY:

Crystal River Unit 3 operated the entire month without an outage.

(1) Reason:
A-EQUIPMENT FAILURE (Explain)
B-MAINTENANCE OR TEST
C-REFUELING
D-REGULATORY RESTRICTION
E-OPERATOR TRAINING / LICENSE EXAMINATION
F-ADMINISTRATIVE
G-OPERATIONAL ERROR (Explain)
H-OTHER (Explain)

(2) Method

1-MANUAL

2-MANUAL TRIP/SCRAM

3-AUTO TRIP/SCRAM

4-CONTINUATION

5-OTHER (Explain)

- (