



July 2, 2004

LICENSE SUA-1341  
DOCKET NO. 40-8502

Mr. Gary Janosko, Chief  
Fuel Cycle Facilities Branch  
U. S. Nuclear Regulatory Commission  
Mail Stop T-8A33  
Two White Flint North  
11545 Rockville Pike  
Rockville, MD 20852

**RE: Quarterly Progress Report of Monitor Wells on Excursion Status - 2nd Qtr. 2004**

Dear Mr. Janosko:

This letter serves as the progress report required by License Sections 11.2 and 12.2, for all of COGEMA's Wyoming operation wells on excursion status through the end the second quarter of 2004. Excursion status is defined as a monitor well which exceeds more than one upper control limit (UCL). Excursion status can be removed when a monitor well no longer exceeds more than one UCL for three consecutive weeks.


COGEMA has had no wells at either the Irigaray or Christensen Ranch project sites on excursion status during the second quarter of this year. Please contact me if you have any questions regarding this report.

Sincerely,

Tom Nicholson  
Environmental Specialist/RSO

cc: Donna Wichers/COGEMA

WP\2004REPT\NRC\NRC-EXC-2.wpd



LMSSO /