August 6, 2004

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Mail Stop P1-137 Washington, DC 20555-0001



ULNRC05040 TAC No. MC2899

Ladies and Gentlemen:

DOCKET NUMBER 50-483 CALLAWAY PLANT UNIT 1 UNION ELECTRIC CO. FACILITY OPERATING LICENSE NPF-30 Response to Request for Additional Information related to Security Plan

Reference

- 1. ULNRC-04857 dated June 2, 2003
- 2. ULNRC-04989 dated April 26, 2004
- 3. USNRC letter (B. Benny to G. L. Randolph) dated July 23, 2004

The enclosed documents are provided pursuant to July 23, 2004, request for additional information (Reference 3) concerning Callaway Plant Security Plan Section 9.4.1 and the Safeguards Contingency Plan.

NOTE: THE ATTACHMENTS TO THIS LETTER CONTAIN 'SAFEGUARDS INFORMATION' AND MUST BE PROTECTED ACCORDINGLY. UPON SEPARATION OF THE ATTACHMENTS, THIS LETTER IS 'DECONTROLLED'.

*N5IROS

ULNRC05040 August 6, 2004 Page 2

Please contact Mark Dunbar at 573-676-4205 to discuss any further issues or clarifications.

Sincerely,

Luke H. Graessle

Superintendent, Protective Services

LHG/rgh

Safeguards Enclosures:

1) Additional Information Concerning the Callaway Plant Security Plan (TAC NO MC2899).

ULNRC05040 August 6, 2004 Page 3

STATE OF MISSOURI)	
)	SS
CALLAWAY COUNTY)	

Luke H. Graessle of lawful age, being first duly sworn upon oath says that he is Superintendent, Protective Services, for Union Electric Company; that he has read the foregoing document and knows the content thereof; that he has executed the same for and on behalf of said company with full power and authority to do so; and that the facts therein stated are true and correct to the best of his knowledge, information and belief.

Luke H. Graessle
Superintendent, Protective Services

SUBSCRIBED and sworn to before me this day of August, 2004.

TERRA E. COOK
Notary Public - Notary Seal
STATE OF MISSOUR!
Callaway County
My Commission Expires May 13, 2006

Jerra E. Cook Notary Public

NOTE: THE ATTACHMENTS TO THIS LETTER CONTAIN 'SAFEGUARDS INFORMATION' AND MUST BE PROTECTED ACCORDINGLY. UPON SEPARATION OF THE ATTACHMENTS, THIS LETTER IS 'DECONTROLLED'.