

SAFEGUARDS INFORMATION

Entergy Nuclear Northeast Indian Point Energy Center 450 Broadway, GSB P.O. Box 249 Buchanan, NY 10511-0249 Tel 914 734 6700

Fred Dacimo Site Vice President Administration

August 27, 2004

Indian Point Unit Nos. 1, 2, and 3 Docket Nos. 50-03, 50-247, and 50-286 NL-04-107

Document Control Desk U. S. Nuclear Regulatory Commission Mail Station O-P1-17 Washington, D.C. 20555-0001

SUBJECT: Supplemental Response to Requests For Additional Information Re: Indian Point Units 1, 2 and 3 Security Plan (TAC Nos. MC2929 and MC2930)

Dear Sir:

Entergy Nuclear Operations, Inc., (ENO), is in receipt of requests for additional information (RAIs) (References 1 through 4). Our initial responses to these RAIs (References 5 through 10) identified a number of issues which were considered to be generic issues that were to be resolved using the security frequently asked question (SFAQ) process.

Those generic issues have now been resolved using the SFAQ process. Also, the NRC review team, by telephone conference, requested that we provide additional detail to earlier responses. The information provided in Attachment 1 to this letter completes our responses to the open NRC RAIs by agreeing to adopt the agreed upon language for the generic RAIs and providing the requested additional detail. Each RAI, for which we are updating our response, is identified by the Physical Security Plan (PSP) or Safeguards Contingency Plan (SCP) section number referenced in the original RAI. In addition, where our earlier responses simply referred to correspondence containing mutually acceptable language, we are updating those responses to reflect the actual text that will be inserted into the PSP and SCP.

This letter contains one new commitments. As noted in references 4 and 5, revised plan pages will be submitted when all RAI questions are resolved. If you have any questions or require additional information, please contact Mr. Patric W. Conroy, Manager, Licensing at (914) 734-6668.

I declare under penalty of perjury that the foregoing is true and correct. Executed on August 27, 2004.

Sincerely,

Fred R. Dacimo Site Vice President Indian Point Energy Center

SAFEGUARDS INFORMATION

NOTICE: ATTACHMENT 1 CONTAINS "SAFEGUARDS INFORMATION" AND MUST BE PROTECTED ACCORDINGLY. UPON SEPARATION OF ATTACHMENT 1 FROM THIS LETTER, THIS LETTER BECOMES "DECONTROLLED."

* NSIR05

SAFEGUARDS INFORMATION

Docket Nos. 50-03, 50-247, and 50-286 NL-04-107 Page 2 of 3

References

- 1. NRC Letter to Entergy, "Indian Point Nuclear Generating Station, Units 2 and 3 Request For Additional Information Re: Security Plan Sections 10-19 (TAC Nos. MC2929 and MC2930)," Dated June 16, 2004
- 2. NRC Letter to Entergy, "Indian Point Nuclear Generating Station, Units 2 and 3 Request For Additional Information Re: Security Plan Sections 1-9 (TAC Nos. MC2929 and MC2930)," Dated June 25, 2004
- 3. NRC Letter to Entergy, "Indian Point Nuclear Generating Station, Units 2 and 3 Request For Additional Information Re: Training and Qualification Plan (TAC Nos. MC2929 and MC2930)," Dated July 9, 2004
- NRC Letter to Entergy, "Indian Point Nuclear Generating Station, Units 2 and 3 Request For Additional Information Re: Safeguards Contingency Plan and Section 9.4.1 of the Physical Security Plan (TAC Nos. MC2929 and MC2930)," dated July 23, 2004
- 5. Entergy letter to NRC, NL-04-082, "Response To Request For Additional Information Re: Indian Point Units 1, 2 and 3 Security Plan Sections 10-19 (TAC Nos. MC2929 and MC2930)," dated July 8, 2004.
- 6. Entergy letter to NRC, NL-04-085, "Response To Request For Additional Information Re: Indian Point Units 1, 2 and 3 Security Plan Sections 1-9 (TAC Nos. MC2929 and MC2930)," dated July 14, 2004.
- 7. Entergy letter to NRC, NL-04-089, Response to Request For Additional Information Re: Indian Point Units 1, 2 and 3 Security Plan, Training and Qualification Plan (TAC Nos. MC2929 and MC2930)" dated July 26, 2004
- 8. Entergy letter to NRC, NL-04-094, "Supplemental Response To Request For Additional Information Re: Indian Point Units 1, 2 and 3 Security Plan Sections 1-19 (TAC Nos. MC2929 and MC2930)," dated August 4, 2004
- Entergy letter to NRC, NL-04-097, "Response to Request For Additional Information Re: Indian Point Units 1, 2 and 3 Safeguards Contingency Plan and Section 9.4.1 of the Physical Security Plan (TAC Nos. MC2929 and MC2930), Dated August 12, 2004
- Entergy Letter to NRC, NL-04-102, "Supplemental Response to Request For Additional Information Re: Indian Point Units 1, 2 and 3 Safeguards Contingency Plan and Section 9.4.1 of the Physical Security Plan (TAC Nos. MC2929 and MC2930)," Dated August 19, 2004

w/o attachments

CC:

Mr. Samuel J. Collins Regional Administrator-Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, Pennsylvania 19406-1415 Resident Inspectors' Office U.S. Nuclear Regulatory Commission Indian Point Unit 3 P.O. Box 337 Buchanan, NY 10511-0337

SAFEGUARDS INFORMATION

NOTICE: ATTACHMENT 1 CONTAINS "SAFEGUARDS INFORMATION" AND MUST BE PROTECTED ACCORDINGLY. UPON SEPARATION OF ATTACHMENT 1 FROM THIS LETTER, THIS LETTER BECOMES "DECONTROLLED."

SAFEGUARDS INFORMATION

Docket Nos. 50-03, 50-247, and 50-286 NL-04-107 Page 3 of 3

Mr. Patrick D. Milano, Sr. Project Manager Project Directorate I Division of Licensing Project Management Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Mail Stop O-8-C2 Washington, D.C. 20555-0001

Mr. Michael K. Webb, Project Manager Project Directorate IV Division of Licensing Project Management Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Mail Stop O-7-D1 Washington, D.C. 20555-0001 Mr. Robert L. Fretz Security Plan Review Team Project Directorate II Division of Licensing Project Management Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Mail Stop 8-B2 Washington, D.C. 20555-0001 w/att

Resident Inspectors' Office U.S. Nuclear Regulatory Commission Indian Point Unit 2 P.O. Box 59 Buchanan, NY 10511-0059

SAFEGUARDS INFORMATION

NOTICE: ATTACHMENT 1 CONTAINS "SAFEGUARDS INFORMATION" AND MUST BE PROTECTED ACCORDINGLY. UPON SEPARATION OF ATTACHMENT 1 FROM THIS LETTER, THIS LETTER BECOMES "DECONTROLLED."