

EXPERT SYSTEM LICENSE EVALUATION
EVALUATION REPORT FOR LICENSE 08-02534-10

--Type and form of materials licensed--
Material-- --Form--
AM-241 Loose material

--For evaluation purposes, amounts of the following materials were obtained--
Material-- --Form-- --Amount-- --Unit--
AM-241 LOOSE 0.0000020 CI

.. License was for loose materials, or materials handled loose
?. The loose materials on this license were not significant, and the site
was eliminated from consideration on this basis.

CATEGORY FOR POTENTIAL SITE CONTAMINATION:
LICENSE ELIMINATED FROM CONSIDERATION FOR SITE CONTAMINATION

The reason is: Insignfcant matls or amts

The reason for elimination was: Insignfcant matls or amts

EXPERT SYSTEM EVALUATION WAS BASED ON THE
INVENTORY RECORD IN JOB 0319, BOX 09

Docket

Licensee: DEPARTMENT OF THE NAVY DIAMOND ORDNANCE FUZE LAB.

Address: WASHINGTON 25, D. C.

Zip:

State of operation: DC

Site used: CONNECTICUT AVE & VAN NESS ST, WASH

Disposition information present: CERTIFICATE

Matl. Transfrd to: U.S. ARMY EDGEWOOD ARSENAL OPERAT.

License to which transferred: 19-1826-6

This license was listed as expired on 03/31/68

Remarks:

JOB NUMBER: 0319

BOX NUMBER: 09

B-49