

Straka, Donald J(Z99942)

From: Kesler, Steven L(Z55768)
Sent: Wednesday, June 16, 2004 10:13 AM
To: Paramithas, Panos (V72983); Leake, Harvey C(Z60326)
Cc: Kesler, Steven L(Z55768); Phegley, Steven D(K74768)
Subject: Additional Digital Pictures of the Failed AR Relay

The pictures below show the nameplate and the contacts a little clearer. The location of the contacts makes it difficult to get a clear picture.
Steve K.

-----Original Message-----

From: Silva, Richard R(K85919)
Sent: Wednesday, June 16, 2004 9:27 AM
To: Kesler, Steven L(Z55768)
Cc: Phegley, Steven D(K74768)
Subject: Better photo of name plate



Liberty

neplate.jpg (102 KB)



Liberty Front

View.jpg (94 KB)...

A/23
A/23

Westinghouse

STYLE 606B017A09A

125
VOLTS

DC
HERTZ

122R03701A

TYPE
AP
REDAV



INSTRUCTION LEAFLET
41-759

WESTINGHOUSE ELECTRIC CO.



