



Palo Verde Nuclear
Generating Station

David Mauldin
Vice President
Nuclear Engineering
and Support

Order EA-03-009

Mail Station 7605
P.O. Box 52034
Phoenix, AZ 85072-2034

TEL (623) 393-5553
FAX (623) 393-6077

102-05169-CDM/SAB/RJR
October 28, 2004

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 3
Docket No. STN 50-530
First Revised NRC Order EA-03-009 – Control Element Drive
Mechanism (CEDM) Nozzles Minimum Distances**

During a phone call on October, 20, 2004, Arizona Public Service (APS) was asked by the NRC to verify that the required minimum CEDM inspection distances for PVNGS Unit 3 identified in APS letter 102-05123, dated July 01, 2004, were achieved. This information was requested to support the NRC review of APS' request for relaxation from First Revised NRC Order EA-03-009.

APS has completed the Unit 3 CEDM nozzle inspection conducted during the current refueling outage (U3R11). The results of this inspection confirm that the minimum required inspection distances identified for Unit 3 in APS letter 102-05123 dated July 1, 2004, were achieved.

No commitments are being made to the NRC in this letter. Should you have any questions, please contact Thomas N. Weber at (623) 393-5764.

Sincerely,

CDM/SAB/RJR

cc: B. S. Mallett
M. B. Fields
N. L. Salgado

A101