

VOID SHEET

TO: License Fee Management Branch

FROM: RIII - COLLEEN CASEY

SUBJECT: VOIDED APPLICATION

Control Number: 313692

Applicant: RADIOLOGY ASSOCIATES, PC,

License Number: 21-16754-01

Docket Number: 030-11590

Date Voided: 11-17-04

Reason for Void: The application letter contained deficiencies and the licensee could not be reached by phone. A deficiency letter was sent & action voided until response submitted.

Colleen Carroll Casey
Signature

11-16-04
Date

Attachment:
Official Record Copy of
Voided Action

FOR LFMB USE ONLY

- Refund Authorized and processed
- No Refund Due
- Fee Exempt or Fee Not Required

Comments: _____

Log completed _____
Processed by: _____



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION III
2443 WARRENVILLE ROAD
LISLE, ILLINOIS 60532-4352

NOV 16 2004

John Mellen, M.D.
Radiology Associates, P.C.
2284 South Ballenger Highway
Flint, MI 48503

Dear Dr. Mellen:

This refers to your letter dated July 19, 2004, requesting an amendment to your license number 21-16754-01 to remove the facility located at 1048 Gilbert Street, Flint, Michigan from the license.

The information provided by your letter was insufficient to complete my review. I unsuccessfully attempted to contact you by telephone several times on November 16, 2004, and November 17, 2004. Apparently the telephone number we have on file for you is incorrect, 586-778-7870. Please advise us of the correct telephone and facsimile numbers for your licensed program.

As we cannot continue to process your request and cannot reach you by telephone, we have voided your request at this time. This action is without prejudice to resubmission. If you resubmit your request please state that the resubmission is additional information to Control Number 313692 and reference it to my attention at the above address.

Your letter stated that a current copy of the leak test results for the sealed sources used at the Gilbert Street facility were included. They were not included with the July 19, 2004, letter. Please submit a copy of the most recent leak test results for the sealed sources used at the Gilbert Street facility. We will then continue our review.

In addition, I noted that your letter stated "This facility is exempt from decommissioning due to low volumes and short physical half-lives of materials used." Please be advised that this statement is incorrect. Your facility is not exempt from decommissioning for any reason.

Please note that on October 25, 2004, the NRC suspended public access to ADAMS, and initiated an additional security review of publicly available documents to ensure that potentially sensitive information is removed from the ADAMS database accessible through the NRC's web site. Interested members of the public may obtain copies of the referenced documents for review and/or copying by contacting the Public Document Room pending resumption of public access to ADAMS. The NRC Public Document Room is located at NRC Headquarters in Rockville, MD, and can be contacted at 800-397-4209 or 301-415-4737 or pdr@nrc.gov

If you have any questions or require clarification on any of the information stated above, you may contact me at (630) 829-9841.

Sincerely,

A handwritten signature in cursive script that reads "Colleen Carol Casey".

Colleen Carol Casey
Materials Licensing Branch

License No. 21-16754-01
Docket No. 030-11590



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**

REGION III
2443 WARRENVILLE ROAD, SUITE 210
LISLE, ILLINOIS 60532-4352

September 20, 2004

John David Mellen, M.D.
Radiation Safety Officer
Radiology Associates, P.C.
2284 South Ballenger Highway
Flint, MI 48503

SUBJECT: ACKNOWLEDGMENT OF CORRESPONDENCE
(Letter Dated 7/19/2004)

Dear John David Mellen, M.D.:

In response to your request, we have completed the initial processing, which is an administrative review of your application for a(n):

New License Amendment Termination

No Administrative deficiencies were identified during this initial review. However, it should be noted that a technical review may identify omissions in the submitted information.

It appears that your request is routine (see 1-2 below, as applicable).

1. New and Amendment actions are normally processed within 90 days, unless we find major deficiencies, or policy issues requiring central program office assistance.
2. Termination actions are normally processed within 90 days, unless confirmatory surveys following decontamination/decommissioning activities are involved.

We will try to complete your request as soon as practicable. Any correspondence about this request should reference the control number(s). Please direct any questions concerning your request to the Materials Licensing Branch at (630) 829-9887.

Materials Licensing Branch

Mail Control No. 313692
License No. 21-16754-01