

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Strata Data, Inc.
2080 Fairgrounds Road
Casper, Wyoming

2. NRC/REGIONAL OFFICE

USNRC Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, Texas 76011-4005

REPORT NUMBER(S) 2004-002

3. DOCKET NUMBER(S)

030-20110

4. LICENSEE NUMBER(S)

49-21256-01

5. DATE(S) OF INSPECTION

November 19 , 2004

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



1. Based on the inspection findings, no violations were identified.



2. Previous violation(s) closed.



3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):



4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title

Printed Name

Signature

Date

LICENSEE'S
REPRESENTATIVE

NRC INSPECTOR

James L. Thompson**/RA/****11/19/2004**

Docket File Information
**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Strata Data, Inc. REPORT NUMBER(S) 2004-002		2. NRC/REGIONAL OFFICE USNRC Region IV	
3. DOCKET NUMBER(S) 030-20110	4. LICENSE NUMBER(S) 49-21256-01	5. DATE(S) OF INSPECTION 11/19/2004	
6. INSPECTION PROCEDURES USED 87123	7. INSPECTION FOCUS AREAS All		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 03111	2. PRIORITY 3	3. LICENSEE CONTACT Bruce McDonald, President, RSO	4. TELEPHONE NUMBER (307) 267-0932
<input checked="" type="checkbox"/> Main Office Inspection		Next Inspection Date: 11/19/2007	
<input type="checkbox"/> Field Office			
<input type="checkbox"/> Temporary Job Site			

PROGRAM SCOPE

This is a small well logging operation consisting of only two well logging supervisors. There are 10 sealed sources possessed by the licensee, and no tracer material is authorized nor used. The president of the company is also the RSO and one of the two logging supervisors. Average work load is approximately 1 job per week, with work performed in Colorado and Wyoming.

There are three radiation survey meters maintained and properly calibrated. Security of material was adequate, and radiation exposure from the storage area are equivalent to background radiation levels, due to the sealed sources being stored in their shielded transport containers.