

ROBERT WOOD JOHNSON  
UNIVERSITY HOSPITAL  
HAMILTON

December 3, 2004

United States Nuclear Regulatory Commission  
Licensing Assistance Section  
475 Allendale Road  
King of Prussia, PA 19406-1415

04 DEC 10 P2:26


RECEIVED  
REGION 1

To Whom It May Concern, 03010491

Robert Wood Johnson University Hospital at Hamilton, license number 29-16145-01 wishes to amend our byproduct materials license to relocate our nuclear stress lab, Room 1, from its current location within the Cardiology Department, to a new area of use within the Radiology Department for the administration of radiopharmaceuticals used during cardiac stress testing. A copy of the area is enclosed for your review. We will perform a daily area survey of the new location and a weekly wipe test. We will also perform a final survey and wipe test of the existing area prior to releasing the area for unrestricted use, a copy of which will be forwarded to your office. We would appreciate it if you could expedite this request as we are in need of space to commence renovations within the cardiology department.

Should you have any additional questions, please contact our Radiation Safety Officer, Ms. Janet Bryant, MS through her office at 908-788-9440.

Sincerely,




Christy Stephenson  
President and Chief Executive Officer

cc. Mr. Jim Kilmer

136110

NMSS/RGNI MATERIALS-002

FILE AREA



RADIOLOGY CORRIDOR

This is to acknowledge the receipt of your letter/application dated

12/3/2004, and to inform you that the initial processing which includes an administrative review has been performed.

☒ AMEND 29-16145-01 There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

☐ Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 136110.  
When calling to inquire about this action, please refer to this control number.  
You may call us on (610) 337-5398, or 337-5260.

BETWEEN:

License Fee Management Branch, ARM  
and  
Regional Licensing Sections

: (FOR LFMS USE)  
: INFORMATION FROM LTS  
: -----  
:  
: Program Code: 02120  
: Status Code: 0  
: Fee Category: 7C  
: Exp. Date: 20130228  
: Fee Comments: CODE 23  
: Decom Fin Assur Req'd: N  
: ::::::::::::::::::::::::::::::::::::::

LICENSE FEE TRANSMITTAL

A. REGION I

1. APPLICATION ATTACHED

Applicant/Licensee: ROBERT WOOD JOHNSON UNIV. HOSP. AT  
Received Date: 20041210  
Docket No: 3010491  
Control No.: 136110  
License No.: 29-16145-01  
Action Type: Amendment

2. FEE ATTACHED

Amount: /  
Check No.: /

3. COMMENTS

Signed M. A. Perlman  
Date 12/13/04

B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered /\_\_/)

1. Fee Category and Amount: \_\_\_\_\_

2. Correct Fee Paid. Application may be processed for:

Amendment \_\_\_\_\_  
Renewal \_\_\_\_\_  
License \_\_\_\_\_

3. OTHER \_\_\_\_\_  
\_\_\_\_\_

Signed \_\_\_\_\_  
Date \_\_\_\_\_