



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
475 ALLENDALE ROAD
KING OF PRUSSIA, PENNSYLVANIA 19406-1415

December 27, 2004

Docket No. 03035002

License No. 45-25467-01

R. Drew Thomas, C.P.G.
Radiation Safety Officer
GeoConcepts Engineering, Inc.
19955 Highland Vista Drive, Suite 170
Ashburn, VA 20147

**SUBJECT: INSPECTION 03035002/2004001, GEOCONCEPTS ENGINEERING, INC.,
ASHBURN, VIRGINIA SITE AND NOTICE OF VIOLATION**

Dear Mr. Thomas:

On December 1, 2004, Jenny Johansen of this office conducted a safety inspection at the above address of activities authorized by the above listed NRC license. The inspection was an examination of your licensed activities as they relate to radiation safety and to compliance with the Commission's regulations and the license conditions. The inspection consisted of observations by the inspector, interviews with personnel, and a selected examination of representative records. The findings of the inspection were discussed with yourself of your organization at the conclusion of the inspection.

Based on the results of this inspection, it appears that your activities were not conducted in full compliance with NRC requirements. A Notice of Violation is enclosed that categorizes the violation by severity level in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," (Enforcement Policy), NUREG 1600. You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. Your response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

Please note that on October 25, 2004, the NRC suspended public access to ADAMS, and initiated an additional security review of publicly available documents to ensure that potentially sensitive information is removed from the ADAMS database accessible through the NRC's web site. Interested members of the public may obtain copies of the referenced documents for review and/or copying by contacting the NRC Public Document Room pending resumption of public access to ADAMS. The NRC Public Document Room is located at NRC Headquarters in Rockville, MD, and can be contacted at 800-397-4209 or 301-415-4737 or pdr@nrc.gov.

R. Thomas
GeoConcepts Engineering, Inc.

2

Your cooperation with us is appreciated.

Sincerely,

Original signed by John D. Kinneman

John D. Kinneman, Chief
Security and Industrial Branch
Division of Nuclear Materials Safety

Enclosure:
Notice of Violation

cc:
Commonwealth of Virginia

R. Thomas
GeoConcepts Engineering, Inc.

Distribution:
D. J. Holody, RI

DOCUMENT NAME: E:\Filenet\ML043620405.wpd

To receive a copy of this document, indicate in the box: "C" = Copy w/o attach/encl "E" = Copy w/ attach/encl "N" = No copy

OFFICE	DNMS/RI	N	DNMS/RI	N	DNMS/RI			
NAME	Jjohansen/jmj		JDKinneman/jdk					
DATE	12/20/2004		12/27/2004					

OFFICIAL RECORD COPY

NOTICE OF VIOLATION

GeoConcepts Engineering, Inc.
Ashburn, VA

Docket No. 03035002
License No. 45-25467-01

During an NRC inspection conducted on December 1, 2004, one violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," (Enforcement Policy), NUREG-1600, the violation is listed below:

- A. 10 CFR 71.5(a) requires that a licensee who transports licensed material outside of the site of usage, as specified in the NRC license, or where transport is on public highways, or who delivers licensed material to a carrier for transport, comply with the applicable requirements of the regulations appropriate to the mode of transport of the Department of Transportation (DOT) in 49 CFR Parts 170 through 189.

49 CFR 172.202(a) and (b) require in part, with exceptions not applicable here, that the shipping description of a hazardous material on the shipping paper include, in the following sequence: (1) the proper shipping name prescribed for the material in 172.101 (2) the hazard class prescribed for the material as shown in Column 3 of the 172.101 Table, and (3) the identification number prescribed for the material as shown in Column 4 of the 172.101 Table. Pursuant to 49 CFR 172.101, radioactive material is classified as hazardous material.

Contrary to the above, between October 1, 2002 and December 1, 2004, the licensee transported outside the confines of its plant, licensed material, and the shipping description on the shipping paper that accompanied the shipments did not include the identification number prescribed for the material as shown in Column 4 of the 172.101 Table, which was effective October 1, 2003. Specifically, the licensee's shipping paper referred to identification number UN2974 instead of UN3332 and the gauges were transported on public roads in Virginia.

This is a Severity Level IV violation (Supplement V).

Pursuant to the provisions of 10 CFR 2.201, GeoConcepts Engineering, Inc. is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555, with a copy to the Regional Administrator, Region I, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Your response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. If an adequate reply is not received within the time specified in this Notice, an order or a Demand for Information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Notice of Violation
GeoConcepts Engineering, Inc.

2

If you contest this enforcement action, you should also provide a copy of your response to the Director, Office of Enforcement, United States Nuclear Regulatory Commission, Washington, DC 20555-0001. Under the authority of Section 182 of the Act, 42 U.S.C. 2232, any response which contests an enforcement action shall be submitted under oath or affirmation.

Your response will be placed in the NRC Public Document Room (PDR) and on the NRC Web site at <http://www.nrc.gov/reading-rm.html>. To the extent possible, it should, therefore, not include any personal privacy, proprietary, or safeguards information so that it can be made publically available without redaction. However, if you find it necessary to include such information, you should clearly indicate the specific information that you desire not to be placed in the PDR, and provide the legal basis to support your request for withholding the information from the public.

In accordance with 10 CFR 19.11, you may be required to post this Notice within two working days.

Dated This 27th day of December, 2004