

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Evanston Hospital Corporation 190 Arrowhead Drive Evanston, Wyoming		2. NRC/REGIONAL OFFICE USNRC Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005	
REPORT NUMBER(S) 2004-001			
3. DOCKET NUMBER(S) 030-33981	4. LICENSEE NUMBER(S) 49-27532-01	5. DATE(S) OF INSPECTION 12 / 14 / 2004	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	James L. Thompson	/RA/	12/14/2004

**Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Evanston Hospital Corporation REPORT NUMBER(S) 2004-001		2. NRC/REGIONAL OFFICE USNRC Region IV	
3. DOCKET NUMBER(S) 030-33981	4. LICENSE NUMBER(S) 49-27532-01	5. DATE(S) OF INSPECTION 12/14/2004	
6. INSPECTION PROCEDURES USED 87130	7. INSPECTION FOCUS AREAS all		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02121	2. PRIORITY 5	3. LICENSEE CONTACT R. Clifford Park, CEO	4. TELEPHONE NUMBER (307) 783-8260
<input checked="" type="checkbox"/> Main Office Inspection		Next Inspection Date: 12/14/2009	
<input type="checkbox"/> Field Office _____			
<input type="checkbox"/> Temporary Job Site _____			

PROGRAM SCOPE

This is a relatively small medical licensee, only licensed for 100 and 200 material. There are two nuclear medicine technologists employed. Diagnostic studies are performed on Mondays, Wednesdays, and Fridays, with mostly Tc-99m. This licensee possesses five sealed check sources used for equipment checks.

A local physicist consults the radiation program quarterly, and the Radiation Safety Committee meets quarterly as well. No exposures for 2003 were greater than 100 millirem. The licensee possesses one radiation survey meter.