NRC FORM 591M PART 1 (10-2003)		U.S. NUCLEAR REGULATORY COMMISSION		
10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION				
1. LICENSEE/LOCATION INSPECTED: Buzdor Engineering 3705 Arctic Boulevard, #1593 Anchorage, Alaska 99503 REPORT NUMBER(S) 04-001		2. NRC/REGIONAL OFFICE USNRC Region IV 611 Ryan Plaza Drive Arlington, Texas 76011-4005		
3. DOCKET NUMBER(S)	4. LICENSEE NUMBER(S)		5. DATE(S) OF INSPECTION	
030-34945	50-27622-01		December/ 5 2004	
LICENSEE:				
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:          1. Based on the inspection findings, no violations were identified.         2. Previous violation(s) closed.         3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.				
<ul> <li>4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.</li> <li>(Violations and Corrective Actions) <ol> <li>FAILURE TO CONDUCT ANNUAL PROGRAM Reviews <ol> <li>FAILURE TO CONDUCT ANNUAL PROGRAM Reviews </li> <li>NUREG 1556 vol. 1, appendix F.</li> </ol> </li> <li>FAILURE TO CONDUCT A PUBLIC DOSE ASSESsment AT </li> <li>FAILURE TO CONDUCT A PUBLIC DOSE ASSESsment AT </li> <li>BOTH STERAGE LO CATIONS - LIZENSEE will use methodology in </li> <li>NUREG 1556. vol. 1, appendix I (10 CFR 1801) </li> <li>FAILURE TO PROVIDE HAZMAT REFRESSMENT FAMILYES </li> <li>FAILURE TO PROVIDE HAZMAT REFRESSMENT FAMILYES </li> <li>Guery 3 yeas per 49 CFR 172. Foo to FOY. Licensee will seek. </li> <li>Local training or down Loud HAZMAT moduly from Dot web site. </li> </ol></li></ul>				
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested. Title Printed Name Date				
LICENSEE'S REPRESENTATIVE	BUZDOR	CC	0	12/15/02
NRC INSPECTOR Lawrence	ce Donovan	Lawren	, Nonova	12/15/04

NRC FORM 591M PART 1 (10-2003)