NRC FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMM									
(10-2003) 10 CFR 2.201									
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION									
	NODEOTED								
1. LICENSEE/LOCATION Materials Integri		2.	. NRC/REGIONAL OFFICE						
P.O. Box 22105	1		USNRC Region IV						
Anchorage, Alaska 99522-1051			USNRC Region IV 611 Ryan Plaza Drive Arlington, Texas 76011-4005						
			Annigton, Texas I	0011-4005					
REPORT NUMBER(S)	04-001								
3. DOCKET NUMBER(S)		4. LICENSEE NUMBER(S)	:	5. DATE(S) OF INSPECTION					
030-35951		50-27722-01		December 14, 200	4				
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X 1. Based on the inspection findings, no violations were identified. Q 2. Previous violation(s) closed. 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.									
4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)									
	Licensee's	s Statement of Correcti	ve Actions for Item 4	, ab <mark>ove.</mark>					
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of									
corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.									
Title Printed Name Signature Date									
LICENSEE'S REPRESENTATIVE									
NRC INSPECTOR	Lawrenc	e Donovan	/F	RA/	12/14/04				
NRC FORM 591M PART 1	(10-2003)								

NRC FORM 591M PART 3 (10-2003) 10 CFR 2.201 U.S. NUCLEAR REGULATORY COMMISSION

Docket File Information SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE				2. NRC/REGIONAL OFFICE					
Materials Integrity, Inc REPORT NUMBER(S) 04-01				USNRC Region IV					
3. DOCKET NUMBER(S) 030-35951		4. LICENSE NUMBER(S) 50-27722-01		5. DATE(S) OF INSPECTION December 14, 2004					
6. INSPECTION PROCEDURES USED		7. INSPECTION FOCUS AREAS 03.01-03.07							
	SUPPLEMENTAL INSPECTION INFORMATION								
1.	PROGRAM CODE(S) 3310	2. PRIORITY 1	3. LICENSEE CONTACT John Lobe, RS		4. TELEPHONE NUMBER 907-345-5967				
	X Main Office Inspection Next Inspection Date: December 2005								
	Field Office								
	Temporary Job Site								
PROGRAM SCOPE									
Small Industrial Radiography Licensee. The President of the company is the RSO and sole user. There are 3 assistants. Licensee possesses one Spec 150 camera. Usage was approximately 46 times during 2004. License authorizes storage in Anchorage and a field station in Fairbanks, but use is mainly in Fairbanks. The licensee is also authorized portable gauges under a different license which are stored and used in Anchorage. All documentation was in order. Last inspection was December 2003 and was clear. This inspection resulted in no violations and a clear 591M was issued on site.									