From:

Charles R. Ogle , R. 2 Payne, Charlie 6/24/04 7:38AM

To: Date:

Subject:

Fwd: Re: HELP ON SUMMER INSPECTION

If you still need help

From:

Sunil Weerakkody , N EM

To:

Ogle, Charles R. 6/22/04 5:30PM

Date: Subject:

Re: HELP ON SUMMER INSPECTION

Chuck: .

I was at meetings all day. I called the number in the appended Email around 5.20 PM. Please ask Charile to contact either Phil Qualls (301-415-1849) or Alex Klein (301-415-3477). In the mean time, here is my two cents (Please confirm with Alex or Phil you proceed):

- 1. The licensee may have an unapproved Manual Action.
- 2. If they do, Charlie should focus on determining the feasibility of the action using March 2003 Feasibility Criteria.
- 3. If they meet the criteria, this becomes an open Item (a green NCV).

They should be able close it when we issue the interim enforcement discretion, until the rule is finalized.

4. If they cannot meet the March 2003 criteria, then the risk could be higher and you enter the enforcement space.

>>> Charles R. Ogle 06/22/04 09:37AM >>>

I know your folks are really busy, but we need to have someone talk to Charlie at Summer. We are in the second week of the TFP and are finding <u>major</u> problems with the licensee's compliance strategy with Appendix R. As I understand it, they did not provide the protection required by III.G.2 and instead de-energize the electrical busses to avoid any maloperations. They then send operators out in the field to perform manual actions to verify that the de-energize components are in the proper position.

In response to our queries, the licensee has been unable to provide any licensing basis documentation to justify their approach. Though they are still looking for paper, their latest position is that this was discussed in phone calls with the NRC when they set up their fire protection program.

Looking ahead, assuming the licensee can't find any paper to document that this approach received NRC approval, I expect the risk will be very large.

Before we get too far down this path, I'd like to have the inspectors talk this over with a technical expert to ensure that we aren't missing something really obvious. If one of your folks has a minute, I'd appreciate it if they could get in contact with Charlie Payne at the Summer RI office 803.345.5683

CC: Hannon, John; Klein, Alex; Koltay, Peter; Qualls, Phil

Mail Envelope Properties (40D8A4FC.AEB: 18:17248)

Subject:

Re: HELP ON SUMMER INSPECTION

Creation Date:

6/22/04 5:30PM

From:

Sunil Weerakkody

Created By:

SDW1@nrc.gov

Recipients

nrc.gov

ATL PO.ATL DO

CRO (Charles R. Ogle)

nrc.gov

owf2_po.OWFN_DO

ARK1 CC (Alex Klein)

PMQ CC (Phil Qualls)

nrc.gov

owf4_po.OWFN_DO

JNH CC (John Hannon)

PSK CC (Peter Koltay)

Post Office

ATL_PO.ATL_DO

owf2_po.OWFN_DO

owf4_po.OWFN_DO

Files

MESSAGE

Size

3300

Date & Time

Route

nrc.gov

nrc.gov

nrc.gov

06/22/04 05:30PM

Options

Expiration Date:

Priority:

None

Standard

Reply Requested:

No

Return Notification:

None

Concealed Subject:

No

Security:

Standard



Mail Envelope Properties (40DABD36.606:20:51263)

Subject:

Fwd: Re: HELP ON SUMMER INSPECTION

Creation Date:

6/24/04 7:38AM

From:

Charles R. Ogle

Created By:

CRO@nrc.gov

Recipients

nrc.gov

ATL_PO.ATL_DO DCP (Charlie Payne)

Post Office

MESSAGE

ATL_PO.ATL_DO

Route

nrc.gov

Files

Size

521

Date & Time 06/24/04 07:38AM

Mail

Options

Expiration Date:

Priority:

None Standard

Reply Requested:

No

Return Notification:

None

Concealed Subject:

No

Security:

Standard