

(10-2003)

10 CFR 2.201

## SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

## 1. LICENSEE/LOCATION INSPECTED:

Sharon L. Long Consulting  
1296 Russell Drive  
Bolivar, OH 44612

## 2. NRC/REGIONAL OFFICE

US NRC Reg III  
2443 Warrnville Rd  
Lisle, IL 60532

REPORT 2005001

## 3. DOCKET NUMBER(S)

03035067

## 4. LICENSEE NUMBER(S)

34-26655-02

## 5. DATE(S) OF INSPECTION

January 26, 2005

## LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

\_\_\_\_\_ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

## Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title

Printed Name

Signature

Date

LICENSEE'S  
REPRESENTATIVE

NRC INSPECTOR

G. Parker

George Parker

1/26/05

**Docket File Information****SAFETY INSPECTION REPORT  
AND COMPLIANCE INSPECTION**

1. LICENSEE <b>Sharon Long Consulting</b>		2. NRC/REGIONAL OFFICE <b>Region III</b> <b>2443 Warrenville Road</b> <b>Lisle, IL 60532</b>	
REPORT NUMBER(S) <b>2005-001</b>			
3. DOCKET NUMBER(S) <b>030-35067</b>	4. LICENSE NUMBER(S) <b>34-26655-02</b>	5. DATE(S) OF INSPECTION <b>1/26/05</b>	
6. INSPECTION PROCEDURES USED <b>87125</b>	7. INSPECTION FOCUS AREAS <b>03.01-03.07</b>		
<b>SUPPLEMENTAL INSPECTION INFORMATION</b>			
1. PROGRAM CODE(S) <b>3222</b>	2. PRIORITY <b>5</b>	3. LICENSEE CONTACT <b>Sharon Long</b>	4. TELEPHONE NUMBER <b>330/878-8057</b>
<input checked="" type="checkbox"/> Main Office Inspection		Next Inspection Date: <b>1/2010</b>	
<input type="checkbox"/> Field Office			
<input type="checkbox"/> Temporary Job Site			

**PROGRAM SCOPE**

Licensee is a small consulting firm located in Bolivar, Ohio with a client base through out Ohio and Michigan. The licensee takes wipe surveys of client facilities and performs analysis of the samples to ensure compliance with regulations. The operations consist of one person who is also the RSO. Licensee performs operations at client facilities primarily. One room in the RSO's home is devoted to the business.

**Performance Observations**

The inspector toured the facility and interviewed the RSO. Licensee appeared knowledgeable in radiation safety and isotope handling techniques. Package receipt procedures were demonstrated for the inspector as well as rad waste handling practices. Independent surveys by the inspector did not detect any abnormal reading and were within the expected range.

