

<b>TELEPHONE CONVERSATION RECORD</b>	<b>Date:</b> December 15, 2004	<b>Time:</b> 14:00
<b>Mail Control No.:</b> N/A Inspection No.: N/A	<b>License No.:</b> 06-28419-01	<b>Docket No.:</b> 030-31265
<b>Person Called:</b> Bernice Buck, Nuclear Medicine Technologist	<b>Licensee:</b> Cardiothoracic and Vascular Group	<b>Telephone No.:</b> 203-562-5115
<b>Person Calling:</b> Steven Courtemanche/(610) 337-5075		
<b>Subject:</b> Non-receipt of renewal application.		
<p><u>Summary:</u> I spoke with the receptionist and determined that Robert J. Ardesia, M.D., RSO could be reached at 203-248-9600.</p> <p>The receptionist at this office indicated that Dr. Ardesia was seeing a patient and referred me to the Nuclear Medicine Technologist. I informed Ms. Buck that , as of this date, a renewal application had not been received by the Commission. Ms. Buck told me that she had been told by her consulting medical physicist to wait for a notification from the NRC before submitting an application. I informed her that all licensees do not receive notifications and that a request to renew the license should be submitted to the Region I office as soon as possible since the license expires on December 31. I also informed her that the information necessary for a renewal application could be found in NUREG-1556, Volume 9. Ms. Buck stated that she would send in an application as soon as possible and if she had any questions she would call me.</p>		
<b>Action Required/Taken:</b> Place into ADAMS.		
<b>Prepared by</b> Steven Courtemanche	<b>Date:</b> December 15, 2004	