

Mark B. Bezilla
Vice President - Nuclear

419-321-7676
Fax: 419-321-7582

Docket Number 50-346

License Number NPF-3

Serial Number 3125

February 17, 2005

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555-0001

Subject: Technical Specification 4.4.5.5a Report of Steam Generator Tube Plugging


Ladies and Gentlemen:

This letter is submitted in accordance with the requirements of the Davis-Besse Nuclear Power Station (DBNPS) Unit Number 1, Operating License, Appendix A, Technical Specifications. Technical Specification 4.4.5.5a requires FirstEnergy Nuclear Operating Company (FENOC) to report to the Nuclear Regulatory Commission (NRC) the number of tubes plugged in each steam generator (SG) following each inservice inspection of steam generator tubes.

As a result of the Cycle 14 Mid-Cycle Outage SG tube inservice inspection findings and outage activities, 76 tubes were newly plugged in SG 1-B and 7 tubes were newly plugged in SG 2-A.

No regulatory commitments are made in this letter. Should you have any questions or require additional information, please contact Mr. Henry L. Hegrat, Supervisor - Licensing, at (330) 315-6944.

Very truly yours,



MAR

A001

Docket Number 50-346

License Number NPF-3

Serial Number 3125

Page 2

cc: J. L. Caldwell, Regional Administrator, NRC Region III
J. B. Hopkins, DB-1 NRC/NRR Senior Project Manager
C. S. Thomas, DB-1 NRC Senior Resident Inspector
Utility Radiological Safety Board