

NRC FORM 591M PART 1
(10-2003)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Siemens Building Technologies, Inc. 8 Fernwood Road Florham Park, New Jersey 07932	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415
--	---

REPORT 2005-001

3. DOCKET NUMBER(S) 030-05354/ 030-05355	4. LICENSEE NUMBER(S) 29-08864-03/ 29-08864-04E	5. DATE(S) OF INSPECTION 01/31/ 2005 through 02/22/2005
--	---	---

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

10 CFR 71.5 and 49 CFR 173.422(a)(2) indicate that the UN number for radioactive material excepted package instrument or articles is UN 2911, contrary to this the licensee's product/package labels state UN 2910. The correct UN number must be on the label for shipment. The licensee will correct the label and ensure packages are properly labeled. The licensee will change the procedures regarding product and package labeling to reflect the requirements and will train the appropriate personnel on the revised procedures.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Harry Lee	<i>Harry Lee</i>	2/28/05
NRC INSPECTOR	John Nicholson	<i>John Nicholson</i>	02/22/2005

NRC FORM 591M PART 1 (10-2003)

G:\Docs\Current\Insp Record\28-08864-03.05-001.591P1.wpd

NRC-002