From:Kathy ModesTo:spratt@htandt.comDate:Fri, Apr 8, 2005 9:07 AMSubject:4 questions

Licensee Name: Huntington Testing & Technology, Inc. License No.: 47-23076-01 Docket No.: 03020243 Control No.: 136270

Dear Steve,

Thank you for taking the time to making these corrections.

First, the error you caught: Answer to question #9 on the test should be 993.

Second, please change answer to question 3 about acceptance criteria for leaking testing to be 0.005 microcuries (see 10 CFR 34.27)

Third, please add the words "and TLD" to answer #4 on the test and to the Internal/ALARA Inspection Checklist to allow for flexibility (you can use either a film badge or a TLD). This is consistent with your Procedure No. 2 "Personnel Monitoring."

Fourth, please add: "Did the radiographer properly supervise the radiographer assistant?" to your Internal/ALARA Inspection Checklist.

Thank you very much.

Kathy Modes

Mail Envelope Properties (425681FF.5F3 : 18 : 35232)

Subject:	4 questions	
Creation Date:	Fri, Apr 8, 2005	9:07 AM
From:	Kathy Modes	

Created By: KAD@nrc.gov

Recipients htandt.com spratt (spratt@htandt.com)

Post Office

Route htandt.com

Files	Size	Date & Time	9:07 AM
MESSAGE	1773	Friday, April 8, 2005	
Options Expiration Date: Priority: Reply Requested: Return Notification:	Fri, Apr 15, 2005 Standard No None		

Concealed Subject: Security:

No Standard