

April 7, 2005

Cathy Modes
US Nuclear Regulatory Commission
Region I, Division of Nuclear Materials Safety
475 Allendale Road
King of Prussia, PA 19406-1415

Subject: Request for Additional Information

License No.: 47-23076-01 Docket No.: 030-20243 Control No:. 136270

Dear Ms. Modes,

This letter is in response to request for additional information, dated March 30, 2005. The additional information you requested pertains to errors or deficiencies in Huntington Testing & Technology's Operating & Emergency Procedures. Enclosed are the O&E Procedures dated April 7, 2005. Revisions, corrections or additions are highlighted yellow except section 3, procedures 2, 3 &4, which are new. Twelve items were listed in your letter and below are the section or paragraph where corrections can be found:

- 1. Section 3
- 2. Attached "Test"
- 3. Section 3
- 4. Section 3 (Additional information in Section 1 Procedure 9)
- 5. Section 3
- 6. Section 3
- 7. Section 2, Procedure 5, Paragraph 4.6 (Also DWG 3 Attached) Huntington Testing & Technology would like to continue performing Radiography at our shop location as a temporary job site status. DWG 1 and 2 (Attached) show shop location and surrounding area.
- 8. Section 2, Procedure 9
- 9. Section 1, Paragraph 6.4.5
- 10. Section 2, Procedure 7, Paragraph 7.3 Section 2 Procedure 17, Paragraph 3.1.4
- 11. Section 2, Procedure 17, Paragraph 3.0(a)
- 12. Section 2, Procedure 26, Paragraph 1.1 Also Section 2 Procedure 7, Paragraph 8.1

Thank you for your time and consideration of these matters and should you have questions or comments please phone or email.

Sincerely,

David McCallister

Operations Manager/RSO

David McCallity