NRC FORM 591M PAI	RT 1		Į	J.S. NUCLEAR REGULATO	RY COMMISSION
(10-2003) 10 CFR 2.201	SAFETY INSPE	CTION REPORT	AND COMPLIANC	F INSPECTION	
		OTION RELOCT		E INOI EOTION	
LICENSEE/LOCATION INSPECTED: Marias Medical Center			2. NRC/REGIONAL OFFICE		
P.O. Box 915 Shelby, Montana 59474			USNRC Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005		
Location: 640 Park Drive, Shelby, Montana			Arlington, Texas 76011-4005		
REPORT NUMBER(S)	2005-001				
3. DOCKET NUMBER(S)		4. LICENSEE NUMBER(S)		5. DATE(S) OF INSPECTION	
030-35221 LICENSEE:		25-27641-01		March 29, 2005	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
corrective actions is mad	n 30 days, the actions desc le in accordance with the r le will be achieved). I unde Prin	cribed by me to the inspecto equirements of 10 CFR 2.2 rstand that no further writtented Name		olations identified. This stater ken, corrective steps which wi uired, unless specifically requ gnature	ill be taken, ested. Date
NRC INSPECTOR	Richard A. Leon	ardi, Jr.	/	RA/	03/29/20