NRC FORM 591M PAR	RT 1		ı	U.S. NUCLEAR REGULATO	RY COMMISSION
(10-2003) 10 CFR 2.201	SAFETY INSPE	CTION REPORT A	AND COMPLIANC	E INSPECTION	
LICENSEE/LOCATION INSPECTED:			2. NRC/REGIONAL OFFICE		
PIKA International, Inc. 12919 Southwest Freeway, Ste.190 Stafford, Texas			USNRC Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005		
REPORT NUMBER(S)	2005-001				
3. DOCKET NUMBER(S)		4. LICENSEE NUMBER(S)		5. DATE(S) OF INSPECTION	
030-36709		42-27787-01		April 13, 2005	
LICENSEE:		•			
Nuclear Regulatory Comof procedures and representations of procedures and representations. 1. Based on the second of the second	mission (NRC) rules and sentative records, interviewe inspection findings, no volation(s) closed. n(s), specifically described and corrective action was oftion, were satisfied. Non-Cited Violation(s) was inspection certain of your actions.	regulations and the condition ws with personnel, and obser- iolations were identified. to you by the inspector as not or is being taken, and the rem as/were discussed involving th	s of your license. The inspector. The vations by the inspector. The inspector is necited violations, are not be aining criteria in the NRC Er e following requirement(s) a and/or attached, were in violations by the inspector.	olation of NRC requirements a	xaminations ollows: elf-identified, 900, to
I hereby state that, withir corrective actions is mad date when full complianc Title LICENSEE'S REPRESENTATIVE	n 30 days, the actions desc le in accordance with the r le will be achieved). I unde Prin	equirements of 10 CFR 2.201 rstand that no further written ted Name	will be taken to correct the vi (corrective steps already ta response to NRC will be req Signature	olations identified. This staten ken, corrective steps which wi uired, unless specifically reque gnature	ll be taken, ested. Date
NRC INSPECTOR	Christi Maier, F	lealth Physicist		RA/	04/13/2005