

A Waste Management Company 6 Howard Avenue Bridgeport, CT 06605 (203) 579-2607 (203) 579-1169 Fax

£

RECEIVED REGION 1

'05 MAY -9 A7:39

May 3, 2005

Licensing Assistant Team U.S. Nuclear Regulatory Commission Region One 475 Allendale Road King of Prussia, PA. 19406

030 29916

Re: License Amendment - License number 06-23678-01

Dear Licensing Assistance Team,

The Wheelabrator Bridgeport waste to energy facility has made a change concerning our Radiation Safety Officer ("RSO"). As a result, our license needs to be amended. The new RSO for our facility is Christopher Lill. Mr. Lill is the current Lead Electrical and Instrumentation ("E&I") Technician at the site with over fifteen years of experience in the E&I field. Additionally, Mr. Lill has been trained and certified as an RSO. A copy of this certification is attached for your review.

Please make the necessary amendments to our license. If you have any questions concerning this matter, please do not hesitate to call me at (203) 579-2607.

Sincerely,

Vincent P. Langone Jr. P. 2 Plant Manager





SEATE OF ACHIEVE STFICATE OF ACHIEVE STEATE This is to Certify that This is to Certify that

CHRISTOPHERJAILLE

Has Completed 40 Hours of

Radiation Safety Officer Training

November 15-19, 2004

K. Paul Steinmeyer, RRPT Radiation Safety Associates, Inc.

:	This is to acknowledge the receip	
	includes an administrative review	and to inform you that the initial processing which has been performed.
		omissions. Your application was assigned to a te that the technical review may identify additionate the technical review may identify additidentity additionate
	Please provide to this office w	ithin 30 days of your receipt of this card
1		
-	A copy of your action has been for	prwarded to our License Fee & Accounts Receiva arately if there is a fee issue involved.
1	A copy of your action has been fo Branch, who will contact you sep Your action has been assigned M	orwarded to our License Fee & Accounts Receiva arately if there is a fee issue involved. fail Control Number /37613
•	A copy of your action has been fo Branch, who will contact you sep Your action has been assigned M	orwarded to our License Fee & Accounts Receiva arately if there is a fee issue involved. fail Control Number /37613
	A copy of your action has been fo Branch, who will contact you sep Your action has been assigned M	orwarded to our License Fee & Accounts Receiva arately if there is a fee issue involved. fail Control Number <u>137613</u> s action, please refer to this control number.
	A copy of your action has been fo Branch, who will contact you sep Your action has been assigned M When calling to inquire about this	orwarded to our License Fee & Accounts Receiva arately if there is a fee issue involved. fail Control Number <u>137613</u> s action, please refer to this control number.

•

.

:

•

	: (FOR LFMS USE)
	: INFORMATION FROM LTS
BETWEEN:	:
	:
License Fee Management Branch, ARM	: Program Code: 03120
and	: Status Code: 0
Regional Licensing Sections	: Fee Category: 3P
	: Exp. Date: 20121031
	: Fee Comments:
	: Decom Fin Assur Reqd: N

LICENSE FEE TRANSMITTAL

- T A. REGION
- 1. APPLICATION ATTACHED

Applicant/Licensee:	WHEELABRATOR	BRIDGEPORT,	L.P.	
Received Date:	20050509			
Docket No:	3029916			
Control No.:	137013			
License No.:	06-23678-01			
Action Type:	Amendment			

2. FEE ATTACHED Amount: Check No.:

3. COMMENTS

Signed M. a. Perkins Date

B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered /__/)

1. Fee Category and Amount: _____

2. Correct Fee Paid. Application may be processed for: Amendment Renewal

- License
- 3. OTHER

Signed Date