

132
From: Brian Holian
To: Region 1 Incident Response Center
Date: Mon, Apr 18, 2005 5:52 PM
Subject: Re: Transmittal of Activity Code / Solicitation for Feedback from Millstone Event Response

get blast dial roster to mgmt to review.
Include OPA, SLOs in the call out.
Also...is there any way to have the RDO or HOO add the SRI and RI from the affected site. Be nice to have them on the initial call, automatically.

Work a set of standard questions....
RCS pressure and temp.
Safety equipment running
Equipment that did not respond
Heat sink available or not
Site Staffing and NRC responders
EAL determinations
Potential for Rad release
Licensee concerns and priorities.....Benchmark this list with other regions. Give it to the RDO and have them run thru these on every call

more later
BEH

>>> Region 1 Incident Response Center 04/18/05 11:16AM >>>
Thanks for supporting Millstone Alert event response. Regional personnel should charge time to Activity Code D91023 (Description: Event Response - Rx Incident Response)

In addition, please to take a few moments now while the event is still fresh in your memory to capture your comments, concerns and recommendations for improvement on the attached feedback form. Completed forms should be returned via email to IRC1 by this Friday, April 22, 2005.

If you have any questions please contact either Neil Perry (x5225) or Felicia Hinson (x5391).

A144