

Mike -

P.S. all left
at 0400
P.H.

see RIO

entry 191 for my

writerup -

Every thing went well -

2 pins missing in one of the
dome (1A" hot leg) when it
was inspected after removal -

CAP 056948 written on this.
Evolution went smooth - was like
night + day from last time.
P.H. USNRC