

U.S. NUCLEAR REGULATORY COMMISSION

Date: June 23, 2005

TELEPHONE CONVERSATION RECORD

Time: 1535

Mail Control 136357
or Report No(s).

License No(s). 52-21175-01

Docket No(s). 03019882

Name of Licensee: Baxter Healthcare Corporation

Name of Participant(s): Angel Alicea (RSO) and Evet Vera

Telephone No. 787-735-8021

Subject: Followup to Baxter Response Received June 20, 2005

(NOTE: This will be used as the
Documents Title in ADAMS)Summary: Two items were discussed with Baxter personnel regarding the Baxter
response provided to NRC letter dated May 17, 2005.

1) It was confirmed that the RSO will be a qualified, trained operator.

2) A typographical errors exist in the Deionizer Monitor Alarm Procedure,
Procedure GAMMA-1. This procedure erroneously refers to the
"Deionizer Monitor" as the "Outlet Monitor". The RSO stated that the
procedure error will be corrected. Since this type procedure change is
allowed without NRC concurrence (10 CFR 36.53(c)), no additional
information is needed by the NRC at this time to support completion of
the license renewal.

Action Required:

Prepared By: James Schmidt

Date: June 27, 2005