

**U.S. NUCLEAR REGULATORY COMMISSION**

Date: 6/24/2005

**TELEPHONE CONVERSATION RECORD**

Time: 3:20 p.m.

Mail Control 136827  
or Report No(s).

License No(s). 01-30362-01

Docket No(s). 03036499

Name of Licensee: Eastern Technologies, Inc.

Name of Participant(s): Mark Fellows, RSO

Telephone No. 334-899-4351

Subject: Question regarding dry type lint collector

(NOTE: This will be used as the  
Documents Title in ADAMS)

Summary: I spoke with Mr. Fellows regarding his letter dated May 26, 2005, which describes the possible use of a dry type lint collector to collect accumulated lint and debris exiting the dryers prior to reaching the pre-filtration section of the Dryer Exhaust HEPA Filtration System. I asked Mr. Fellows how ETI planned to dispose of this accumulated lint and debris. Mr. Fellows stated that it would be considered secondary waste and handled in accordance with current practices. Any material with radioactive contamination would either be returned to the client or disposed of as radioactive waste at a licensed facility. Mr. Fellows will send a letter by fax which describes handling of the lint and/or debris.

Action Required:

Prepared By:

DMJ

Date: 6/28/2005