| NRC FORM 591M PAR (10-2003) 10 CFR 2.201 | | | U.S. NUCLEAR REGULATORY COMMISSION | | |
|--|---|---|---|---|----------------------------------|
| | SAFETY INS | PECTION REPORT | AND COMPLIANCE IN | SPECTION | |
| LICENSEE/LOCATION INSPECTED: Prince William Nuclear Cardiology 8567-B Sudley Road Manassas, VA 20110 | | | 2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road | | |
| DEPORT N | | | King of Prussia, Pennsylvania 19406-1415 | | |
| REPORT Nos 2005 | | | ~ | | |
| 3. DOCKET NUMBER(S) | | 4. LICENSE NUMBER(| S) | 5. DATE(S) OF INSPECT | ON |
| 030-36615 LICENSEE: | | 45-30929-01 | | June 14, 2005 | |
| Nuclear Regulatory Con of procedures and repre 1. Based on the second s | nmission (NRC) rules and sentative records, intervious inspection findings, no plation(s) closed. | d regulations and the con- ews with personnel, and on p violations were identified and to you by the inspector | as non-cited violations, are n | spection consisted of selection findings at the inspection findings at the | tive examinations re as follows: |
| NUREG-1600, | to exercise discretion, w | ere satisfied. | ken, and the remaining criterion of the control of | | Policy, |
| | is form is a NOTICE OF | VIOLATION, which may | pelow and/or attached, were in the subject to posting in according | dance with 10 CFR 19.11. | ents and are |
| corrective actions is mad | n 30 days, the actions de de in accordance with the ce will be achieved). I un | escribed by me to the inspection of 10 CFR | ector will be taken to correct 2.201 (corrective steps alrea ritten response to NRC will be | the violations identified. The dy taken, corrective steps were | which will be taken, |
| LICENSEE'S REPRESENTATIVE | | | A 10 A | 100 | |
| NRC INSPECTOR | Joseph Nick | | | X / V > | 6/14/05 |