

James A. FitzPatrick Nuclear Power Plant

OPERATIONS TRAINING PROGRAMS JOB PERFORMANCE MEASURE

S/RO/NPO	20101012	TASK TITLE: <u>ISOLATE AND ELECTRICALLY DISARM A</u> HYDRAULIC CONTROL UNIT (HCU)
APPL. TO	JPM NUMBER	TITOTACLIC CONTINCE ONLY (FICO)
REV: <u>8</u>	DATE: <u>3/7/05</u>	NRC K/A SYSTEM NUMBER: 201003 K1.01 3.2/3.3
JAF TASK NUMBEF	R: JAF	QUAL STANDARD NUMBER:
ESTIMATED COMPI	LETION TIME: 2	0 Minutes
SUBMITTED:		OPERATION REVIEW:
APPROVED:		
CANDIDATE NAME	:	S.S. NUMBER:
JPM Completion:	(X) Simulated	() Performed
Location:	(X) Plant	() Simulator
DATE PERFORMED:		TIME TO COMPLETE: Minutes
PERFORMANCE EV	ALUATION: ()	Satisfactory () Unsatisfactory
		SATISFACTORY PERFORMANCE)
EVALUATOR:	SIGNATUF	RE/PRINTED

JOB PERFORMANCE MEASURE RECORD AND CHECKLIST

Comments:

S/RO/NPO	20101012	TASK TITLE:	ISOLATI	E AND ELECTRICALLY DISARM A
APPL. TO	JPM NUMBER		HYDRAU	ULIC CONTROL UNIT (HCU)
Current Update:	3/7/05 Date		By: <u>R\</u> Int.	<u>WD</u>
Outstanding Items:				
Tech	nnical Review			Additional Information
Que:	stions and Answers			Validation
Proc	edural Change Require	ed	X	None

JOB PERFORMANCE MEASURE REQUIRED TASK INFORMATION

S/RO/NPO

20101012

TASK TITLE: ISOLATE AND ELECTRICALLY DISARM A

HYDRAULIC CONTROL UNIT (HCU)

APPL. TO

JPM NUMBER

I. SAFETY CONSIDERATIONS

A. Proper safety attire (hardhat, safety shoes, safety glasses, ear protection, etc.) is to be worn while out in the plant.

II. REFERENCES

- A. OP-25, Control Rod Drive Hydraulic System, Rev. 75
- B. N-1 Key

III. TOOLS AND EQUIPMENT

A. Fuse Pullers

IV. SET UP REQUIREMENTS

- A. Obtain Shift Manager's permission prior to perform this task.
- B. Contact Radiation Protection prior to performance of this task to discuss radiological conditions in the area of the HCU.

V. EVALUATOR NOTES

- A. If performing JPM in the plant, inform the candidate that the conditions of each step need only be properly identified and <u>not</u> actually performed.
- B. The candidate should, at a minimum, identify the change in equipment status light indication when equipment operation is simulated.

VI. TASK CONDITIONS

- A. The Plant is Mode 1 at 100% Reactor Power.
- B. Control Rod 22-19 has been fully inserted and declared inoperable to support maintenance on 03SOV-117 and 03SOV-118.
- C. HCU-22-19 must now be isolated.

EVALUATOR: The HCU chosen for this task may be changed as necessary to accommodate plant conditions.

* - CRITICAL STEP

TASK TITLE: ISOLATE AND ELECTRICALLY DISARM A HYDRAULIC CONTROL UNIT (HCU)

VII.INITIATING CUE

The Plant is Mode 1 at 100% Reactor Power. Control Rod 22-19 has been fully inserted and declared inoperable to support maintenance on the associated Scram Pilot Air Solenoid Valves (03SOV-117 and 03SOV-118). Isolate HCU-22-19 per OP-25, Section G.1. OP-25 actions G.1.1 through G.1.6 are complete. Nitrogen depressurization of HCU-22-19 will not be required.

VIII. TASK STANDARD

The candidate will isolate and electrically disarm HCU 22-19 (or alternate HCU chosen to support plant conditions).

	STEP	STANDARD	EVALUATION / COMMENT
1.	Obtain and review procedure	Candidate obtains and reviews OP-25. Candidate determines that the start point is step G.1.7.	SAT / UNSAT
		EVALUATOR:	
		If candidate requests information to support requirement for Control Rod operability, inform candidate that Control Rods are required to be operable.	
2.	(G.1.7) IF Control Rods are required to be operable, THEN electrically disarm CRD-(*) per subsection G.24 of OP-25.	Candidate obtains and reviews OP-25, section G.24. Candidate determines that the start point is step G.24.1.	SAT / UNSAT
3.	(G.24.1) Notify Control Room that CRD-(*) will be electrically disarmed.	EVALUATOR: When the candidate states that he/she would contact the Control Room to notify them that CRD 22-19 will be electrically disarmed, inform the candidate that "CRD 22-19 will be electrically disarmed."	SAT / UNSAT

	STEP	STANDARD	EVALUATION / COMMENT
4.	(G.24.2) Unplug amphenol connector from each of the following solenoid operated valves at HCU-() and control per AP-12.06. • 03SOV-120(*) (WITHDRAW SETTLE SOV) • 03SOV-121(*) (INSERT EXHAUST WATER SOV) • 03SOV-122(*) (WITHDRAW DRIVE WATER SOV) • 03SOV-123(*) (INSERT DRIVE WATER SOV)	Candidate correctly locates amphenols associated with CRD/HCU 22-19 and indicates that he/she would unplug / control them. Candidate should indicate the amphenol control per the tagging process or the equipment status log. EVALUATOR: When the candidate states that he/she would unplug the respective amphenols, inform the candidate that "The four respective amphenols are unplugged and the PTR is hung." EVALUATOR NOTE: HCU-22-19 is isolated RB 272' East.	SAT / UNSAT *CRITICAL STEP*
5.	(G.24.3) Notify Control Room that CRD-(*) has been electrically disarmed.	EVALUATOR: When the candidate states that he/she would contact the Control Room to notify them that CRD 22-19 has been electrically disarmed, inform the candidate that "CRD 22-19 has been electrically disarmed."	SAT / UNSAT
6.	(G.1.8) Close 03HCU-101() (CRD INSERT LINE ISOL VALVE).	Candidate correctly locates 03HCU-101 associated with CRD/HCU 22-19 and indicates that he/she would close it. EVALUATOR: When the candidate goes to the Reactor Building 272' East side HCU area, locates and identifies HCU 22-19 and 03HCU-101; states that he/she would close 03HCU-101, then inform the candidate "03HCU-101 (22-19) is CLOSED."	SAT / UNSAT *CRITICAL STEP*

	STEP	STANDARD	EVALUATION / COMMENT
7.	(G.1.9) Close 03HCU-102() (CRD WITHDRAW LINE ISOL VALVE).	Candidate correctly locates 03HCU-102 associated with CRD/HCU 22-19 and indicates that he/she would close it.	SAT / UNSAT *CRITICAL STEP*
		EVALUATOR: When the candidate locates and identifies 03HCU- 102 and states that he/she would close 03HCU-102, then inform the candidate "03HCU-102 (22-19) is CLOSED."	
8.	(G.1.10) Close 03HCU-113() (CHARGING WATER HEADER ISOL VALVE).	Candidate correctly locates 03HCU-113 associated with CRD/HCU 22-19 and indicates that he/she would close it. EVALUATOR:	SAT / UNSAT *CRITICAL STEP*
		When the candidate locates and identifies 03HCU-113 and states that he/she would close 03HCU-113, then inform the candidate "03HCU-113 (22-19) is CLOSED."	

	STEP	STANDARD	EVALUATION / COMMENT
9.	(G.1.11) Close 03HCU-104() (COOLING WATER SUPPLY ISOL VALVE).	Candidate correctly locates 03HCU-104 associated with CRD/HCU 22-19 and indicates that he/she would close it.	SAT / UNSAT *CRITICAL STEP*
		EVALUATOR: When the candidate locates and identifies 03HCU- 104 and states that he/she would close 03HCU-104, then inform the candidate "03HCU-104 (22-19) is CLOSED."	
10.	(G.1.12) Close 03HCU-103() (CRD DRIVE WATER SUPPLY ISOL VALVE).	Candidate correctly locates 03HCU-103 associated with CRD/HCU 22-19 and indicates that he/she would close it.	SAT / UNSAT *CRITICAL STEP*
		EVALUATOR: When the candidate locates and identifies 03HCU- 103 and states that he/she would close 03HCU-103, then inform the candidate "03HCU-103 (22-19) is CLOSED."	

	STEP	STANDARD	EVALUATION / COMMENT
11.	(G.1.13) Close 03HCU-105() (EXHAUST WATER ISOL VALVE).	Candidate correctly locates 03HCU-105 associated with CRD/HCU 22-19 and indicates that he/she would close it.	SAT / UNSAT *CRITICAL STEP*
		EVALUATOR: When the candidate locates and identifies 03HCU- 105 and states that he/she would close 03HCU-105, then inform the candidate "03HCU-105 (22-19) is CLOSED."	
12.	(G.1.14) Close 03HCU-112() (SCRAM DISCHARGE HEADER ISOL VALVE).	Candidate correctly locates 03HCU-112 associated with CRD/HCU 22-19 and indicates that he/she would close it. EVALUATOR:	SAT / UNSAT *CRITICAL STEP*
		When the candidate locates and identifies 03HCU-112 and states that he/she would close 03HCU-112, then inform the candidate "03HCU-112 (22-19) is CLOSED."	

	STEP	STANDARD	EVALUATION / COMMENT
13.	(G.1.15) Remove the following fuses to deenergized Scram Pilot Solenoid Operated Valves 03SOV-117()and 09SOV-118(*):	Candidate correctly locates Scram Pilot Solenoid Fuses associated with CRD/HCU 22-19 SOVs 117/118; and indicates that he/she would pull them with the fuse puller.	SAT / UNSAT *CRITICAL STEP*
	5A-F19A(*)5A-F19B(*)	EVALUATOR: When the candidate goes to the Scram Solenoid Fuse Panel and states that he/she would open the panel and remove fuses 5A-F19A(22-19) and 5A-F19B(22-19), then inform the candidate "Fuses 5A-F19A(22-19) and 5A-F19B(22-19) are removed."	
14.	(G.1.16) Verify open the following valves by observing valve position indicators at HCU-(*): • 03AOV-126(*) (HCU INLET	Candidate correctly locates 03AOV-126/127 associated with CRD/HCU 22-19 and indicates that he/she would observe mechanical position indication to verify current valve position.	SAT / UNSAT
	SCRAM AIR OPER VALVE) • 03AOV-127(*) (HCU OUTLET SCRAM AIR OPER VALVE)	EVALUATOR: When the candidate locates and identifies 03AOV- 126 and 03AOV-127 and states that he/she would use the mechanical position indicators on 03AOV-126 and 03AOV-127 to observe that the valves are open, then inform the candidate "03AOV-126 and 03AOV- 127 indicate OPEN."	

	STEP	STANDARD	EVALUATION / COMMENT
15.	(G.1.17) Verify HCU-(*) blue SCRAM light is on at FULL CLOSE DISPLAY.	Candidate recognizes need to obtain information from 09-5 Panel in the Control Room.	SAT / UNSAT
		EVALUATOR:	
		When the candidate states that he/she would contact the Control Room and request the status of the blue scram light for control rod 22-19, then inform the candidate "Blue Scram light for Control Rod 22-19 is ON".	
16.	(G.1.18) Loosen threaded cap on 03HCU- 107() (ACCUMULATOR DRAIN VALVE) to thoroughly vent pressure before proceeding to the next step.	Candidate correctly locates 03HCU-107 associated with CRD/HCU 22-19 and recognizes WARNING through indicating that he/she would loosen the cap "slowly", "carefully", or "in a controlled manner" (or similar wording).	SAT / UNSAT *CRITICAL STEP*
		EVALUATOR:	
		When the candidate states that he/she would loosen threaded cap on 03HCU-107-22-19, then inform the candidate "Threaded cap on 03HCU-107(22-19) is LOOSE and DEPRESSURIZED".	

	STEP	STANDARD	EVALUATION / COMMENT
17.	(G.1.19) Remove threaded cap from 03HCU- 107() (ACCUMULATOR DRAIN VALVE).	Candidate correctly identifies 03HCU-107 associated with CRD/HCU 22-19 and indicates that he/she would remove it (may add "by turning counterclockwise")	SAT / UNSAT *CRITICAL STEP*
		EVALUATOR: When the candidate states that he/she would remove threaded cap on 03HCU-107-22-19, then inform the candidate "Threaded cap on 03HCU-107(22-19) is REMOVED."	
18.	(G.1.20) Connect hose to 03HCU-107(*) (ACCUMULATOR DRAIN VALVE) and route other end of hose to a floor drain or suitable container.	Candidate correctly identifies 03HCU-107 associated with CRD/HCU 22-19 and identifies hose routing location (floor drain / poly bottle in vicinity) EVALUATOR:	SAT / UNSAT
		When the candidate locates, identifies and states that he/she would connect a hose to 03HCU-107(22-19) and properly route the other end, then inform the candidate "Hose is INSTALLED".	

	STEP	STANDARD	EVALUATION / COMMENT
19.	(G.1.21) Crack open 03HCU-107(*) (ACCUMULATOR DRAIN VALVE).	Candidate correctly identifies 03HCU-107 associated with CRD/HCU 22-19 and indicates that he/she would crack it open.	SAT / UNSAT
1		EVALUATOR:	
		When the candidate locates and identifies 03HCU- 107 and states that he/she would crack open 03HCU- 107, then inform the candidate "03HCU-107 (22-19) is CRACKED OPEN."	
20.	(G.1.22) WHEN HCU 22-19 water accumulator is thoroughly vented, open 03HCU-107() (ACCUMULATOR DRAIN VALVE).	Candidate correctly identifies 03HCU-107 associated with CRD/HCU 22-19 and indicates that he/she would fully open it upon indications that it was depressurized.	SAT / UNSAT *CRITICAL STEP*
		EVALUATOR:	
		When the candidate locates and identifies 03HCU- 107 and states that he/she would fully open 03HCU- 107, then inform the candidate "03HCU-107 (22-19) is FULL OPEN."	

	STEP	STANDARD	EVALUATION / COMMENT
21.	(G.1.23) IF maintenance is to be performed on any of the following: O3AOV-126 () (HCU INLET SCRAM AIR OPER VALVE) O3AOV-127 (*) (HCU OUTLET SCRAM AIR OPER VALVE) O3SOV-117/118 (*) (SCRAM PILOT AIR SOLENOID OPER VALVE) Instrument air piping downstream of O3HCU-116 (*) (SCRAM PILOT AIR ISOL VALVE) THEN close O3HCU-116 (*)(SCRAM PILOT AIR ISOL VALVE)	Candidate recognizes need to perform step based on planned maintenance on 03SOV-117/118; and correctly locates 03HCU-116 associated with CRD/HCU 22-19 and indicates that he/she would close it. EVALUATOR: When the candidate locates and identifies 03HCU-116 and states that he/she would close 03HCU-116, then inform the candidate "03HCU-116 (22-19) is CLOSED."	SAT / UNSAT *CRITICAL STEP*
22.	(G.1.24) IF maintenance is to be performed that requires depressurizing the HCU nitrogen accumulator, THEN perform the following: (N/A) LIST NOT REQUIRED	EVALUATOR: If requested, inform candidate that no maintenance is planned that required depressurizing the accumulator.	SAT / UNSAT

	STEP	STANDARD	EVALUATION / COMMENT
23.	(G.1.25) Verify red light is on at CRD ACCUMULATOR MONITOR & SCRAM VALVE POSITION SELECTOR panel 25-04 (east side) or 25-22 (west side) Reactor Building 272'.	Candidate goes to the CRD ACCUMULATOR MONITOR & SCRAM VALVE POSITION SELECTOR Panel 25-04 (east side) and verifies red light is on for HCU-22-19. EVALUATOR: As candidate approaches panel and indicates that he/she would be looking for a red light on Panel 25- 04 that corresponds to HCU 22-19, inform candidate that "Red light is on for HCU 22-19 at Panel 25-04."	SAT / UNSAT
24.	(G.1.26) Notify Control Room that HCU-(*) has been removed from service.	EVALUATOR: When the candidate states that he/she would contact the Control Room and inform them that HCU 22-19 has been removed from service, then inform the candidate, "HCU 22-19 has been removed from service".	SAT / UNSAT
25.	(G.1.27) Verify HCU-(*) yellow ACCUM light is on at FULL CORE DISPLAY.	Candidate recognizes need to obtain information from 09-5 Panel in the Control Room. EVALUATOR: When the candidate states that he/she would contact the Control Room and request the status of the yellow ACCUM light for control rod 22-19, then inform the candidate "Yellow ACCUM light for Control Rod 22-19 is ON".	SAT / UNSAT
	EVA	LUATOR: Terminate the task at this point.	

INITIATING CUE

The Plant is Mode 1 at 100% Reactor Power. Control Rod 22-19 has been fully inserted and declared inoperable to support maintenance on the associated Scram Pilot Air Solenoid Valves (03SOV-117 and 03SOV-118). Isolate HCU-22-19 per OP-25, Section G.1. OP-25 actions G.1.1 through G.1.6 are complete. Nitrogen depressurization of HCU-22-19 will not be required.



James A. FitzPatrick Nuclear Power Plant

OPERATIONS TRAINING PROGRAMS JOB PERFORMANCE MEASURE

S/RO/NPO	20505005	IASK IIILE	:: CROSS-TIE FIRE PROT INJECT TO RHR SERV	
APPL. TO	JPM NUMBER		INSECT TO MIN SERV	ICE WATER
REV:7	DATE: <u>3/7/05</u>	NRC	K/A SYSTEM NUMBER:	295031 EA1.08 3.8/3.9
JAF TASK NUMBEF	R:	JAF	QUAL STANDARD NUM	BER:
ESTIMATED COMPI	LETION TIME:1	5 Minutes		
SUBMITTED:		OPE	RATION REVIEW:	
APPROVED:				
~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~		~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	
CANDIDATE NAME	:		S.S. NUMBER:	
JPM Completion:	(X) Simulated	() Perform	ned	
Location:	(X) Plant	() Simulat	or	
DATE PERFORMED:			TIME TO COMPLETE:	Minutes
PERFORMANCE EVA	ALUATION: ()	Satisfactory	() Unsatisfactory	
COMMENTS: (MAN				
EVALUATOR:	SIGNATUR	RE/PRINTED		
		. ——		

JOB PERFORMANCE MEASURE

Comments:

RECORD AND CHECKLIST

S/RO/NPO	20505005	TASK TITLE:	CROSS-TIE FIRE PROTECTION SYSTEM 1 INJECT TO RHR SERVICE WATER	<u>TO</u>
APPL. TO	JPM NUMBER		INDECT TO NEW SERVICE WATER	
Current Update:	3/7/05 Date		By: <u>RWD</u> Int.	
Outstanding Items:				
Tech	nnical Review		Additional Information	
Que:	stions and Answers		Validation	
Proc	edural Change Requ	iired	X None	

JOB PERFORMANCE MEASURE REQUIRED TASK INFORMATION

S/RO/NPO 20505005 TASK TITLE: CROSS-TIE FIRE PROTECTION SYSTEM TO

APPL. TO JPM NUMBER

I. SAFETY CONSIDERATIONS

A. None

II. REFERENCES

A. EP-8, Alternate Injection Systems, Rev. 2

III. TOOLS AND EQUIPMENT

- A. Emergency cross connect hose located in the North Safety Pump Room.
- B. N1 Key

IV. SET UP REQUIREMENTS

A. None

V. EVALUATOR NOTES

- A. If performing JPM in the plant, inform the candidate that the conditions of each step need only be properly identified and <u>not</u> actually performed.
- B. The candidate should, at a minimum, identify the change in equipment status light indication when equipment operation is simulated.

VI. TASK CONDITIONS

- A. To maintain RPV water level >0" (TAF), water level control must be augmented by using the lake as a source.
- B. The RHRSW pumps are unavailable.
- C. The Shift Manager has directed that the Fire Protection System be utilized to inject water into the RHRSW System.

* - CRITICAL STEP

TASK TITLE: CROSS-TIE FIRE PROTECTION SYSTEM TO INJECT TO RHR SERVICE WATER

VII. INITIATING CUE

A transient has occurred which has resulted in a break in the RPV causing a loss of inventory. Due to a series of failures, no high pressure and most low pressure injection systems are unavailable. The Shift Manager directs you to align the Fire Protection System header to the "Alpha" RHR Service Water header per EP-8, Section 5.3.

VIII. TASK STANDARD

The candidate will cross-tie the Fire Protection System header to supply RPV injection via RHR Service Water per EP-8.

	STEP	STANDARD	EVALUATION / COMMENT
1.	Obtain and review procedure	Candidate obtains and reviews EP-8. Candidate determines that the start point is step 5.3	SAT / UNSAT
2.	(5.3.1) Verifies the following RHR pumps are stopped: • RHR PMP 10P-3A • RHR PMP 10P-3C	Contacts the Control Room to verify RHR Pumps "A" and "C" are stopped. EVALUATOR: Inform the candidate that "RHR Pumps 3"Alpha" and 3"Charlie" are not running."	SAT / UNSAT
*3.	(5.3.2) Removes caps from the following valves: • 10RHR-432 (RHRSW TO FIRE PROTECTION CROSS-TIE ISOL VALVE) • 76FPS-720 (RHRSW / FIRE PROTECTION CROSSTIE ISOL VALVE)	EVALUATOR: When the candidate goes to the North Emergency Service Water Room and states that he/she would remove the hose connection caps at 10RHR-432 and 76FPS-720, then inform the candidate "Hose connection caps are removed."	SAT / UNSAT *CRITICAL STEP*

TASK TITLE: CROSS-TIE FIRE PROTECTION SYSTEM TO INJECT TO RHR SERVICE WATER

	STEP	STANDARD	EVALUATION / COMMENT
4.	(5.3.3)	EVALUATOR:	SAT / UNSAT
	Connect a hose (stored in cabinet 76CAB-1 on west wall of north emergency service water room) between the following valves: • 10RHR-432 (RHRSW TO FIRE	When the candidate opens 76CAB-1 with N-1 key and points out the emergency cross connect hose and tools and states he/she would connect the hose between 10RHR-432 and 76FPS-720, then inform the candidate "Hose is connected."	*CRITICAL STEP*
	PROTECTION CROSS-TIE ISOL VALVE) • 76FPS-720 (RHRSW / FIRE PROTECTION CROSSTIE ISOL VALVE)		
*5.	(5.3.4) Ensure closed 10MOV-89A RHRSW DISCH VLV FROM HX A.	Contacts Control Room to verify that 10MOV-89A is closed.	SAT / UNSAT
	Signification for A.	EVALUATOR:	
		Inform the candidate "10MOV-89A is CLOSED."	
EVALUA	ATOR: Ensure candidate observed "CAL methods of determining forebay	JTION" pertaining to Screenwell Forebay Water Level. (i. water level.)	e. have candidate point out
6.	(5.3.5) Start one or more of the following	Informs the Control Room that he/she is ready to have one or more of the Fire protection System	SAT / UNSAT
	pumps:	pumps started.	*CRITICAL STEP*
	ELEC FIRE PMP 76-P2	EVALUATOR:	
	 DIESEL FIRE PMP 76-P1 DIESEL FIRE PMP 76-P4 	Inform the candidate "Electric Fire Pump 76P-2 is operating."	
<u> </u>			

S/RO/NPO TASK TITLE: CROSS-TIE FIRE PROTECTION SYSTEM TO INJECT TO RHR SERVICE WATER

	STEP	STANDARD	EVALUATION / COMMENT		
7.	(5.3.6) Unlock and open the following valves: • 10RHR-432 (RHRSW TO FIRE PROTECTION CROSS-TIE ISOL VALVE) • 76FPS-720 (RHRSW / FIRE PROTECTION CROSSTIE ISOL VALVE)	EVALUATOR: When the candidate states that he/she would unlock and open 10RHR-432 by turning the handwheel in the counterclockwise direction until full open, then inform the candidate that "10RHR-432 is OPEN." When the candidate states that he/she would unlock and open 76FPS-720 by turning the handwheel in the counterclockwise direction until full open, the inform the candidate that "76FPS-720 is OPEN."	SAT / UNSAT *CRITICAL STEP*		
	EVALUATOR: Terminate the task at this point.				

INITIATING CUE

A transient has occurred which has resulted in a break in the RPV causing a loss of inventory. Due to a series of failures, no high pressure and most low pressure injection systems are unavailable. The Shift Manager directs you to align the Fire Protection System header to the "Alpha" RHR Service Water header per EP-8, Section 5.3.



James A. FitzPatrick Nuclear Power Plant

OPERATIONS TRAINING PROGRAMS JOB PERFORMANCE MEASURE

<u>S/RO</u> APPL. TO		REOPEN MSIV's WITH RPV PRESSURIZED
REV:1	DATE: <u>3/7/05</u> NRC	K/A SYSTEM NUMBER: 239001 A4.04 3.8/3.7
JAF TASK NUMBEF	R: JAF (QUAL STANDARD NUMBER:
ESTIMATED COMP	LETION TIME: <u>15</u> Minutes	
SUBMITTED:	OPER	ATION REVIEW:
APPROVED:		
~~~~~~~~~~~~		~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~
CANDIDATE NAME	:	S.S. NUMBER:
JPM Completion:	( ) Simulated ( X ) Perform	ed
Location:	( ) Plant ( X ) Simulat	or
DATE PERFORMED:	:	TIME TO COMPLETE: Minutes
PERFORMANCE EV	ALUATION: ( ) Satisfactory	( ) Unsatisfactory
	NDATORY FOR UNSATISFACTORY	PERFORMANCE)
EVALUATOR:	SIGNATURE/PRINTED	

# JOB PERFORMANCE MEASURE RECORD AND CHECKLIST

<u>S/RO</u> APPL. TO	FROM LOI-03-01 JPM NUMBER	TASK TITLE: Reopen	MSIV's with RPV Pressurized
Current Update	e:3/7/05 Date	By: <u>RWD</u> Int.	
Outstanding Ite	ems:		
	Technical Review		Additional Information
<del></del>	Questions and Answers		Validation
	Procedural Change Require	d <u>X</u>	None
Comments:			

Simulator Validated

## JOB PERFORMANCE MEASURE REQUIRED TASK INFORMATION

S/RO FROM LOI-03-01 TASK TITLE: Reopen MSIV's with RPV Pressurized APPL. TO JPM NUMBER

### I. SAFETY CONSIDERATIONS

A. None

### II. REFERENCES

A. EP-9; OPENING MSIV's, Rev 3

### III. TOOLS AND EQUIPMENT

A. None

### IV. SET UP REQUIREMENTS

- A. LOI-05-01 IC-139
- B. Rx Scrammed with MSIV's closed.
- C. RPV Level > 126.5 and < 222.5 controlling on HPCI.
- D. RPV Pressure Control on SRV's/HPCI/RCIC at 800-1000 psig.
- E. PCIS Group I isolation signals reset
- F. Assign to Trigger 1, ORI-TC ZAOP1MSPA and B to 800 psig on a 5 minute ramp

### V. EVALUATOR NOTES

- A. If performing JPM in the plant, inform the candidate that the conditions of each step need only be properly identified and <u>not</u> actually performed.
- B. The candidate should, at a minimum, identify the change in equipment status light indication when equipment operation is simulated.

### VI. TASK CONDITIONS

A. Plant is post scram with MSIV's closed

### * - CRITICAL STEP

### VII. INITIATING CUE:

The reactor has scrammed and the MSIV's are closed. MSIV isolation signals have been reset. Another operator has RPV pressure control on the SRV's at 800-1000 psig. The plant is being controlled as directed by the EOP's. To reestablish the main condenser as the heat sink, equalize and reopen the MSIV's per EP-9.

TASK STANDARD

The candidate will equalize to less than a 200 psid D/P and open the MSIV's per EP-9

	STEP	STANDARD	EVALUATION / COMMENT
1.	Obtain a controlled copy of procedure EP-9, OPENING MSIV's	The candidate obtains a controlled copy of EP-9.	SAT / UNSAT
2.	IF differential pressure across the MSIVs is LESS THAN OR EQUAL TO 200 psid, THEN perform the following:	Candidate uses 06PI-90A, B, and or C at panel 09-5 and MAIN STEAM PRESS A and or B at EHC section of panel 09-5 to determine that differential pressure exceeds 200 psid.	SAT / UNSAT
3.	Ensure closed the following valves:  MSIV 29AOV-80A-D  MSIV 29AOV-86A-D  MAIN STM DRN 29MOV-74, 77, 78 and 79  MAIN STM DRN VLV 29MOV-101A-D  RFPT A and B HP STOP VLV HP SVA-1 and SVB-1  TSV-1-4  TO PCV 96MOV-S1  PCV BYP 96MOV-S2  29MST-105 (SJAE MST supply 29PCV-107 outlet isol valve) (remote operated from East Electric Bay)  29MST-107 (SJAE MST supply 29PCV-107 bypass strainer outlet isol valve) (remote operated from East Electric Bay)	Candidate closes and/or observes green closed light on and red open light off at the following locations:  MSIV 29AOV-80A-D at 09-3 and 09-4  MSIV 29AOV-86A-D at 09-3 and 09-4  MAIN STM DRN 29MOV-74, 77, 78 and 79 at 09-3 and 09-4  MAIN STM DRN VLV 29MOV-101A-D at 09-7  RFPT A and B HP STOP VLV HP SVA-1 at 09-6  TSV-1-4 at 09-5  TO PCV 96MOV-S1 at 09-7  PCV BYP 96MOV-S2 at 09-7  ***29MST-105 (SJAE MST supply 29PCV-107 outlet isol valve) (remote operated from East Electric Bay) by telcon to NPO***  ***29MST-107 (SJAE MST supply 29PCV-107 bypass strainer outlet isol valve) (remote operated from East Electric Bay) by telcon to NPO.***  ****1NSTRUCTOR NOTE***  RFI-MC31 TO 0	SAT / UNSAT

	STEP	STANDARD	EVALUATION / COMMENT
*4.	Open the following valves: MAIN STM DRN 29MOV-74 MAIN STM DRN 29MOV-77	At panel 09-3 and 4 candidate opens 29 MOV-74 and 77 and observes green closed light off and red open light on.	SAT / UNSAT *CRITICAL STEP*
5.	Jog open MAIN STM DRN 29MOV-79 until full open.	At panel 09-4 candidate jogs opens 29 MOV-79 until full open and observes green closed light off and red open light on.	SAT / UNSAT
*6.	Open the following valves: MSIV 29AOV-86A MSIV 29AOV-86B MSIV 29AOV-86C MSIV 29AOV-86D	At panel 09-3 candidate opens 29AOV-86 A-D and observes green closed light off and red open light on.	SAT / UNSAT *CRITICAL STEP*
*7.	Open MAIN STM DRN 29MOV-78.	At panel 09-4 candidate opens 29 MOV-78 and observes green closed light off and red open light on.  INSTRUCTOR NOTE  TRIGGER 1	SAT / UNSAT *CRITICAL STEP*
8.	Close MAIN STM DRN 29MOV-79.	EVALUATOR Act as SM and waive step 5.9  At panel 09-4 candidate closes 29 MOV-79 and observes green closed light on and red open light off.	SAT / UNSAT
*9.	WHEN differential pressure across the MSIVs is LESS THAN OR EQUAL TO 200 psid, open the following valves: MSIV 29AOV-80A MSIV 29AOV-80B MSIV 29AOV-80C MSIV 29AOV-80D	Candidate uses 06PI-90A, B, and or C at panel 09-5 and MAIN STEAM PRESS A and or B at EHC section of panel 09-5 to determine differential pressure.  When differential pressure is < 200 psid, candidate opens 29AOV-80 A-D at panel 09-4 and observes green closed light off and red open light on.	SAT / UNSAT *CRITICAL STEP*
		INSTRUCTOR NOTE DELETE TRIGGER 1	
	EVA	ALUATOR: Terminate the task at this point.	

## **INITIATING CUE:**

The reactor has scrammed and the MSIV's are closed. MSIV isolation signals have been reset. Another operator has RPV pressure control on the SRV's at 800-1000 psig. The plant is being controlled as directed by the EOP's. To reestablish the main condenser as the heat sink, equalize and reopen the MSIV's per EP-9.



## James A. FitzPatrick Nuclear Power Plant

# OPERATIONS TRAINING PROGRAMS JOB PERFORMANCE MEASURE

S/RO	26201001A	TASK TITLE:	SWAP ELECTRICAL BUSES FROM RESERVE STATION SERVICE TO NORMAL STATION SERVICE (T-4)
APPL. TO	JPM NUMBER		DETIVIDE TO NOTIFICE OF ATTOM DETIVIDE (1 4)
REV: 0	DATE: <u>3/1</u> 0	0/05	NRC K/A SYSTEM NUMBER: <u>262001 A4.04 3.6/3.7</u>
JAF TASK N	JMBER:		JAF QUAL STANDARD NUMBER:
ESTIMATED	COMPLETION TIME:	15 Minut	tes
SUBMITTED:			OPERATION REVIEW:
APPROVED:			
		***********	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
CANDIDATE	NAME:	<del></del>	S.S. NUMBER:
JPM Complet	ion: ( ) Simulate	d (X) Pe	rformed
Location:	( ) Plant		(X) Simulator
DATE PERFO	RMED:		TIME TO COMPLETE: Minutes
PERFORMAN	CE EVALUATION:	( ) Satisfact	ory ( ) Unsatisfactory
			TORY PERFORMANCE)
COMMENTS.	(MANDATORT FOR	ONSATISFAC	TORT FERFORIVIANCE
EVALUATOR		TUDE	
	SIGNA	ATURE/PRINTE	ט

## JOB PERFORMANCE MEASURE

Comments:

## **RECORD AND CHECKLIST**

_S/RO	NEW TASK TITLE:	<b>SWAP ELECTRICAL BUSES FROM RESERVE STA</b>	<b>IOIT</b>
		SERVICE TO NORMAL STATION SERVICE (T-4)	
APPL. TO	JPM NUMBER		
O	2/10/05	D DIA/D	
Current Update:	3/10/05	By: <u>RWD</u>	
	Date	Int.	
Outstanding Item	s:		
Те	echnical Review	Additional Information	
Q	uestions and Answers	Validation	
Pr	ocedural Change Required	X None	

## JOB PERFORMANCE MEASURE REQUIRED TASK INFORMATION

S/RO NEW TASK TITLE: SWAP ELECTRICAL BUSES FROM RESERVE STATION SERVICE TO NORMAL STATION SERVICE (T-4)

APPL. TO JPM NUMBER

### I. SAFETY CONSIDERATIONS

A. None

#### II. REFERENCES

- A. OP-46A, 4160V and 600V NORMAL AC POWER DISTRIBUTION, Rev. 48
- B. OP-65, Startup and Shutdown Procedure, Rev. 102

### III. TOOLS AND EQUIPMENT

A. Synch Selector Switch Key

### IV. SET UP REQUIREMENTS

- A. LOI-05-01 IC-138
- B. Obtain current copy of OP-46A, 4160V and 600V NORMAL AC POWER DISTRIBUTION.
- C. 25-30% CTP IC during reactor startup with plant conditions stable.
- D. Main Generator is synchronized to the Grid. The 10700 Bus is de-energized. All 4160 VAC Busses on RSS.
- E. ORI Running Voltmeter downscale (ORI-ED ZA009SYNC17A) and attach a PID/Caution Tag.

#### V. EVALUATOR NOTES

- A. If performing JPM in the plant, inform the candidate that the conditions of each step need only be properly identified and <u>not</u> actually performed.
- B. The candidate should, at a minimum, identify the change in equipment status light indication when equipment operation is simulated.

### VI. TASK CONDITIONS

- A. A Reactor Startup is in progress. Reactor Power is ~25% CTP. Currently at Step D.23.5 of OP-65, Startup and Shutdown Procedure
- B. All prerequisites for transferring from reserve to normal station service have been met. Main Generator is synched to the grid.
- C. The Shift Manager has given direction to transfer loads from Reserve to Normal Station Service.

### * - CRITICAL STEP

### VII. INITIATING CUE

A reactor startup is in progress with the plant at approximately 25% CTP and the Main Generator synched to the grid. Per OP-65, Step D.23.5, you have been directed to transfer loads from Reserve 115kv Transformers T2 and T3 to Normal Station Service Transformer T-4. The CRS has directed that the 10100 bus be transferred first.

### VIII. TASK STANDARD

The candidate will transfer the 10100 Bus per OP-46A.

	STEP	STANDARD	EVALUATION / COMMENT
1.	Obtain and review procedure.	Candidate obtains and reviews OP-65 and OP-46A. Candidate determines that the start point is step D.20 (10100) of OP-46A.	SAT / UNSAT
2.	(D.20.1) While performing the remainder of this subsection maintain 4 KV and 600V bus voltage per Section E.	Candidate obtains/reviews OP-46A, Section E.	SAT / UNSAT
3.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4	(D.20.2)  IF a degraded or undervoltage condition occurs while transferring bus, THEN immediately establish GREATER THAN 3.9 KV using LTC CONTROL.	Not expected with established conditions. Therefore N/A	N/A

S/RO
TASK TITLE: SWAP ELECTRICAL BUSES FROM RESERVE STATION SERVICE TO NORMAL STATION SERVICE (T-4)

	STEP	STANDARD	EVALUATION / COMMENT
4.	(D.20.3)  IF Main Generator is synchronized to 345 KV System, THEN verify Main Generator has a stable load of at least 70 MWe.	At the 09-7 Panel, candidate observes MAIN GEN MW to be greater than or equal to 70MWe.	SAT / UNSAT
5.	(D.20.4) Ensure Clark Energy Control Center and Nine Mile Point 1 Control Room (due to effect on 115 KV line loading) have been notified that 10100 Bus will be transferred from reserve to normal service.	EVALUATOR: Inform candidate that notifications have been made.	SAT / UNSAT
6.	<ul> <li>(D.20.5)</li> <li>Station operators as follows:</li> <li>One to adjust bus voltage at LTC CONTROL</li> <li>One to operate breaker control switches</li> </ul>	EVALUATOR: Inform candidate that a surrogate operator is at the LTC CONTROL to respond to his/her direction.	SAT / UNSAT
*7.	(D.20.6) Place BUS 10100 FDR SYNCH SW switch in NORM.	At 09-8, candidate inserts Synch Selector Switch Key into BUS 10100 FDR SYNCH SW and turns clockwise on notch to NORM (Normal) position.	SAT / UNSAT *CRITICAL STEP*

S/RO
TASK TITLE: SWAP ELECTRICAL BUSES FROM RESERVE STATION SERVICE TO NORMAL STATION SERVICE (T-4)

	STEP	STANDARD	EVALUATION / COMMENT
8.	(D.20.7)  IF voltages on NON-EMERG BKRS INCOMING and RUNNING volt meters can not be matched in following step, THEN perform subsection G.14, Single Meter Voltage Match Method.	Candidate will recognize the need, during performance of next step (D.20.8), that this step will be applicable and will obtain and review OP-46A, Section G.14; and determine start point to be G.14.1.	SAT / UNSAT
*9.	(D.20.8)  Match voltages on NON-EMERG BKRS INCOMING and RUNNING volt meters using LTC CONTROL switch.	Candidate will determine that INCOMING and RUNNING Voltages are unable to be matched within required band, necessitating use of the OP-46A, Section G.14, Single Meter Voltage Match Method.  EVALUATOR:  Surrogate is acting as the extra operator at LTC CONTROL, and will respond to candidate direction	SAT / UNSAT *CRITICAL STEP*
		only.	
10.	(G.14.1)  IF voltage mismatch is greater than 6 meter increments, THEN obtain guidance for performing bus transfer from Design Engineering.	EVALUATOR: Inform candidate that due to the failure of the Running meter, Design Engineering has recommended the use of OP-46A, Section G.14.	N / A
*11.	(G.14.2.a)  IF transferring 4.16 KV bus from reserve to normal, THEN perform the following:  a. Place 4.16 KV bus FDR SYNCH	At 09-8, candidate turns Synch Selector Switch Key for BUS 10100 FDR SYNCH SW counterclockwise two notches to RES (Reserve) position.	SAT / UNSAT *CRITICAL STEP*
	SW switch in RES.		

S/RO
TASK TITLE: SWAP ELECTRICAL BUSES FROM RESERVE STATION SERVICE TO NORMAL STATION SERVICE (T-4)

	STEP	STANDARD	EVALUATION / COMMENT
12.	(G.14.2.b) b. Note voltage on incoming meter.	Candidate observes 09-8 Panel INCOMING Voltmeter. Candidate may write the value down or just commit it to memory.  EVALUATOR: Ensure that you note voltage also.	SAT / UNSAT
*13.	(G.14.2.c) c. Place 4.16 KV bus FDR SYNCH SW switch in NORM.	At 09-8, candidate turns Synch Selector Switch Key for BUS 10100 FDR SYNCH SW clockwise two notches to NORM (Normal) position.	SAT / UNSAT *CRITICAL STEP*
*14.	(G.14.2.d)  d. Match voltages on NON-EMERG BKRS INCOMING and RUNNING volt meters using LTC CONTROL switch.	At 09-8, candidate directs LTC CONTROL operator to operate tap changer to obtain voltage mismatch value within 5% (maximum) of value noted / written down in step G.14.2.b (JPM Step 12 above).  EVALUATOR:	SAT / UNSAT *CRITICAL STEP*
		The surrogate is acting as the extra operator at LTC CONTROL, and will respond to candidate direction only.	
15.	(D.20.9)  IF phase angle is GREATER THAN 17 degrees NON-EMERG BKRS SYNCHROSCOPE, THEN perform the following:  List not required.	Not expected with established conditions.  At 09-8, candidate locates and correctly reads the phase angle as indicated on Synchroscope, compares the indicated value to value contained in OP-46A (17°), and determines phase angle is less than 17°.	SAT / UNSAT

S/RO
TASK TITLE: SWAP ELECTRICAL BUSES FROM RESERVE STATION SERVICE TO NORMAL STATION SERVICE (T-4)

	STEP	STANDARD	EVALUATION / COMMENT
*16.	(D.20.10)	At 09-8, candidate:	SAT / UNSAT
*16.	WHEN incoming and running voltages are matched, AND synchroscope is at approximately 12 o'clock, perform the following bus transfer using the same hand, without unnecessary delay, to perform each breaker operation:  a. Close NSS TO BUS 10100 BKR 10102  b. Open RSS TO BUS 10100 BKR 10112	<ol> <li>At 09-8, candidate:</li> <li>Observes incoming meter</li> <li>Directs voltage adjustment, if necessary, to reestablish matched conditions</li> <li>Observes position of synchroscope</li> <li>When synchroscope is at approximately 12 o'clock (&lt;17° phase angle)</li> <li>Without hesitation and with same hand, operates breakers as follows:         <ul> <li>Close NSS TO BUS 10100 BKR 10102 by</li> </ul> </li> </ol>	SAT / UNSAT  *CRITICAL STEP*
		turning control switch clockwise to CLOSE; and releasing on Red light indication of breaker closure.  • Open RSS TO BUS 10100 BKR 10112 by turning control switch counterclockwise to TRIP; and releasing on Green light indication of breaker open.  EVALUATOR:  Breaker operations should occur in an expeditious and deliberate process. Due to concern for possible high current developing and causing Breaker Trips. Also, the same hand should be used, operating the breakers one at a time, to prevent inadvertently opening both beakers at the same time.	

S/RO
TASK TITLE: SWAP ELECTRICAL BUSES FROM RESERVE STATION SERVICE TO NORMAL STATION SERVICE (T-4)

-	STEP	STANDARD	EVALUATION / COMMENT
17.	(D.20.11)  Place Bus 10100 FDR SYNCH SW switch in OFF and remove handle.	At 09-8, candidate turns Synch Selector Switch Key for BUS 10100 FDR SYNCH SW counterclockwise one notch to OFF position and removes key.	SAT / UNSAT
18.	(D.20.12)  Verify all white lights for RPS A and RPS B power source selectors are on at Panel 09-16.	Candidate proceeds to Panel 09-16, locates white RPS A and RPS B power lights, and observes that they are illuminated.	SAT / UNSAT
	EV	ALUATOR: Terminate the task at this point.	

# **INITIATING CUE**

A reactor startup is in progress with the plant at approximately 25% CTP and the Main Generator synched to the grid. Per OP-65, Step D.23.5, you have been directed to transfer loads from Reserve 115kv Transformers T2 and T3 to Normal Station Service Transformer T-4. The CRS has directed that the 10100 bus be transferred first.



# James A. FitzPatrick Nuclear Power Plant OPERATIONS TRAINING PROGRAMS JOB PERFORMANCE MEASURE

S/RO_APPL. TO	NEW TASK T JPM NUMBER	ITLE: <u>CRD PUMP TRIP (ALT PATH)</u>
REV: 0	DATE: <u>1/14/05</u>	NRC K/A SYSTEM NUMBER: 201001 A2.01 3.2/3.3
JAF TASK NUMBER	:	JAF QUAL STANDARD NUMBER:
ESTIMATED COMPL	ETION TIME: 10	Minutes
SUBMITTED:		OPERATION REVIEW:
APPROVED:		
~~~~~~~~~~~	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
CANDIDATE NAME:		S.S. NUMBER:
JPM Completion:	() Simulated (X) Performed
Location:	() Plant (X) Simulator
DATE PERFORMED:		TIME TO COMPLETE: Minutes
PERFORMANCE EVA	ALUATION: () Sat	sfactory () Unsatisfactory
		SFACTORY PERFORMANCE)
EVALUATOR:	SIGNATURE/PI	RINTED

JOB PERFORMANCE MEASURE

RECORD AND CHECKLIST

_S/RO	NEW TASK TITLE: _	CRD PUMP TRIP (ALT PATH)
APPL. TO	JPM NUMBER	,
Current Update: _	1/14/05 Date	By: <u>RWD</u> Int.
Outstanding Items	:	
Tec	chnical Review	Additional Information
Qu	estions and Answers	Validation
Pro	ocedural Change Required	X None
Comments:		

JOB PERFORMANCE MEASURE REQUIRED TASK INFORMATION

_S/RO APPL.		NEW TASK TITLE: CRD PUMP TRIP (ALT PATH) JPM NUMBER
I.	SAFET	TY CONSIDERATIONS
	A.	None
II.	REFER	ENCES
	Α.	AOP-69, CONTROL ROD DRIVE TROUBLE, Revision 6.
III.	TOOL	S AND EQUIPMENT
	Α.	None
IV.	SET U	P REQUIREMENTS
	Α.	LOI-05-01 IC-138
	B.	Simulator in any power operation IC with the "A" CRD pump in service
	C.	Insert MFI-RD06:A ("A" CRD Pump Trip) and allow one accumulator trouble alarm to appear.
	D.	Insert MFI-RD06:B ("B" CRD Pump Trip)

- a. 30:39, 120 sec delay
 - b. 46:35, 150 sec delay

On Trigger 1, insert MFI-RD09:

Insert MFI-RD09:14:31

- c. 26:51, 200 sec delay
- d. 30:27, 300 sec delay
- e. 14:27, 310 sec delay
- f. 42:07, 315 sec delay

V. EVALUATOR NOTES

E.

F.

- A. If performing JPM in the plant, inform the candidate that the conditions of each step need only be properly identified and <u>not</u> actually performed.
- B. The candidate should, at a minimum, identify the change in equipment status light indication when equipment operation is simulated.

VI. TASK CONDITIONS

A. None

• - CRITICAL STEP

TASK TITLE: <u>CRD PUMP TRIP (ALT PATH)</u>

VII. INITIATING CUE

The plant was operating normally at power when the "A" CRD pump tripped unexpectedly. Local inspections indicate catastrophic failure of the gear case requiring extensive maintenance. An NPO is responding to the Accumulator Trouble Alarm. The SNO is responding to the CRD High Temperature. You are instructed to start the "B" CRD pump per AOP-69.

VIII. TASK STANDARD

The candidate will respond to a CRD Pump Trip per AOP-69

	STEP	STANDARD	EVALUATION / COMMENT
1.	Obtain and review procedure	Candidate obtains and reviews AOP-69. Candidate determines that the start point is step C.1.5	SAT / UNSAT
		EVALUATOR	
		If requested, "A" CRD pump did NOT trip on low suction pressure and the CRD pump breakers have been inspected at 71L15 and 71L16.	
2.	a. Ensure CRD FLOW CNTRL 03FIC- 301 is in MAN.	At 09-5, candidate selects CRD Flow Control GEMAC Controller mode select knob to MAN.	SAT / UNSAT
		INSTRUCTOR NOTE INSERT TRIGGER 1	*CRITICAL STEP*
3.	b. Rotate manual control knob on CRD FLOW CNTRL 03FIC-301 fully counterclockwise.	At 09-5, candidate rotates CRD Flow Control GEMAC manual flow control knurled knob counterclockwise.	SAT / UNSAT *CRITICAL STEP*
4.	c. Verify inservice CRD flow control valve (03FCV-19A or B) is closed.	At 09-5, candidate observes green lamp on and red lamp off for both CRD Flow Control Valves.	SAT / UNSAT

S/RO
TASK TITLE: CRD PUMP TRIP (ALT PATH)

	STEP	STANDARD	EVALUATION / COMMENT
5.	d. Attempt to start one CRD pump (CRD PMP 03P-16A or CRD PMP	At 09-5, Candidate selects "B" CRD Pump Control Switch to START (Spring Return to NORM)	SAT / UNSAT
	03P-16B). If the first pump fails to start, attempt to start the other.	Candidate recognizes trip of "B" CRD Pump	*CRITICAL STEP*
		Candidate dispatches NPO to investigate.	
6.	e. IF neither CRD pump can be started, THEN proceed to Subsection C.2.	EVALUATOR Act as NPO and report the "B" CRD Pump Breaker has exploded.	SAT / UNSAT
		Candidate determines that neither CRD pump can be started and proceeds to Subsection C.2	
7.	C.2.1 IF at least one CRD pump will not be made available within a	EVALUATOR If necessary, provide feedback that several hours will	SAT / UNSAT
	reasonable period of time, as determined by the SM or CRS, AND two or more ACCUM alarm lights are	be required to repair/replace the "B" CRD pump breaker.	*CRITICAL STEP*
	on at panel 09-5 full core display,	Upon receipt of multiple Accumulator Trouble Lights,	
	THEN manually scram reactor and enter AOP-1.	the candidate inserts a manual scram and commences AOP-1 Immediate Actions.	

INITIATING CUE

The plant was operating normally at power when the "A" CRD pump tripped unexpectedly. Local inspections indicate catastrophic failure of the gear case requiring extensive maintenance. An NPO is responding to the Accumulator Trouble Alarm. The SNO is responding to the CRD High Temperature. You are instructed to start the "B" CRD pump per AOP-69.



James A. FitzPatrick Nuclear Power Plant

OPERATIONS TRAINING PROGRAMS JOB PERFORMANCE MEASURE

S/RO APPL. TO	NEW TASK TITLE: JPM NUMBER	VERIFY HPCI ISOLATION
REV:O	DATE: <u>3/9/05</u>	NRC K/A SYSTEM NUMBER: <u>206000 A2.10 4.0/4.1</u>
JAF TASK NUMBER	:	JAF QUAL STANDARD NUMBER:
ESTIMATED COMPL	ETION TIME:10_ Minut	tes
SUBMITTED:		OPERATION REVIEW:
APPROVED:		
~~~~~~~~~~~~~~~~	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
CANDIDATE NAME:		_ S.S. NUMBER:
JPM Completion:	( ) Simulated(X) Performed	d
Location:	( ) Plant (X) Sir	mulator
DATE PERFORMED:		TIME TO COMPLETE: Minutes
PERFORMANCE EVA	ALUATION: ( ) Satisfact	ory ( ) Unsatisfactory
	ZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZ	CTORY PERFORMANCE)
		, , , , , , , , , , , , , , , , , , ,
EVALUATOR:	SIGNATURE/PRINTE	:D

# JOB PERFORMANCE MEASURE

# **RECORD AND CHECKLIST**

_S/RO APPL. TO	<u>NEW</u>			VERIFY HPCI ISOLATION		
Current Update:	3/9/05 Date		By: <u>R'</u> Int.	W <u>D</u>		
Outstanding Items	s:					
Te	echnical Review			Additional Information		
Qı	uestions and Answ	vers		Validation		
Pr	ocedural Change F	Required	X	None		
Comments:						

# JOB PERFORMANCE MEASURE REQUIRED TASK INFORMATION

S/RO NEW TASK TITLE: VERIFY HPCI ISOLATION
APPL. TO JPM NUMBER

#### I. SAFETY CONSIDERATIONS

A. None

### II. REFERENCES

- A. OP-15, High Pressure Coolant Injection, Revision 50
- B. AP-12.03, Conduct of Operations, Revision 30, Section 8.3

### III. TOOLS AND EQUIPMENT

A. None

### IV. SET UP REQUIREMENTS

- A. LOI-05-01 IC-138
- B. Reset simulator to any > 150 psig IC.
- C. Verify HPCI in normal standby lineup.
- D. Insert Simulator Malfunction HP11, HPCI 23MOV-15 AUTO ISOLATION FAILURE.
- E. Insert Simulator Malfunction HP06, HPCI STEAM LINE BREAK then immediately delete upon isolation.

### V. EVALUATOR NOTES

- A. If performing JPM in the plant, inform the candidate that the conditions of each step need only be properly identified and <u>not</u> actually performed.
- B. The candidate should, at a minimum, identify the change in equipment status light indication when equipment operation is simulated.

### VI. TASK CONDITIONS

- A. HPCI has received an auto-isolation signal on a HPCI Steam Line Break
- B. The Control Room Supervisor directs that the HPCI Isolation be verified per OP-15.

### • - CRITICAL STEP

S/RO

TASK TITLE: VERIFY HPCI ISOLATION

# VII. INITIATING CUE

A HPCI Isolation has just occurred during operation of the HPCI System for surveillance testing. Verify that the HPCI Isolation is complete per OP-15.

# VIII. TASK STANDARD

The candidate will manually isolate 23MOV-15 (Fails to Close), verify the HPCI Isolation is complete, and start the HPCI Aux Oil Pump.

	STEP	STANDARD	EVALUATION / COMMENT
1.	Obtain and review procedure	Candidate obtains and reviews OP-15. Candidate determines that the start point is step G.1.1.	SAT / UNSAT
*2.	(G.1.1) Ensure the following valves are closed:  • TURB STOP VLV 23HOV-1  • OUTBD STM SUPP VLV 23MOV-16  • MIN FLOW VLV 23MOV-25  • INBD TORUS SUCT VLV 23MOV-58  • INBD STM SUPP VLV 23MOV-15  • OUTBD TORUS SUCT VLV 23MOV-57  • STM LINE WARMING ISOL VLV 23MOV-60  • INJ VLV 23MOV-19	Candidate sequentially locates listed valves and verifies each valve indicates "CLOSED." At the point where candidate encounters an "OPEN" INBD STM SUPP VLV 23MOV-15 (failure to isolate), candidate will close 23MOV-15. Candidate may or may not report the valve out-of-position to CRS.  EVALUATOR:  Respond to candidate report(s) of isolation verification and/or 23MOV-15 failure to isolate in a manner consistent with the standard rules of three-point communications.	SAT / UNSAT *CRITICAL STEP*

S/RO
TASK TITLE: VERIFY HPCI ISOLATION

	STEP	STANDARD	EVALUATION / COMMENT		
3.	(G.1.2)  IF drywell pressure is above 2.7 psig AND a HPCI low steam supply pressure isolation is present,  THEN close and protective tag HPCI EXH VAC BKR 23MOV-59.	Candidate observes drywell pressure indication (local panel and/or EPIC) and determines step is <b>not</b> applicable based on the fact that drywell pressure is less than 2.7 psig.	SAT / UNSAT		
4.	(G.1.3)  Depress TURB TRIP 23A-S19 pushbutton.	At the 09-3 Panel, candidate pushes the HPCI Turbine Trip pushbutton.	SAT / UNSAT		
5.	(G.1.4)  IF HPCI was in operation before the isolation,  THEN ensure AUX OIL PMP 23P-150 is running.	Candidate will make the determination that HPCI was, in fact, in operation prior to the isolation occurring. At the 09-3 Panel, candidate will then take the control switch for the HPCI Aux Oil Pump from "AUTO" to "START" position.	SAT / UNSAT *CRITICAL STEP*		
	EVALUATOR: Terminate the task at this point.				

# **INITIATING CUE**

A HPCI Isolation has just occurred during operation of the HPCI System for surveillance testing. Verify that the HPCI Isolation is complete per OP-15.



# James A. FitzPatrick Nuclear Power Plant

# OPERATIONS TRAINING PROGRAMS JOB PERFORMANCE MEASURE

S/RO APPL. TO	FROM LOI-03-01 JPM NUMBER	TASK TITLE: ST-5D, APRM C	ALIBRATION
REV:1	DATE: <u>3/7/05</u>	NRC K/A SYSTEM NUMBER:	215005 A1.07 3.0/3.4
JAF TASK NUMBER	:	JAF QUAL STANDARD NUMB	ER:
ESTIMATED COMPL	ETION TIME: 20 Minu	ites	
SUBMITTED:		OPERATION REVIEW:	
APPROVED:			
~~~~~~~~~~~	~~~~~~~~~~~~~~~~~		~~~~~~~
CANDIDATE NAME:		S.S. NUMBER:	
JPM Completion:	() Simulated (X) I	Performed	
Location:	() Plant (X) :	Simulator	
DATE PERFORMED:		TIME TO COMPLETE: _	Minutes
PERFORMANCE EVA	ALUATION: () Satisfac	tory () Unsatisfactory	
~~~~~~~~~~~~~~~~	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~		~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~
COMMENTS: (MAN	IDATORY FOR UNSATISFAC	CTORY PERFORMANCE)	
EVALUATOR:	SIGNATURE/PRINTE	 ED	

# JOB PERFORMANCE MEASURE RECORD AND CHECKLIST

S/RO APPL. TO	FROM LOI-03-01 JPM NUMBER	TASK TITLE:	ST-5D,	APRM CALIBRATION
Current Update:	3/7/05 Date		By: <u>R\</u> Int.	<u>WD</u>
Outstanding Item	ns:			
Т	echnical Review			Additional Information
0	Questions and Answers			Validation
P	Procedural Change Require	ed	X	None
Comments:				
Simulator validat	ed			

# JOB PERFORMANCE MEASURE REQUIRED TASK INFORMATION

S/RO FROM LOI-03-01
APPL. TO JPM NUMBER

TASK TITLE: ST-5D, APRM CALIBRATION

#### I. SAFETY CONSIDERATIONS

A. None

#### II. REFERENCES

- A. ST-5D, APRM CALIBRATION, Rev. 2
- B. OP-16, NEUTRON MONITORING, Rev. 25

### III. TOOLS AND EQUIPMENT

A. Small Screwdriver

#### IV. SET UP REQUIREMENTS

- A. LOI-05-01 IC-138
- B. 25-30% CTP IC. EPIC/3D available and plant conditions stable.
- C. Adjust all APRM's to an acceptable value per ST-5D.
- D. Adjust "D" APRM to 3-4% below desired value of ST-5D.

#### V. EVALUATOR NOTES

- A. If performing JPM in the plant, inform the candidate that the conditions of each step need only be properly identified and <u>not</u> actually performed.
- B. The candidate should, at a minimum, identify the change in equipment status light indication when equipment operation is simulated.

### VI. TASK CONDITIONS

- A. A plant startup is in progress. Currently at ~25% CTP.
- B. ST-5D required prior to continuing startup.

#### * - CRITICAL STEP

S/RO FROM LOI-03-01

TASK TITLE: ST-5D, APRM CALIBRATION

VII. INITIATING CUE

You are the SNO. A plant startup is in progress with the plant currently operating at ~25% CTP and no equipment out of service. The plant has been stable for several minutes. 3D Monicore is available and core power has changed 4% since the last core performance program was executed. ST-5D, APRM CALIBRATION is required prior to continuing with the startup. Perform ST-5D.

# **EVALUATOR**

Hand partially completed ST-5D to candidate

### TASK STANDARD

The candidate will conduct an APRM calibration as directed by ST-5D. This calibration will require the adjustment to 1 APRM.

	STEP	STANDARD	EVALUATION / COMMENT
1.	Obtain and review procedure	Candidate obtains and reviews a current copy of ST-5D	SAT / UNSAT
2.	8.1 Procedure Performance Determine the applicable procedure subsection to perform as follows:  (_) IF reactor power is LESS THAN 25%, THEN perform Subsection 8.2.  (_) IF reactor power is GREATER THAN OR EQUAL TO 25%, AND the MONICORE programs are operable, THEN perform Subsection 8.3.  (_) IF reactor power is GREATER THAN OR EQUAL TO 25%, AND the MONICORE programs are not operable, THEN have Reactor Engineering perform Subsection 8.4.	Candidate selects subsection 8.3	SAT / UNSAT

S/RO FROM LOI-03-01
TASK TITLE: ST-5D, APRM CALIBRATION

	STEP	STANDARD	EVALUATION / COMMENT
*3.	8.3.1 IF core power has changed GREATER THAN 2%, OR the control rod pattern has changed since the last	Candidate demands Official 3D at 3D keyboard by selecting:	SAT / UNSAT
	core performance program was	Option 4, Run Official 3D	*CRITICAL STEP*
:	executed, <b>THEN</b> demand an Official 3D Program.	Tab to Execute	OKITIOAL STEE
		Select 2 on the number pad	
*4.	8.3.2 Determine APRM DR from the higher of the following values:	Candidate selects Percent Core Thermal Power with a	SAT / UNSAT
	Largest MFLPD x 100	value of ~27%.	*CRITICAL STEP*
	Percent core thermal power	EVALUATOR NOTE Inform candidate that the largest core MFLPD is .247	-
5.	8.3.3 <b>[ITS]</b> Adjust APRMs per Subsection 8.5.	Candidate proceeds to subsection 8.5	SAT / UNSAT
6.	8.5.1 Record initial APRM readings in Table 1.	Candidate records values from Official 3D or control room panel	SAT / UNSAT
7.	8.5.2 Record DR in Table 1.	Candidate records value selected in 8.3.2	SAT / UNSAT
*8.	8.5.3 [ITS] Identify any APRM(s) requiring adjustment in Table 1. APRM	Candidate identifies D APRM as requiring adjustment.	SAT / UNSAT
	shall be adjusted to indicate within ±2% of the DR.		*CRITICAL STEP*
9.	8.5.4 IF APRM adjustment is required,	EVALUATOR	SAT / UNSAT
	THEN perform the following for each APRM requiring adjustment:	The Shift Manager desires that the APRM's be	-
	NOTE: Bypassing APRM may be omitted per SM.	bypassed for adjustments.	
10.	A. Bypass the APRM channel requiring calibration per Section E of OP-16.	Candidate obtains and review OP-16 noting any cautions that may be applicable	SAT / UNSAT
11.	Select proper procedure section	Candidate selects section E.16	SAT / UNSAT
12.	E.16.1 Place APRM BYP switch in (*).	At 09-5 panel, candidate selects 'B' division joystick to D.	SAT / UNSAT

S/RO FROM LOI-03-01

TASK TITLE: ST-5D, APRM CALIBRATION

	STEP	STANDARD	EVALUATION / COMMENT
13.	E.16.2 Verify APRM (*) is bypassed using one or both of the following: APRM (*) BYPASS indicating light is on APRM (*) EPIC alarm indicates bypassed	At 09-5 panel, candidate observes white bypass lamp for APRM D.  AND / OR  Candidate notes EPIC alarm typer indicates selected APRM bypass is ON	SAT / UNSAT
14.	E.16.3 Verify the other two APRM channels associated with the same APRM BYP switch are in service using one or both of the following: APRM BYPASS indicating lights are off for the other two APRMs No EPIC bypassed alarms for the other two APRMs	Candidate notes the absence of the same indications for the remaining APRM's in that RPS division (B and F).	SAT / UNSAT
15.	ST-5D, 8.5.4 continued:  B. Ensure METER FUNCTION switch is set to AVERAGE.	At panel 09-14, candidate selects 'D' APRM and confirms Meter Function switch is in average.	SAT / UNSAT
16.	C. Ensure APRM MODE switch is in the OPERATE position.	At panel 09-14, candidate selects 'D' APRM and confirms Mode switch is in operate.	SAT / UNSAT
*17.	NOTE: Clockwise turn raises meter reading; counterclockwise turn lowers meter reading.  D. [ITS] Turn gain adjustment control (R16) on LPRM card Z-31 to obtain a meter reading within ±2% of DR.	At panel 09-14, candidate inserts small screwdriver into upper left simulated rheostat for the 'D' APRM. Candidate turns clockwise to raise indication to 27 + 2%.  EVALUATOR In the simulator, Z-31 card can be identified but the photos do not support reading R-16	SAT / UNSAT <u>*CRITICAL STEP*</u>
18.	E. Unbypass APRM per Section E of OP-16.	Candidate obtains OP-16 and selects section E.17	SAT / UNSAT
20.	E.17.1 Verify the following lights for APRM (*) are off at panel 09-14: INOP UPSCL NEUT TRIP UPSCL THERM TRIP	At top of panel 09-14, candidate identifies lamps for the 'D' APRM.	SAT / UNSAT

S/RO FROM LOI-03-01

TASK TITLE: ST-5D, APRM CALIBRATION

	STEP	STANDARD	EVALUATION / COMMENT
21.	E.17.2 Place APRM BYP switch for APRM (*) in center position.	At panel 09-5, candidate selects 'B' division APRM joystick to center position.	SAT / UNSAT
22.	E.17.3 Verify APRM (*) is returned to service using one or both of the following: APRM (*) BYPASS indicating light is off No EPIC bypassed alarm for APRM (*)	At 09-5 panel, candidate observes bypass lamp extinguished  AND / OR  Candidate notes alarm typer indicates APRM bypass is OFF	SAT / UNSAT
23.	E.17.4 Verify all three APRM channels associated with the same APRM BYP switch are in service using one or both of the following:  APRM BYPASS indicating lights are off for the three APRMs  No EPIC bypassed alarms for the three APRMs	Candidates notes above indications for the 'B and 'F' APRM's.	SAT / UNSAT
24.	8.5.5 Record final APRM readings for adjusted APRMs in Table 1.	Candidate record final reading.	SAT / UNSAT

# **INITIATING CUE**

You are the SNO. A plant startup is in progress with the plant currently operating at ~25% CTP and no equipment out of service. The plant has been stable for several minutes. 3D Monicore is available and core power has changed 4% since the last core performance program was executed. ST-5D, APRM CALIBRATION is required prior to continuing with the startup. Perform ST-5D.



# James A. FitzPatrick Nuclear Power Plant

# OPERATIONS TRAINING PROGRAMS JOB PERFORMANCE MEASURE

S/RO APPL. TO	FROM LOI-03-01 JPM NUMBER	TASK TITLE: GROUP 1 ISOLATION RESET
REV:1	DATE: <u>3/3/05</u>	NRC K/A SYSTEM NUMBER: <u>223002 A4.03 3.6/3.5</u>
JAF TASK NUMBER	·	JAF QUAL STANDARD NUMBER:
ESTIMATED COMPL	ETION TIME:10 Minut	es
SUBMITTED:	···	OPERATION REVIEW:
APPROVED:	·	
~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~
CANDIDATE NAME:	***************************************	S.S. NUMBER:
JPM Completion:	( ) Simulated ( X ) P	erformed
Location:	( ) Plant ( X ) S	imulator
DATE PERFORMED:		TIME TO COMPLETE: Minutes
PERFORMANCE EVA	ALUATION: ( ) Satisfacto	ory ( ) Unsatisfactory
	DATORY FOR UNSATISFAC	TORY PERFORMANCE)
EVALUATOR:	SIGNATURE/PRINTE	 D

# JOB PERFORMANCE MEASURE RECORD AND CHECKLIST

S/RO APPL. TO	FROM LOI-03-01 JPM NUMBER	TASK TITLE: GROUP 1 ISOLATION RESE	Ι
Current Update	e: <u>3/3/05</u> Date	By: <u>RWD</u> Int.	
Outstanding Ite	ems:		
	Technical Review	Additional Information	
	Questions and Answers	Validation	
	Procedural Change Required	XNone	
Comments:			
Simulator valid	ated		

# JOB PERFORMANCE MEASURE REQUIRED TASK INFORMATION

S/RO FROM LOI-03-01 TASK TITLE: GROUP 1 ISOLATION RESET
APPL. TO JPM NUMBER

#### I. SAFETY CONSIDERATIONS

A. Ensure proper safety equipment and safety procedures are observed.

#### II. REFERENCES

A. AOP-15, ISOLATION VERIFICATON AND RECOVERY Rev 23

#### III. TOOLS AND EQUIPMENT

A. None

### IV. SET UP REQUIREMENTS

- A. LOI-05-01 IC-139
- B. Current copy of AOP-15.
- C. Setup simulator with post trip conditions following MSIV closure on low steam pressure and ready for re-opening.

### V. EVALUATOR NOTES

- A. If performing JPM in the plant, inform the candidate that the conditions of each step need only be properly identified and <u>not</u> actually performed.
- B. The candidate should, at a minimum, identify the change in equipment status light indication when equipment operation is simulated.

# VI. TASK CONDITIONS

- A. Conditions have occurred which caused the MSIVs to isolate on low steam pressure.
- B. Action to restore the main condenser as a heat sink must be completed

### * - CRITICAL STEP

S/RO/NLO NEW

TASK TITLE: GROUP 1 ISOLATION RESET

VII. INITIATING CUE

Conditions have occurred which caused the MSIVs to isolate on low steam pressure. The cause of the isolation has been corrected. All radiological conditions and Reactor Chemistry samples are within normal bands. Reset the MSIV isolation using AOP-15."

TASK STANDARD

The candidate will reset the PCIS Group I isolation per AOP-15 Section C.2

	STEP	STANDARD	EVALUATION / COMMENT
1.	Obtain a controlled copy of AOP-15.	Obtains a controlled copy of AOP-15 and selects section C.2.	SAT / UNSAT
2.	CAUTION: The circumstances leading to an	Informs SM/CRS of CAUTION.	SAT / UNSAT
	isolation could have caused high radioactivity levels in the drywell or in reactor coolant.	EVALUATOR: Acknowledge candidate and respond that there is no concern for high radioactivity levels in drywell or reactor coolant.	
3.	Verify Group 1 Isolation per posted Attachment 1 Item 4.	Selects the posted attachment 1 and at panel 09-3 and/or 09-4 confirms green closed light on and red open light off for:	SAT / UNSAT
		✓ 29 AOV-80 A-D	
		✓ 29 AOV-86 A-D	
		✓ 29 MOV-74 and 77	
4.	Determine and correct cause of the isolation.	Candidate may confirm initiating cue information that cause has been determined and corrected.	SAT / UNSAT
		EVALUATOR: If asked, confirm that cause is known and corrected and candidate may proceed as directed.	

S/RO/NLO NEW

TASK TITLE: GROUP 1 ISOLATION RESET

	STEP	STANDARD	EVALUATION / COMMENT
5.	IF cause of isolation was high main steam line radiation, THEN	Reviews step and determines that cause was NOT a result of high main steam line radiation and a release will not occur as a result of isolation reset.	SAT / UNSAT
 		EVALUATOR: If candidate requests, respond that an undesirable release will not occur.	
6.	Determine whether an undesired release will occur when isolation is reset. Request RES assistance if in	Reviews step and determines that release will not occur as a result of isolation reset.	SAT / UNSAT
	doubt.	EVALUATOR: If candidate requests, the cause of the isolation was not a high radiation condition.	
7.	WHEN it has been determined that an undesired release will not occur when isolation is reset, continue with	Reviews step and determines that release will not occur as a result of isolation reset.  EVALUATOR: If candidate requests, respond that an	SAT / UNSAT
	procedure.	undesirable release will not occur.	
* 8.	Ensure control switches for the following valves are in CLOSE:  RWR LOOP B SMPL ISOL VLV 02-	At 09-3 and 09-4 panels, place the valve switches are in close and confirm green closed light on and red open light off.	SAT / UNSAT
	• RWR LOOP B SMPL ISOL VLV 02- 2AOV-40		*CRITICAL STEP*
* 9.	IF MSIVs are closed, THEN place control switch for each of the following valves in CLOSE:	At 09-3 and 09-4 panels, place the valve switches in close and confirm green closed light on and red open light off.	SAT / UNSAT
	<ul><li>MSIV 29AOV-80A</li><li>MSIV 29AOV-80B</li><li>MSIV 29AOV-80C</li></ul>		*CRITICAL STEP*
	<ul><li>MSIV 29AOV-80D</li><li>MSIV 29AOV-86A</li><li>MSIV 29AOV-86B</li></ul>		
	<ul><li>MSIV 29AOV-86C</li><li>MSIV 29AOV-86D</li></ul>		

S/RO/NLO NEW

	STEP	STANDARD	EVALUATION / COMMENT
10.	NOTE: Step C.2.8 is not required to open MSIVs if Group 1 isolation was due to high main steam line radiation (3X normal full power background).	Reviews NOTE and determines that step C.2.8 IS REQUIRED.  EVALUATOR: If candidate requests feedback regarding note, acknowledge the isolation was not due to high radiation.	SAT / UNSAT
* 11.	Simultaneously rotate the following PCIS VLV RESET switches to both RESET positions, spring return to NORM:  • 16A-S32  • 16A-S33	At panel 09-5, operates the switches and confirm annunciators 09-5-1-55 and 56 clear.	SAT / UNSAT *CRITICAL STEP*
12.	NOTE: Steps C.2.9 and C.2.10 may be performed in any order at the Shift Manager's discretion.	Reviews Note and requests feedback from SM regarding priority for action.  EVALUATOR: When candidate requests feedback regarding step priority, acknowledge the MSIVs have priority.	SAT / UNSAT
	EVA	LUATOR: Terminate the task at this point.	

# **INITIATING CUE**

Conditions have occurred which caused the MSIVs to isolate on low steam pressure. The cause of the isolation has been corrected. All radiological conditions and Reactor Chemistry samples are within normal bands. Reset the MSIV isolation using AOP-15."



# James A. FitzPatrick Nuclear Power Plant

# OPERATIONS TRAINING PROGRAMS JOB PERFORMANCE MEASURE

S/RO	NEW TASK TIT	LE: SWAP FEEDWATER LEVEL CONTROL (SINGLE TO THREE-ELEMENT)
APPL. TO	JPM NUMBER	TTITLE-ELLIVICINTY
REV:0	DATE: <u>3/9/05</u>	NRC K/A SYSTEM NUMBER: <u>259002 A4.06 3.1/3.2</u>
JAF TASK NUMBER		JAF QUAL STANDARD NUMBER:
ESTIMATED COMPL	ETION TIME: <u>15</u> Mi	nutes
SUBMITTED:		OPERATION REVIEW:
APPROVED:	·	
~~~~~~~~~~~~~	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
CANDIDATE NAME:		S.S. NUMBER:
JPM Completion:	() Simulated (X)	Performed
Location:	() Plant	(X) Simulator
DATE PERFORMED:		TIME TO COMPLETE: Minutes
		actory () Unsatisfactory
		ACTORY PERFORMANCE)
·		, in the second of the second
EVALUATOR:		
	SIGNATURE/PRIN	ITED

JOB PERFORMANCE MEASURE

Comments:

RECORD AND CHECKLIST

S/RO	NEW TASK TITLE	: SWAP FEEDWATER LEVEL CONTROL	(SINGLE TO
APPL. TO	JPM NUMBER	THREE-ELEMENT)	
Current Update: _	3/9/05 Date	By: <u>RWD</u> Int.	
Outstanding Items	:		
Tec	chnical Review	Additional Information	
Qu	estions and Answers	Validation	
Pro	cedural Change Required	XNone	

JOB PERFORMANCE MEASURE REQUIRED TASK INFORMATION

S/RO NEW TASK TITLE: SWAP FEEDWATER LEVEL CONTROL (SINGLE TO THREE-ELEMENT)

APPL. TO JPM NUMBER

I. SAFETY CONSIDERATIONS

A. None

II. REFERENCES

A. OP-2A, Feedwater System, Rev.54

B. OP-65, Startup and Shutdown Procedure, Rev. 102

III. TOOLS AND EQUIPMENT

A. None

IV. SET UP REQUIREMENTS

- A. LOI-05-01 IC-138
- B. Obtain current copies of OP-65, Startup and Shutdown Procedure and OP-2A, Feedwater System.
- C. 25-30% CTP IC during reactor startup with plant conditions stable.
- D. FWLC in Master Auto Single-Element Control on Both Reactor Feed Pumps.

V. EVALUATOR NOTES

- A. If performing JPM in the plant, inform the candidate that the conditions of each step need only be properly identified and <u>not</u> actually performed.
- B. The candidate should, at a minimum, identify the change in equipment status light indication when equipment operation is simulated.

VI. TASK CONDITIONS

- A. A Reactor Startup is in progress.
- B. Reactor Power is just above 25% CTP.
- C. Currently at Step D.24.4 of OP-65, Startup and Shutdown Procedure

* - CRITICAL STEP

VII. INITIATING CUE

A reactor startup is in progress. Per OP-65, Step D.24.4, you have been directed to transfer the Feedwater Level Control System from Single-Element to Three-Element control.

VIII. TASK STANDARD

The candidate will transfer Feedwater Level Control from Single-Element to Three-Element per OP-2A.

	STEP	STANDARD	EVALUATION / COMMENT
1.	Obtain and review procedure.	Candidate obtains and reviews OP-65 and OP-2A. Candidate determines that the start point is step G.34.1 of OP-2A.	SAT / UNSAT
2.	(G.34.1) Stabilize RPV water level at 197 to 203 inches on 06LI-94A, B, and C.	Candidate verifies stable 09-5 Panel RPV Level parameters in the required range (197 to 203 inches).	SAT / UNSAT
3.	(G.34.2) Verify RX WTR LVL CNTRL 06LC-83 is in BAL.	Candidate verifies that 09-5 Panel Master Control Transfer (Mode Selector) Switch (collar around knurled knob) for RX WTR LVL CNTRL 06LC-83 is in the "BAL" (Balance) position.	SAT / UNSAT
*4.	(G.34.3) Slowly adjust RX WTR LVL CNTRL 06LC-83 manual control knob to balance controller.	Candidate adjusts 09-5 Panel Manual Output Control (knurled knob potentiometer) until red pointer on Deviation Meter is approximately mid-scale.	SAT / UNSAT *CRITICAL STEP*

S/RO
TASK TITLE: SWAP FEEDWATER LEVEL CONTROL (SINGLE TO THREE-ELEMENT)

	STEP	STANDARD	EVALUATION / COMMENT
5.	(G.34.4.a) Ensure RFP A FLOW CNTRL 06-84A in manual as follows: a. Ensure controller is in BAL	Candidate verifies that 09-5 Panel M/A Transfer Switch (collar around knurled knob) for RFP A FLOW CNTRL 06-84A is in the "BAL" (Balance) position.	SAT / UNSAT
*6.	(G.34.4.b) b. Balance controller by adjusting manual control knob	Candidate adjusts 09-5 Panel Manual Output Control (knurled knob potentiometer) on RFP A FLOW CNTRL 06-84A until pointer is mid-scale on Deviation Meter (top of controller).	SAT / UNSAT *CRITICAL STEP*
*7.	(G.34.4.c) c. Place controller in MAN	Candidate turns 09-5 Panel M/A Transfer Switch (collar around knurled knob) for RFP A FLOW CNTRL 06-84A clockwise one position to "MAN" (Manual).	SAT / UNSAT *CRITICAL STEP*
8.	(G.34.5.a) Ensure RFP B FLOW CNTRL 06-84B in manual as follows: a. Ensure controller is in BAL	Candidate verifies that 09-5 Panel M/A Transfer Switch (collar around knurled knob) for RFP B FLOW CNTRL 06-84B is in the "BAL" (Balance) position.	SAT / UNSAT
*9.	(G.34.5.b) b. Balance controller by adjusting manual control knob	Candidate adjusts 09-5 Panel Manual Output Control (knurled knob potentiometer) RFP B FLOW CNTRL 06-84B until pointer is mid-scale on Deviation Meter (top of controller).	SAT / UNSAT *CRITICAL STEP*

S/RO
TASK TITLE: SWAP FEEDWATER LEVEL CONTROL (SINGLE TO THREE-ELEMENT)

	STEP	STANDARD	EVALUATION / COMMENT
*10.	(G.34.5.c) c. Place controller in MAN	Candidate turns 09-5 Panel M/A Transfer Switch (collar around knurled knob) for RFP B FLOW CNTRL 06-84B clockwise one position to "MAN" (Manual).	SAT / UNSAT *CRITICAL STEP*
		EVALUATOR NOTE:	
		Candidate now has RPV Water Level Control in Manual and will adjust the Manual Control Potentiometer on 06-84A/B, as necessary, to maintain level 196 to 206.5 inches.	
*11.	(G.34.6)	Candidate turns Element Control Select Switch on 09-	SAT / UNSAT
	Place 1 or 3 ELEMENT LVL CNTRL SEL 06S-2 in 3 ELEMENT.	5 Panel clockwise one position to "3 ELEMENT".	*CRITICAL STEP*
12.	(G.34.7) Verify RX WTR LVL CNTRL 06LC-83 remains balanced.	Candidate verifies 09-5 Panel RX WTR LVL CNTRL 06LC-83 red pointer on Deviation Meter is approximately mid-scale.	SAT / UNSAT
13.	(G.34.8)	Candidate obtains and reviews OP-2A, Section G.7.	SAT / UNSAT
	Transfer RFP A and B control to automatic per Subsection G.7.	Candidate determines that the start point is step G.7.1 of OP-2A.	
14.	(G.7.1) Stabilize RPV water level at 197 to 203 inches on 06LI-94A, B, and C.	Candidate verifies stable 09-5 Panel RPV Level parameters in the required range.	SAT / UNSAT

S/RO
TASK TITLE: SWAP FEEDWATER LEVEL CONTROL (SINGLE TO THREE-ELEMENT)

	STEP	STANDARD	EVALUATION / COMMENT
15.	(G.7.2) Verify the following controllers are in MAN: • RFP A FLOW CNTRL 06-84A • RFP B FLOW CNTRL 06-84B	Candidate verifies 09-5 Panel M/A Transfer Switches (collars around knurled knob) for RFP A/B FLOW CNTRL 06-84A/B are in the position of "MAN" (Manual).	SAT / UNSAT
*16.	(G.7.3) Place RX WTR LVL CNTRL 06LC-83 in MAN.	Candidate turns the 09-5 Panel M/A Transfer Switch (collar around knurled knob) for RX WTR LVL CNTRL 06LC-83 clockwise one position to "MAN" (Manual).	SAT / UNSAT *CRITICAL STEP*
*17.	(G.7.4) Slowly adjust RX WTR LVL CNTRL 06LC-83 manual control knob to balance RFP A FLOW CNTRL 06-84A.	Candidate adjusts 09-5 Panel Manual Output Control (knurled knob potentiometer) on RX WTR LVL CNTRL 06LC-83 until pointer on RFP A FLOW CNTRL 06-84A is mid-scale on Deviation Meter (top of controller).	SAT / UNSAT *CRITICAL STEP*
*18.	(G.7.5) Place RFP A FLOW CNTRL 06-84A in BAL.	Candidate turns 09-5 Panel M/A Transfer Switch (collar around knurled knob) for RFP A FLOW CNTRL 06-84A counterclockwise one position to "BAL" (Balance).	SAT / UNSAT *CRITICAL STEP*
*19.	(G.7.6.a) Line up RX WTR LVL CNTRL 06LC-83 as follows: a. Balance controller by adjusting SP ADJUST.	Candidate adjusts 09-5 Panel Setpoint Control on RX WTR LVL CNTRL 06LC-83 until red pointer on Deviation Meter is approximately mid-scale.	SAT / UNSAT *CRITICAL STEP*

S/RO
TASK TITLE: <u>SWAP FEEDWATER LEVEL CONTROL (SINGLE TO THREE-ELEMENT)</u>

	STEP	STANDARD	EVALUATION / COMMENT		
*20.	(G.7.6.b) b. Place controller in BAL. (G.7.7.a)	Candidate turns 09-5 Panel Master Control Transfer Switch (collar around knurled knob) for RX WTR LVL CNTRL 06LC-83 counterclockwise one position to "BAL" (Balance). EVALUATOR NOTE: This step restores Automatic RPV Water Level Control. Candidate slowly adjusts 09-5 Panel Manual Output	SAT / UNSAT *CRITICAL STEP* SAT / UNSAT		
	Line up RFP B FLOW CNTRL 06-84B as follows: a. Balance controller by adjusting manual control knob	Control (knurled knob potentiometer) RFP B FLOW CNTRL 06-84B until pointer is mid-scale on Deviation Meter (top of controller).	*CRITICAL STEP*		
*22.	(G.7.7.b) b. Place controller in BAL.	Candidate turns 09-5 Panel M/A Transfer Switch (collar around knurled knob) for RFP B FLOW CNTRL 06-84B counterclockwise one position to "BAL" (Balance).	SAT / UNSAT *CRITICAL STEP*		
	EVALUATOR: Terminate the task at this point.				

INITIATING CUE

A reactor startup is in progress. Per OP-65, Step D.24.4, you have been directed to transfer the Feedwater Level Control System from Single-Element to Three-Element control.



James A. FitzPatrick Nuclear Power Plant

OPERATIONS TRAINING PROGRAMS JOB PERFORMANCE MEASURE

S/RO APPL. TO	NEW TAS	SK TITLE:	START UP MAIN STEAM LEAKAGE COLL	<u>.ECTION</u>
REV:0	DATE: <u>3/7/05</u>		NRC K/A SYSTEM NUMBER: 239003 A4	.01 3.2/3.2
JAF TASK NUMBER:			JAF QUAL STANDARD NUMBER:	
ESTIMATED COMPL	ETION TIME:1	0 Minut	es	
SUBMITTED:			OPERATION REVIEW:	
APPROVED:				
~~~~~~~~~~~~~~~	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~		~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	~ ~ ~ ~ ~ ~ ~ ~
CANDIDATE NAME:			S.S. NUMBER:	
JPM Completion:	(X) Simulated	( ) Pe	erformed	
Location:	(X) Plant	( ) Si	mulator	
DATE PERFORMED:			TIME TO COMPLETE: Minute	s
			ory ( ) Unsatisfactory	
			TORY PERFORMANCE)	
EVALUATOR:	SIGNATUR	RE/PRINTE	D	

# JOB PERFORMANCE MEASURE

# **RECORD AND CHECKLIST**

S/RO APPL. TO	<u>NEW</u> JPM NUMBEI		START UP MA	AIN STEAM LEAKAGE COLLECTION
Current Update:	3/7/05 Date	_	By: <u>R</u> Int.	<u>WD</u>
Outstanding Items:				
Tec	hnical Review			Additional Information
Que	stions and Ans	wers		Validation
Proc	cedural Change	Required	X	None
Comments:				

# JOB PERFORMANCE MEASURE REQUIRED TASK INFORMATION

S/RO APPL.		NEW TASK TITLE: START UP MAIN STEAM LEAKAGE COLLECTION JPM NUMBER
I.	SAFET	Y CONSIDERATIONS
	A.	None
H.	REFER	ENCES
	A.	AOP-40, Main Steam Line Break, Revision 8
111.	TOOLS	S AND EQUIPMENT
	A.	None

### IV. SET UP REQUIREMENTS

- A. Obtain permission from the Shift Manager prior to performing this task.
- B. Obtain a current copy of AOP-40, Main Steam Line Break.

# V. EVALUATOR NOTES

- A. If performing JPM in the plant, inform the candidate that the conditions of each step need only be properly identified and <u>not</u> actually performed.
- B. The candidate should, at a minimum, identify the change in equipment status light indication when equipment operation is simulated.

### VI. TASK CONDITIONS

- A. A Main Steam Line Break has occurred in the Turbine Building.
- B. All automatic isolations / initiations were successful.
- C. All MSIVs are "CLOSED".
- D. The "Alpha" Train of the Standby Gas Treatment System is in operation.

#### * - CRITICAL STEP

# S/RO

# TASK TITLE: START UP MAIN STEAM LEAKAGE COLLECTION

# VII. INITIATING CUE

A high energy Main Steam Line Break has occurred in the Turbine Building. All automatic initiations and isolations were successful. The Shift Manager has directed that the Main Steam Leakage Collection System be placed into service per AOP-40. The SNO has verified that the "Alpha" train of the Standby Gas Treatment System is operating. The SNO directs you to place the "Alpha" train of the Main Steam Leakage Collection System into operation per AOP-40, Section C.3.

### VIII. TASK STANDARD

The candidate will start up the "Alpha" train of the Main Steam Leakage Collection System

	STEP	STANDARD	EVALUATION / COMMENT
1.	Obtain and review procedure	Candidate obtains and reviews AOP-40. Candidate determines that the start point is step C.3.2	SAT / UNSAT
*2.	(C.3.2.a.1) Close 29MOV-204A MSLC LINE "Alpha" BYPASS DRAIN VALVE.	Locates 29MOV-204A on Panel 29MSLCS in the Relay Room and closes 29MOV-204A.  EVALUATOR: Inform the candidate 29MOV-204 "Alpha" indicates "CLOSED."	SAT / UNSAT *CRITICAL STEP*
*3.	(C.3.2.a.2) Open 29MOV-200A MSLC LINE "Alpha" ISOL VALVE.	Locates 29MOV-200A on Panel 29MSLCS in the Relay Room and opens 29MOV-200A.  EVALUATOR: Inform the candidate 29MOV-200 "Alpha" indicates "OPEN."	SAT / UNSAT *CRITICAL STEP*

S/RO
TASK TITLE: START UP MAIN STEAM LEAKAGE COLLECTION

	STEP	STANDARD	EVALUATION / COMMENT		
4.	(C.3.2.a.3)  Monitors annunciator 09-5-2-49  "MSLCS A PRESS HI."	Contacts the Control Room operator and asks to be informed when annunciator 09-5-2-49 MSLCS "A" PRESS HI Clears.  EVALUATOR: Act as the Control Room and inform the candidate that the annunciator is clear.	SAT / UNSAT		
*5.	(C.3.2.a.3.a) Open 29MOV-201A MSLC LINE "A" TO SGT UPSTR ISOL VLV.	Locates 29MOV-201A on Panel 29MSLCS in the Relay Room and opens 29MOV-201A.  EVALUATOR: Inform the candidate 29MOV-201A indicates "OPEN".	SAT / UNSAT *CRITICAL STEP*		
6.	(C.3.2.a.3.b) Ensure open 29MOV-202A MSLC LINE "A" TO SGT DNSTR ISOL VLV.	Locates 29MOV-202A on Panel 29MSLCS in the Relay Room and ensures open 29MOV-202A.  EVALUATOR: Inform the candidate that 29MOV-202A indicates "OPEN".	SAT / UNSAT		
*7.	(C.3.3) Open 29MOV-203A MST OUTBD MSIV STEM LEAKOFF LINE "A" ISOL VLV.	Locates 29MOV-203A on Panel 29MSLCS in the Relay Room and opens 29MOV-203A.  EVALUATOR: Inform the candidate that 29MOV-203A indicates "OPEN".	SAT / UNSAT *CRITICAL STEP*		
	EVALUATOR: Terminate the task at this point.				

# **INITIATING CUE**

A high energy Main Steam Line Break has occurred in the Turbine Building. All automatic initiations and isolations were successful. The Shift Manager has directed that the Main Steam Leakage Collection System be placed into service per AOP-40. The SNO has verified that the "Alpha" train of the Standby Gas Treatment System is operating. The SNO directs you to place the "Alpha" train of the Main Steam Leakage Collection System into operation per AOP-40, Section C.3.