NRC FORM 591M PAR (10-2003)	T1			U.S. NUCLEAR REGULATO	DRY COMMISSION
10 CFR 2.201	CACETY INC	PECTION REPORT	ND COMPLIANCE	INCRECTION	
1. LICENSEE/LOCATION INSPECTED: Lanxess Corporation			2. NRC/REGIONAL OFFICE		
P.O. Box 500			U.S. Nuclear Regulatory Commission		
New Martinsville, West Virginia 26155-0500			Region I, 475 Allendale Road		
REPORT Nos 2005-001			King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(S		4. LICENSE NUMBER(S		5. DATE(S) OF INSPECT	ION
030-36607	,	47-30926-01	,	June 14, 2005	
LICENSEE:					
Nuclear Regulatory Com of procedures and repres 1. Based on th 2. Previous vic 3. The violation identified, non- NUREG-1600,	mission (NRC) rules and sentative records, intervi- e inspection findings, no lation(s) closed. n(s), specifically describ- repetitive, and corrective to exercise discretion, we	d regulations and the condiews with personnel, and one of violations were identified and to you by the inspector action was or is being taken	itions of your license. The bservations by the inspect. as non-cited violations, are en, and the remaining crit	idiation safety and to complian e inspection consisted of sele- tor. The inspection findings a re not being cited because the teria in the NRC Enforcement and Corrective Action(s):	ctive examinations are as follows:
				re in violation of NRC requiren cordance with 10 CFR 19.11.	nents and are
	Licensee's	Statement of Corre	ctive Actions for Ite	m 4. above.	
corrective actions is mad	n 30 days, the actions do de in accordance with the ee will be achieved). I un	escribed by me to the insperence requirements of 10 CFR	ector will be taken to corre 2.201 (corrective steps al itten response to NRC wil	m 4, above. act the violations identified. The ready taken, corrective steps if the required, unless specifical signature.	which will be taken,
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Ronald G. Rolph		(man	10h 011	1./14/20