•	: (FOR LFMS USE) : INFORMATION FROM LTS
BETWEEN:	
License Fee Management Branch, ARM	Program Code: 02201 : Status Code: 0
and Regional Licensing Sections	Status Code: U Fee Category: 7C Exp. Date: 20121031 Fee Comments: Decom Fin Assur Read: N
LICENSE FEE TRANSMITTAL	
A. REGION	
1. APPLICATION ATTACHED Applicant/Licensee: MERCY CARDIOLOGY CLINIC, INC. Received Date: 20050315 Docket No: 3036126 Control No.: 314294 License No.: 24-32420-01 Action Type: Amendment	
2. FEE ATTACHED Amount: Check No.:	
3. COMMENTS Signed J. A. Horsey Date 49-1025	
B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered //)	
1. Fee Category and Amount:	
2. Correct Fee Paid. Application may b Amendment Renewal License	e processed for:
3. OTHER	
Signed _ Date _	